TECHNICAL MANUAL

COMMISSIONING OF ELECTRICAL SYSTEMS FOR COMMAND, CONTROL, COMMUNICATIONS, COMPUTER, INTELLIGENCE, SURVEILLANCE, AND RECONNAISSANCE (C4ISR) FACILITIES

APPROVED FOR PUBLIC RELEASE: DISTRIBUTION IS UNLIMITED

REPRODUCTION AUTHORIZATION/RESTRICTIONS

This manual has been prepared by or for the Government and, except to the extent indicated below, is public property and not subject to copyright.

Reprint or republication of this manual should include a credit substantially as follows: "Department of the Army, TM 5-694, Commissioning of Electrical Systems for Command, Control, Communications, Computer, Intelligence, Surveillance, and Reconnaissance (C4ISR) Facilities, *17 February 2006*."

Table 2-1, Recommended minimum resistance values at $40^{\circ}C$ (all values in $M\Omega$) and Table 2-2, Recommended minimum values of polarization index for all machine components insulation classes reprinted with permission from IEEE Std. 43-2000 "IEEE Recommended Practice for Testing Insulation Resistance of Rotating Machinery", copyright © 2000 by IEEE. The IEEE disclaims any responsibility or liability resulting from the placement and use in the described matter.

Table 3-1, *Medium-voltage cables maximum field acceptance test voltages (kV, dc)* reprinted from NETA's Acceptance Testing Specifications, copyright © 1999. Courtesy of the International Electrical Testing Association. All rights reserved.

Technical Manual

No. 5-694

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED

COMMISSIONING OF ELECTRICAL SYSTEMS FOR COMMAND, CONTROL, COMMUNICATIONS, COMPUTER, INTELLIGENCE, SURVEILLANCE, AND RECONNAISSANCE (C4ISR) FACILITIES

CONTENTS

		PARAGRAPH	PAGE
CHAPTER 1	INTRODUCTION		
	Purpose	1-1	1-1
	Scope	1-2	1-1
	Reference	1-3	1-1
	General system testing requirements	1-4	1-1
	Component testing	1-5	1-2
	System commissioning testing	1-6	1-2
	Cost of commissioning	1-7	1-3
CHAPTER 2	GENERAL SYSTEM TESTING REQUIREMENTS		
	Introduction	2-1	2-1
	General test plan	2-2	2-1
	Types of testing methods	2-3	2-8
	Insulation testing	2-4	2-9
	Switch/circuit breaker testing	2-5	2-13
	Transformer testing	2-6	2-14
	Rotating machine testing	2-7	2-15
	Protective relays	2-8	2-17
	Ground system testing	2-9	2-18
CHAPTER 3	COMPONENT TESTING		
	Introduction to component testing	3-1	3-1
	Circuit switchers	3-2	3-1
	Transformers	3-3	3-2
	Switchgear – medium voltage	3-4	3-3
	Switchgear – low voltage	3-5	3-3
	Transfer switch	3-6	3-4
	AC/DC drives	3-7	3-4
	Motors	3-8	3-4
	Generators	3-9	3-5
	Batteries	3-10	3-7
	Battery chargers	3-11	3-8
	UPS systems	3-12	3-8
	Cables	3-13	3-9

TM 5-694

CHAPTER 4	MAIN DOWED OVOTEM	PARAGRAPH	PAGE
CHAITER 4	MAIN POWER SYSTEM Description of main power system	4-1	4-1
	Operation of main power system	4-1 4-2	4-1 4-2
	Commissioning plan for main power system	4-2 4-3	4-2 4-2
	Installation inspections and component testing of main power system	4-3 4-4	4-2 4-2
	Energizing and test of the main power system	4-4 4-5	4-2 4-3
	Possible failures and corrective actions of the main power system	4-5 4-6	4-3 4-5
	Possible families and corrective actions of the main power system	4-0	4-3
CHAPTER 5	STANDBY POWER SYSTEM		
	Description of standby power system	5-1	5-1
	Operation of standby power system	5-2	5-1
	Commissioning plan for standby power system	5-3	5-2
	Installation inspections and component testing of standby power	5-4	5-2
	system		
	Energizing and test of the standby power system	5-5	5-3
	Possible failures and corrective actions of the standby power system:	5-6	5-4
CHAPTER 6	UNINTERRUPTIBLE POWER SUPPLY SYSTEMS		
	Description of uninterruptible power supply (UPS) system	6-1	6-1
	Operation of uninterruptible power supply system	6-2	6-2
	Commissioning plan for the UPS system	6-3	6-2
	Installation inspections and component testing of the UPS system	6-4	6-2
	Energizing and test of the UPS system	6-5	6-3
	Possible failures and corrective actions	6-6	6-6
CHAPTER 7	HIGH ALTITUDE ELECTROMAGNETIC PULSE (HEMP) AND		
	HIGH POWER MICROWAVE (HPM) EQUIPMENT & CONTROLS		
	General HEMP protection systems	7-1	7-1
	HEMP protection systems	7-2	7-1
	· · ·		
APPENDIX A	REFERENCES		A-1

LIST OF TABLES

Table	Title	Page
1-1	Costs of commissioning, new construction	1-3
2-1	Recommended minimum insulation resistance values at 40°C (all values in	2-10
	ΜΩ)	
2-2	Recommended minimum values of polarization index for all machine components insulation classes	2-16
3-1	Medium-voltage cables maximum field acceptance test voltages (kV, dc)	3-10
4-1	Circuit switcher functional checklist	4-4
4-2	Possible failures and corrective actions of the main power system	4-6
5-1	Possible failures and corrective actions of the standby power system	5-5
6-1	Possible failures and corrective actions of the UPS system	6-6

LIST OF FIGURES

Figure	Title	Page
Figure 2-1	Sample of a commissioning plan	2-8
Figure 2-2	Step-voltage vs. time	2-12
Figure 2-3	Step-voltage high-potential test current	2-12
Figure 2-4	Power transformer diagram (Reprinted from Department of the Army TM 5-	2-15
	686. Power Transformer Maintenance and Acceptance Testing 16 November	
	1998)	
Figure 3-1	Static UPS system 150 to 750 kVA (courtesy of Liebert).	3-9
Figure 4-1	Main power system single line diagram	4-7
Figure 4-2	Main power system control cable block diagram	4-8
Figure 4-3	Main power system functional diagram – circuit switcher (typical for 2)	4-9
Figure 4-4	Main power system functional diagram – switchgear load breaker (typical for 8)	4-10
Figure 4-5	Main power system functional diagram – switchgear incoming breaker (typical	4-11
	for 3)	
Figure 4-6	Main power system circuit switcher wiring diagram (typical for 2)	4-12
Figure 4-7	Main power system incoming breaker wiring diagram	4-13
Figure 4-8	Sample of completed DA Form 7463-R	4-14
Figure 4-9	Sample of completed DA Form 7464-R	4-15
Figure 4-10	Sample of completed DA Form 7465-R	4-16
Figure 4-11	Sample of completed DA Form 7466-R	4-17
Figure 4-12	Sample of completed DA Form 7467-R	4-18
Figure 5-1	Standby power system single line diagram	5-6
Figure 5-2	Standby power system block diagram	5-7
Figure 5-3	Standby power system wiring diagram	5-8
Figure 5-4	Engine fault tree	5-9
Figure 5-5	Sample of completed DA Form 7468-R	5-10
Figure 5-6	Sample of completed DA Form 7469-R	5-12
Figure 5-7	Sample of completed DA Form 7470-R	5-13
Figure 6-1	Uninterruptible power supply system single line diagram	6-9
Figure 6-2	Uninterruptible power supply system block diagram	6-10
Figure 6-3	Uninterruptible power supply system wiring diagram	6-11
Figure 6-4	Sample of completed DA Form 7471-R	6-12
Figure 6-5	Sample of completed DA Form 7472-R	6-13
Figure 6-6	Sample of completed DA Form 7473-R	6-14
Figure 6-7	Sample of completed DA Form 7474-R	6-15
Figure 6-8	Sample of completed DA Form 7475-R	6-16

CHAPTER 1

INTRODUCTION

1-1. Purpose

The purpose of this publication is to provide guidance to engineering managers/planners for the commissioning of electrical systems at command, control, communications, computer, intelligence, surveillance, and reconnaissance (C4ISR) facilities. It specifically addresses different types of electrical power systems, the preparation of commissioning statements of work (SOW), specifications, and examples of commissioning tests that should be included during start-up. Electrical systems commissioning (sometimes referred to as "acceptance testing") on new projects is critical to ascertain that a system is installed correctly and that it will remain in service for its projected life cycle.

1-2. Scope

Guidance for commissioning of electric power systems on new projects is discussed in this manual. The systems addressed include the main power substation, standby generator, and uninterruptible power supply. The following areas are addressed: general commissioning criteria, commissioning plan, documentation requirements, verification procedures, system functional performance tests, deferred performance tests, corrective measures, acceptance documentation, post commissioning follow up procedures and examples of commissioning.

1-3. References

Appendix A contains a list of references used in this manual. Other pertinent literature may be substituted or used as supplements. Prescribed forms are also listed in appendix A.

1-4. General system testing requirements

The purpose of electric systems commissioning is to increase the reliability of electrical power systems after installation by identifying problems and providing a set of baseline values for comparison with subsequent routine tests. A procedure should be developed to include a planned approach (road map) of what should be done in order to verify the proper system installation. This procedure is the commissioning plan. Specific areas addressed in a commissioning plan include the verification of the installation of all equipment/components, interface connections between equipment and individual systems, and interconnection drawings. The development of this test plan specific to each system and/or component is key to the usefulness of any maintenance program. The plan consists of the schedule of when acceptance and routine tests should be performed, test forms to be used to record the outcome of the tests which are retained for comparison with previous and subsequent tests, and a listing of the required test devices. Since the results of the commissioning tests become baseline test values to compare with later tests and the results of the routine maintenance tests are compiled to identify any downward trend in performance, it is vital to the maintenance program to have accurate and complete records. To perform the testing, the plan lists all required tests in order of performance and gives a schedule for each test. The work items and schedule depend on many items including the importance and cost of the equipment, consequences of failure, age of equipment, past and future frequency of service, hours of operation, future maintenance availability, environmental conditions, and safety requirements.

1-5. Component testing

The reliability of any system is dependent on the interconnection of the equipment and the equipment itself. This manual predominately provides guidance for testing of electrical systems. It is assumed that the detailed and comprehensive individual testing of equipment has been completed before the commencing of commissioning of the system. However, general testing procedures for the components of the systems described in this manual are addressed in chapter 3. Commissioning requirements for the system components are typically provided with the original proposal for the procurement of the equipment. The requirements provided by the equipment manufacturer should be adhered to in addition to the recommended testing herein. Although there are many different components in any electrical system, there are some tests that are common among the equipment. Examples of the common testing procedures include the assembly check, alignment check, grounding verification, insulation resistance tests and polarization index to name a few. These common tests are described in detail in chapter 2. Sufficient time should be allocated to define the inspections required, perform the check, and document the results. A review of the system drawings will show major pieces of equipment. Specific procedures should be developed for each test referencing the equipment to be used, drawings to be followed, and step by step procedures with readings to be recorded and forms for the results.

1-6. System commissioning testing

Electrical systems commissioning on new projects is critical to ascertain that a system is installed properly and that it will operate as designed. The commissioning of a system encompasses the individual testing of the related components, the verification of the component interconnection against the drawings, and the functional testing of the system as a whole. An understanding of the equipment involved and the modes of operation for a system are essential to the development of the system commissioning plan. A survey of the equipment of the system and listing the equipment in order of importance and startup is the first step in developing the commissioning plan. The schedule of the tests and inspections is dependent on many aspects of the equipment such as its importance and cost, the frequency of service, hours of operation, environmental conditions, accessibility, and safety requirements. The inspection, testing, and startup plan is then developed in conjunction with this schedule with instructions and procedures for the test plan. Examples of systems testing are discussed in chapters 4, 5 and 6. DA Form 7463 (Circuit Switcher Inspection Checklist), DA Form &7464 (Transformer Inspection Checklist), DA Form 7465 (Switchgear Inspection Checklist), DA Form 7466 (Power Cable Inspection Checklist), DA Form 7467 (Main Power System Energization Checklist), DA Form 7468 (Engine Generator Set Inspection Checklist), DA Form 7469 (Backup Power System Inspection Checklist), DA Form 7470 (Utility and Generator Circuit Breaker Inspection Checklist), DA Form 7471 (Transfer Switch Inspection Checklist), DA Form 7572 (Uninterruptible Power Supply [UPS] Inspection Checklist), DA Form 7473 (Battery Inspection Checklist), DA Form 7474 (Uninterruptible Power Supply [UPS] Switchboard Inspection Checklist) and DA Form 7475 (Uninterruptible Power Supply [UPS] System Inspection Checklist) are checklists designed to assist in these inspections and tests. They are found as reproducible forms at the end of this manual. Similar types of forms are also available in ANNEX F of NFPA 70B. Problems may arise during the testing of the equipment and systems. In order to identify and correct these problems, troubleshooting techniques should be developed. Checking of equipment such as fuses, lights, and breakers for continuity, equipment calibration and settings, and investigating for faulty equipment or connections should be the first troubleshooting steps. For all problems, the equipment and component manuals are consulted for troubleshooting directions. Examples of the possible causes to common problems are shown for each system in the chapters that follow.

1-7. Cost of commissioning

The cost of commissioning for an electrical system is dependent upon many factors including the system size, complexity and the level of reliability desired. New building construction, renovation of an existing building, or the modernization also will affect the cost of commissioning. Experience has shown that the initial commissioning cost is more than offset by increased system reliability and reduced operating costs. The cost for commissioning a new building can range from 0.5 to 1.5 percent of the total construction cost as shown in the table below. For an existing building the commissioning costs can range from three to five percent of the total operating costs.

Table 1-1. Costs of commissioning, new construction

Commissioning Scope	Cost
Entire building (HVAC, Controls, Electrical,	0.5-1.5% of total construction cost
Mechanical) Commissioning	
HVAC and Automated Control System Commissioning	1.5-2.5% of mechanical system cost
Electrical Systems Commissioning	1.0-1.5% of electrical system cost
Energy Efficiency Measures Commissioning	\$0.23-0.28 per square foot

Source: Portland Energy Conservation Incorporated/Building Commissioning Guide, US Department of Energy, 30 July 1998

CHAPTER 2

GENERAL SYSTEM TESTING REQUIREMENTS

2-1. Introduction

The purpose of electrical testing on systems and their components is two-fold. The first is to check the installation of the equipment and perform component and systems tests to ensure that, when energized, the system will function properly. The second is to develop a set of baseline test results for comparison in future testing to identify equipment deterioration. Commissioning tests are usually performed by independent contractors, the installation contractor, or the manufacturer. Each commissioning test should be witnessed and approved by a person not associated professionally with the person performing the test. The individuals who perform the acceptance tests should be certified and/or licensed for the equipment under test. The system should be initially checked for damage, deterioration, and component failures using specific component checks, inspections, and tests defined by the equipment manufacturer. Then the interconnection of the system components should be checked, using de-energized and energized methods, to verify the proper interconnection and operation of the components, including on/off control, system process interlocks, and protective relaying functions. Once the above tests are complete, the system can be energized and operational tests and measurements should be performed. All steps and results of the testing should be carefully documented for review and for use in the future for comparison with the results of future tests. Many of the same component tests initially run will be performed at regular intervals as part of a maintenance program. The new results will be compared to the initial results, where variations may be indicative of problems like deterioration of insulation or dirty equipment. The steps involved are to review the system and equipment, develop a general system and specific equipment test plan, provide inspection and checks, perform component testing, verify and check the continuity of wiring, check control functions, calibrate instruments and relays, energize portions of the circuits and check for proper operation in a specific order, and, once complete, perform specific checks and control tests on the complete system during initial period of operation.

2-2. General test plan

There are management, economic, technical, and operational requirements associated with every test plan. The development and use of a comprehensive test plan is like an insurance policy. While it has specific costs, it does not usually show any direct paybacks as the systems will usually startup without significant problems such as equipment failure or lost time. The cost of the tests will rise with the complexity of the test program. Many inspections and tests are redundant, but are used as checks and balances before system energization to ensure successful startup and operation. Many times, if the equipment is in the same operating condition as when it left the factory and the system design and installation are adequate, the system startup and testing will find no problems and the de-energized checks and energized testing may seem like a waste of time and money. There are occasions when a test will show bad insulation like a faulted transformer winding or a missing interlock in a control scheme that would have resulted in catastrophic failure if the system had been energized. The complexity of the system and equipment, experience of the designers/installers/operators, the possible results of a failure, and the costs of the testing are all considered when determining the amount of testing required. The component and system inspections and checks are the key to the success of the program. Sufficient time should be allocated to define the inspections required, perform the check, and document the results. A review of the system drawings will show major pieces of equipment. Specific procedures should be developed for each commissioning test referencing the equipment to be used, systems operation documents (SODs), systems

operation and maintenance manuals (SOMMs), drawings to be followed, and step by step procedures with readings to be recorded and forms for the results. Once the equipment is identified, the manufacturer's manuals should be used to identify the required inspections, handling and installation procedures, energized and de-energized component tests, drawing and wiring verification, minimum report requirements for on-going maintenance and testing baseline, and requirements for repair and retesting if certain checks and tests produce unsatisfactory results. To perform the testing, a definite plan listing all required tests in order of performance and giving a schedule for each test should be developed. The work items and schedule will depend on many items including the importance and cost of the equipment, consequences of failure, age of equipment, past and future frequency of service, hours of operation, future maintenance availability, environmental conditions, and safety requirements. (For remote unattended systems, additional items will be required in the initial test plan, to help assure all possible operating sequences, malfunctions, and corrections have been verified. The plan should be revised as the inspection and testing proceeds depending on the acceptability of the results.) Certain failures may require retesting of component and system operation. When wiring problems are found and repaired, all affected wiring terminations should be re-verified for their proper connections. The success of a test program and its use to support an on-going maintenance program also greatly depends on the attention given to development and review of the test records and reports by the testing and operations personnel and system management. To have an effective program it is imperative that test data be complete, organized, and readily available. Forms should be developed with the test procedures which list the required test procedure, test sequence, test instrument, test data and, most importantly, acceptable test values for each result. (Examples of test forms are found in each applicable chapter. These forms should only be used as samples.) A remarks area should be included to list any pass or fail, comments, recommendations for repair and retest, additional follow-up testing required during the next steps of the system operation, and helpful information for future testing. Note that the data collected and recorded will be used over the years to analyze trends for equipment deterioration or help determine causes for system malfunctions, so if the records are not complete and correct a large part of the usefulness of a good test program is lost. The technical requirements for a test program can be stated as follows.

a. Survey of system equipment. An accurate and complete description of a power system and its equipment is required to develop a test program. This will include written system description, one-line diagrams, short circuit and coordination studies, three line diagrams, control logic diagrams, schematic logic diagrams, cable block and interconnecting diagrams, equipment physical and wiring drawings, equipment manuals, and auxiliary system manuals and drawings for support systems such as lighting, fire protection, backup power, building and building services, etc.. These documents serve to depict the design and operation of the system for use during installation, testing, startup, operation, and maintenance. Various standards groups such as the Institute of Electrical and Electronics Engineers (IEEE) and National Electrical Manufacturers Association (NEMA) have developed standards for these materials. Typical drawings and their definitions are as follows:

(1) One-line (single-line) diagram. Shows, by means of single lines and graphic symbols, the flow of electrical power or the course of electrical circuit symbols, and how they are connected. In this diagram, physical relationships are usually disregarded.

(2) Block diagram. Shows a group of interconnected blocks, each of which represent a device or subsystem.

(3) Schematic (elementary) diagram. Shows all circuits and device elements of the equipment. This diagram emphasizes the device elements and their functions, and it is always drawn with all devices shown in deenergized mode.

(4) Control sequence (truth-table) diagram. Shows a description of the contact positions, connections, that are made for each position of control action or device.

(5) Wiring diagram (connection diagram). Locates and identifies electrical devices, terminals, and interconnecting wires in an assembly. This diagram may show interconnecting wiring by lines or terminal designations.

(6) Interconnection diagram. Shows only the external connection between controllers and associated equipment or between various housing units of an assembly of switchgear apparatus.

(7) *Circuit layout and routing diagram.* Shows the physical layout of the facility and equipment and how the circuit to the various equipment is run.

(8) Short-circuit coordination study. Electrical power system data, diagrams, and drawings are needed during maintenance and testing of electrical equipment. This may involve information and data relating to protective devices and relays. Such data are usually found in a short-circuit coordination study and usually encompass all the short-circuit values available in the power system, relays, and trip device settings. Normally, this study is performed during the construction phase of the facility. It would be much more desirable to perform this engineering study as part of the initial facility design, and then validate it during the construction phase to assure that equipment and values specified have been met. When accepting the facility, this study data should be used as a benchmark, and any changes that may have been made during construction in the system should be incorporated to update the study for future references.

b. Listing of critical system equipment. The major equipment of a system is vital to its operation and failure of this equipment could be a threat to personnel and system operation, i.e., potential single point failures. From a review of the system documentation, especially the single line diagram, a list of critical equipment and the order in which the items should be inspected, tested, and energized should be developed. From this list, the plan and schedule for the test program can be developed. Normally the listing in order of criticality of the equipment is from the normal power source into the system with onsite sources failing after the main power source and distribution equipment. The listing may be difficult to prepare as it will vary for each system, and therefore a team from system engineering, operations, and maintenance may be required. This will also serve to provide the operations and maintenance personnel an opportunity to review the system during the early stages of a project, which helps them in the performance of their work.

c. Steps for the test program. A test program will commence after completion of installation and will usually include field inspection and installation checks, de-energized component testing, verify instrument and relay operation and calibration, visual check of all wiring, continuity checking of control circuits, energized functional testing of control circuits, megger testing of power circuits, test of power circuits phasing, energizing of equipment, and service testing. If problems are found during the testing; an analysis should be performed, and a repair and retest should be performed that is approved by the commissioning authority, manufacturer, engineer, and system operator. Many of these initial tests will be repeated periodically as part of the system maintenance program depending on the load conditions, duty cycle, environmental conditions, and the critical nature of the equipment. Because of this, the completeness and clarity of the test reports is important as they supply baseline data for comparison with the results of the maintenance tests.

d. General definition of test steps. Prior to testing, overall completion of installation should be verified including setting, wiring, grounding of the equipment, and conditioning of the overall area, i.e., clean complete site to work in. This is considered a pretest. Note: all of the items below should be

performed in strict accordance with the drawings, systems operations documents, systems operation and maintenance manuals (provided by contractor), and the engineer's and manufacturer's instructions for each piece of equipment. The manufacturer typically provides the instructions in the form of diagrams indicating how to connect the test instruments as well as charts indicating acceptable and unacceptable values. The engineer's instructions will be found in the system specifications and drawings, and the manufacturer's instructions are found in the equipment manuals and drawings. IEEE, NEMA, National Fire Protection Association (NFPA), and other standards also include acceptable procedures for the performance of the tests. As the acceptance tests and energization is performed; failures and repairs, availability of equipment and personnel, schedules, weather, and other items may cause the delay or nonperformance of a test. In any of these cases, the missing, failed, newly required, or postponed test should be noted in the test documentation along with the reason for missing the test and the technical consequences. An evaluation should be made as to whether the system can be energized without this test noting the possible effect on safety, personnel, and equipment operation; and noting when or even if the test should be performed in the future. If the test yet to be performed or needs to be performed to prove the adequacy of a repair, the test should be scheduled with the system operations personnel as part of an on-going maintenance program.

(1) Field inspection and installation checks. Include inspection of impact recorders, verification of removal of shipping braces, inspection of installation against drawings and nameplates, inspecting of components for damage and cleanliness, inspection of insulators for cracking, inspection of anchorage and grounding, sizing check of fuses and breakers, alignment and adjustment checks, mechanical operation and interlock checks, remove CT shorting jumpers, lubrication application, verification of insulating liquid or gas level or pressure, and verification that local safety equipment is in place.

(2) De-energized component testing. Include pressure and level checks, megger and insulation resistance testing of equipment and connections including grounds, turns ratio measurements, polarity tests, insulating liquid dielectric and moisture testing, power factor or dissipation factor tests, overpotential tests, contact resistance measurements, operation time travel analysis, battery and cell voltage measurements, charger/UPS (uninterruptible power supply)/generator current and voltage measurements, and equipment/systems impedance or resistance tests.

(3) Verification of instrument and relay operation and calibration. Include verification of auxiliary device operation, calibration of instruments and relays, functional testing of individual instruments/gauges/alarms/relays/limit switches/etc.

(4) Visual check of all wiring. Include visual inspection of all wiring against the schematic and wiring, both internal and external, diagrams.

(5) Continuity checking of control circuits. Include continuity and voltage testing of all control circuits against schematic diagrams.

(6) *Energized functional testing of control circuits*. Include energizing of control circuits and checking all remote and local close/trip operations, protective relay operations, safety and interlock operations, and all process and communication operations.

(7) *Megger testing of power circuits*. Include megger testing of power, current transformer, and potential transformer buses and cables after connection.

(8) *Phase out testing of power circuits*. Include primary and/or secondary injection testing for circuit impedance and polarity checks.

(9) Energizing of equipment. Include energizing of equipment in specific order after all above testing is complete and evaluated.

(10) Service testing. Include measurement of value and relationship of power, potential, and current on sources, buses, feeders, and neutrals in the power system.

(11) Post acceptance tests. Include on-going maintenance and operation tests, corrective action tests, and deferred testing.

e. Reports, forms, and records. Accurate and complete reports, forms, and records should be developed and kept updated after the testing for the equipment and the system for initial evaluation of the results before energization and on-going evaluation by operations and maintenance. Analysis of the data and results should provide a decision to startup and a guide for future maintenance requirements and its cost. Figures should be kept for the time, cost, and equipment used for each test for input to the development of the maintenance program. Care should be taken to ensure that extraneous information does not become part of the record, because record keeping might hamper future use. Test reports giving test description and basic procedure, components, drawing and other document references, test circuit diagrams, test equipment model and age and calibration date, special tools required, test forms with results filled in, time to run the test, acceptance criteria, failure or unusual event information, recommended repair, and when the test should be performed again for equipment maintenance should be developed for the tests. Summary logs developed from the information can be used for developing and scheduling an on-going maintenance program. Forms should be used to document the results of testing procedures. They should be detailed and direct, but simple and durable enough to be used in the field. The forms should be used as input to the development of the test reports. A well designed form will contain checklist information for inspections, test procedures, safety and special precautions, required equipment and tools, reference drawings and manuals, acceptance criteria, estimated time to perform the test, and remarks/event recording area. Sample forms for basic equipment and tests are attached.

Special precautions and safety. Many tests on electrical equipment involve the use of high voltages f. and currents that are dangerous, both from the standpoint of being life hazards to personnel and because they are capable of damaging or destroying the equipment under test. Adequate safety rules should be instituted and practiced to prevent injury to personnel, both personnel who are performing the tests and others who might be exposed to the hazard. Also, the test procedures used should be designed to ensure that no intentional damage to equipment will result from the testing process. It should be recognized, as the name implies, that over-potential or high-potential testing is intended to stress the insulation structure above that of normal system voltage. The purpose of the test is to establish the integrity of the insulation to withstand voltage transients associated with switching and lightning surges and hence reduce the probability of in-service equipment failures. Direct voltage over-potential testing is generally considered a controlled, nondestructive test in that an experienced operator, utilizing a suitable test set, can often detect marginal insulation from the behavior of measured current. It is therefore possible; in many cases to detect questionable insulation and plan for replacement without actually breaking it down under test. Unfortunately, some insulations might break down with no warning. Plans for coping with this possibility should be included in the test schedule. Low-voltage insulation testing can generally be done at the beginning of the planned maintenance shutdown. In the event of an insulation failure under test, maximum time would be available for repair prior to the scheduled system start-up. Equipment found in wet or dirty condition should be cleaned and dried before high-potential testing is done or a breakdown can damage the equipment. Low-voltage circuit breakers, which require very high interrupting ratings, are available with integral current-limiting fuses. Although the fuse size is selected to override without damage to the time-current operating characteristics of the series trip device, it is desirable to bypass or remove the fuse prior to applying simulated overload and fault current. If a testing program is to provide meaningful information relative to the condition of the equipment under test, then the person evaluating

the test data must be ensured that the test was conducted in a proper manner and that all of the conditions that could affect the evaluation of the tests were considered and any pertinent factors reported. The test operator, therefore, must be thoroughly familiar with the test equipment used in the type of test to be performed and also sufficiently experienced to be able to detect any equipment abnormalities or questionable data during the performance of the tests.

g. Test equipment. It is important that in any test program the proper equipment is used. The equipment should be calibrated, in good condition, and used by qualified operators. Any test equipment used for calibration shall have twice the accuracy of the equipment to be tested. Care should be taken to use a quality or regulated power source for the equipment as voltage, frequency, and waveform variation can produce invalid results. All equipment should be operated in accordance with its instruction manual.

h. Sample Commissioning (Cx) *Plan*: The primary intent of this technical manual is to propose different procedures that should be considered when commissioning a new electrical system and /or component. The figures, forms, and tests in this manual are only examples of the concepts that should be implemented when developing a commissioning plan. The following paragraphs discuss an example of commissioning program planning stages that can be used to commission a new system as shown in figure 2.1 (Commissioning Plan Example). The time period in which a commissioning process begins determines what steps in the planning stages are considered:

(1) Initial commissioning (kick-off) meeting. The first commissioning meeting may start as early as before a contract is awarded or as late as after the system has been installed (before it is turned over to the customer). The participants in the meeting should include customer, government contractor personnel, participating engineers, commissioning personnel (may be an independent commissioning contractor or government engineer), general contractor, and electrical and mechanical sub-contractors. Topics of meeting should include areas of responsibility, expectations, overall presentation of system, methodology, potential problem areas, etc. The participants should be all considered "part of a team".

(2) Review initial statement of work (SOW). All participants should review the SOW that describes the requirements of the commissioning process. The customer (or designated authority) should have the ultimate control where decisions are required.

(3) Review drawing submittals. After the systems are installed, drawings should be submitted for review and comment. Sometimes the review may be before systems are installed. Care must be taken to verify that the drawings submitted reflect the actual installed system.

(4) Approval meeting. After the SOW and drawing submittals have been submitted, reviewed, comments made, and comments incorporated, approval of documents should be provided.

(5) Systems operation document (SOD)/systems operation and maintenance manual (SOMM) document. Prime contractor should provide a SOD or SOMM. These documents are required in order to develop specific commissioning tests.

(6) Submit functional performance tests (FPTs). System/component tests or FPTs should be developed from submitted drawings, SODs and SOMMs. The tests should include large

component testing (i.e. transformers, cable, generators, UPS), and how components operate as part of the total system. The test should be developed for the commissioning authority who can designate a contractor to develop the test. The commissioning authority should not be the installation contractor or sub-contractor.

(7) *Quality assurance*. As the equipment/components/systems are installed quality assurance procedures should be administered to verify components are installed in-accordance with minimum manufacturer's recommendations, safety codes, and acceptable installation practices. Quality assurance discrepancies should be identified and added to a "commissioning action list" that must be rectified as part of the commissioning program. These items would usually be discussed during commissioning meetings. Discrepancies are usually identified initially by visual inspection.

(8) *Review FPTs*. The tests should be reviewed by the customer, electrical contractors, quality assurance personnel, maintenance personnel, etc (the commissioning team). Areas of concern should be 1) are all functions of the system being tested, 2) are all major components included, 3) do the tests reflect the system operating documents, 4) do the tests make sense, etc.

(9) *Make changes to FPTs*. This is where corrections, questions answered, and additions made will be implemented. This will be done by the commissioning authority.

(10) FPT approval. After the changes are made to the FPTs they will again be submitted to the commissioning team. When it is acceptable the customer or his/her designated approval authority should approve the FPTs. It should be noted that even though the FPT is approved, problems that arise during the test (or areas not covered) should be addressed.

(11) Systems operate. The FPTs can be implemented as various systems become operative (i.e. test the generator system) or when the entire system is installed. However the final "pull the plug" test will be performed after all systems are completely installed. If the FPTs are implemented by the electrical contractor (or sub-contractor) then a witness should initial each step of the test. The witness should not be employed directly or indirectly by the electrical contractor.

(12) Customer receives system. After all tests are completed (including the "pull the plug" test) the system should be turned over to the customer.

Commissioning (Cx) Planning Stages



Development Of Functional Performance Tests (FPT's)




Figure 2-1. Sample of a commissioning plan

2-3. Types of testing methods

Types of testing methods include the four categories of tests as well as the tests themselves.

a. Categories of tests. There are four categories of tests for electrical equipment; factory, acceptance, routine maintenance, and special maintenance. Factory tests are performed at the factory to prove the equipment was manufactured properly and meets specific design parameters. Commissioning tests, the main subject of this document, are also proof tests performed on new equipment and systems usually after installation and before energization. They are run to determine whether the equipment is in compliance with specifications, to establish benchmarks for future tests, to determine the equipment was installed correctly and without damage, and to verify whether the equipment meets its intended design operation and limits. Routine and special maintenance tests are run after the equipment has been in service for a certain amount of time to determine the degree of deterioration of physical parameters as operating time increases. Routine tests are performed on a periodic basis and special tests are performed on defective equipment to help determine the cause of a failure and/or the extent of the damage. The same type of tests and measurements are performed for all of the categories using different voltage values. The acceptance tests are usually run at 80% and the maintenance tests are usually run at 60% of the factory test voltage values to help indicate deterioration without being destructive.

b. Types of testing methods. The testing of electrical power system equipment involves checking the insulation adequacy, electrical properties, protection and control, operation, and other items as they relate to the overall system. Some of these checks are accomplished using de-energized component tests, instrumentation and relay operation and calibration tests, energized functional testing of control circuits, megger testing of power circuits, phase out testing of power circuits, and service testing.

2-4. Insulation testing

Insulation can either be solid, liquid, or gaseous dielectric materials that prevent the flow of electricity between points of different potential. Insulation testing is performed to determine the integrity of the insulation. This usually consists of applying a high potential voltage to the item and measuring the leakage current that may flow to ground. Excessive leakage current is an indication of dielectric breakdown and/or impending failure. Insulation may weaken over time at a rate tightly related to the operating time and temperature of operation. Therefore, these tests are run periodically to track the insulation deterioration. Insulation testing, the most common electrical testing performed, can be performed by applying a direct current (dc) or alternating current (ac) voltage. The type and value of the voltage determines whether the test is considered non-destructive or destructive. The higher the voltage, the more destructive the test. Usually destructive tests are run as acceptance and maintenance tests to measure deterioration from the original value. Both the dc and ac tests are "go no-go" tests. In addition, the dc test can indicate the amount of deterioration and forecast the remaining time for safe operation by comparing the leakage current and test voltage to values from previous tests.

a. Advantage of direct-current testing. Direct-current test is preferred on equipment whose charging capacitance is very high, such as cables. Direct-current voltage stress is considered much less damaging to insulation than ac voltages. The time of voltage application is not as critical with dc voltage as with ac voltage. The test can be stopped before equipment failure. Measurements can be taken concurrently. It is not necessary to make a separate insulation resistance test prior to making a dc over potential test.

b. Disadvantage of direct-current testing. The stress distribution for transformers, motors, and generator winding is different for dc voltage than for ac voltage. The residual charge after a dc voltage test must be carefully discharged. The time required to conduct a dc high-potential test is longer than for an ac high-potential test.

c. Direct-current (dc) testing. When a dc potential is applied across an insulation, the resultant current flow is composed of several components as follows:

(1) Capacitance-charging current. Capacitance-charging current is the current resulting from charge absorbed by the capacitor formed by the capacitance of the component under test. This current is a function of time which also depends on applied dc voltage, insulation resistance and the time constant of the circuit.

(2) *Dielectric-absorption current*. Dielectric-absorption current is the current that is absorbed and trapped in the dielectric during the charging of the piece of equipment and released after the equipment is discharged. This current can be calculated from test voltage, capacitance, and time. In air-cooled and hydrogen-cooled ac rotating machines, dielectric absorption varies with temperature.

(3) Surface leakage current. The passage of current over the surface of an insulation rather than through its volume is surface leakage current. In measuring insulation resistance of armature and field windings in rotating machines (rated 1 hp, 750 W or greater), a high surface leakage current is usually caused by moisture or another type of partly conductive contamination present in the rotating machine.

(4) Partial discharge (corona current). This is a type of localized discharge resulting from transient gaseous ionization in an insulation system when the voltage stress exceeds a critical value. Partial discharge is not desirable and should be eliminated. It is caused by overstressing of air at sharp corners of the conductor due to high test voltage. In shielded power cable systems (rated > 5 kV), humidity or wind can increase the corona current.

(5) Volumetric leakage current. The current that flows through the volume insulation itself is volumetric leakage current. It is the current that is of primary interest in the evaluation of the condition of the insulation. In shielded power cable systems (rated > 5 kV), humidity, condensation, and precipitation on the surface of a termination can increase surface leakage current and volumetric leakage current. Surface leakage current and volumetric current added together is the quotient of the applied dc voltage and insulation resistance. In large ac rotating machines rated 10,000 kVA or greater and rated 6000 V or higher, moisture, on the end windings, increases surface leakage current and volumetric leakage current especially when dirt is also on the winding. Since the insulation may weaken over time, age may cause an increase in the various currents during testing.

d. Insulation-resistance (megger) testing. For equipment containing electronic components, megger testing must not be performed. However, this equipment should be tested according to manufacturer specifications. In an insulation-resistance test, an applied voltage, from 600 to 5000 volts, supplied from a source of constant potential, is applied across the insulation. The usual potential source is a megohmeter, also known as a megger, either hand or power operated that indicates the insulation resistance directly on a scale calibrated in megohms. A megohmeter that is a hand cranked, a rectifiertype, or battery-operated instrument is suitable for testing equipment rated up to 600 volts. For equipment rated over 600 volts, use of a 1000-volt or 2500-volt motor-driven or rectifier-type megohmeter is recommended for optimum test results. The quality of the insulation is evaluated based on the level of the insulation resistance. The insulation resistance of many types of insulation is variable with temperature, so the data obtained should be corrected to the standard temperature for the class of equipment under test. Published charts similar to table 2-1 are available for this purpose. The megohm value of insulation resistance obtained will be inversely proportional to the volume of insulation being tested. For example, a cable 1000-ft (304.8 m) long would be expected to have one-tenth the insulation resistance of a cable 100-ft (30.48 m) long if all other conditions were identical. The insulation-resistance test is relatively easy to perform and is a useful test used on all types and classes of electrical equipment. Its main value lies in the charting of data from periodic tests, corrected for temperature, over the life of the equipment so that deteriorative trends might be detected.

Minimum Insulation Resistance after 1 minute (MΩ)	Test specimen
kV + 1	For most windings made before about 1970, all
(Example: 15 kV machine is $15 + 1 = 16 \text{ M}\Omega$)	field windings, and others not described below
100	For most dc armature and ac windings built after
100	about 1970 (form-wound coils)
5	For most machines with random-wound stator
5	coils and form-wound coils rated below 1 kV

<i>Table 2-1.</i>	Recommended	minimum	insulation	resistance	values at	$40^{\circ}C$	(all values in $M\Omega$)).
-------------------	-------------	---------	------------	------------	-----------	---------------	----------------------------	----

Notes: kV is the rated machine terminal to terminal voltage, in rms (root mean square) kV. Recommended minimum insulation resistance values above, in megohms, at 40°C of the entire machine winding for overvoltage testing or operation of ac and dc machine stator windings and rotor windings. From IEEE Std. 43-2000. Copyright © 2000 IEEE. All rights reserved.

e. Dielectric absorption testing. In a dielectric-absorption test, a voltage supplied from a source of constant potential is applied across the insulation. The test voltage used may have to be significantly higher than the insulation-resistance test in order to obtain measurable current readings. The potential source can be either a meg-ohmmeter, as described above or a high-voltage power supply with an ammeter indicating the current being drawn by the specimen under test. The voltage is applied for an extended period of time, from 5 to 15 minutes, and periodic readings are taken of the insulation resistance or leakage current. The test data is evaluated on the basis that if insulation is in good condition, its apparent insulation resistance will increase as the test progresses.

Unlike the insulation-resistance test, the dielectric-absorption test results are independent of the volume and the temperature of the insulation under test. For the dielectric absorption test, the values recorded at each one minute interval are plotted on log-log paper with coordinates for resistance versus time. The slope of the resulting curve gives a good indication of the insulation condition. A good insulation system will have a slope that is a straight line increasing in respect to time. The characteristic slope of a poor insulation system will be a curve that flattens out with respect to time.

f. Polarization index testing. The polarization index is a specialized application of the dielectric absorption test. The index is the ratio of insulation resistance at two different times after voltage application, usually the insulation resistance at 10 minutes to the insulation resistance at 1 minute. The use of polarization-index testing is usually confined to rotating machines, cables, and transformers. A polarization index less than 1.0 indicates that the equipment needs maintenance before being placed in service. References are available for polarization indexes for various types of equipment as well as in table 2-2. Acceptance testing specifications for Electrical Power and Distribution Equipment and Systems NETA 1999 and Recommended Practice for Testing Insulation Resistance of Rotating Machinery (IEEE Std. 43-2000) are references available for polarization index is the quotient of the 10-minute and 1 minute readings as shown in the following equation:

$$PI = R_{10}/R_1$$
 (dimensionless)

Where:

PI = polarization indexR = resistance.

For polarization indexes in transformers an acceptable value would be 2 or higher, values between 2 and 1 indicate marginal condition, and values below 1 indicate poor condition. After insulation resistance readings have been made, the test voltage is returned to zero and the insulation is discharged.

g. High-potential testing. A high-potential test (hi-pot) consists of applying voltage across an insulation at or above the dc equivalent of the 60-Hz operating crest voltage. The dc equivalent of the 60-Hz operating crest voltage is calculated using the following equation:

$$Vac = Vdc / \sqrt{2}$$

Where:

Vdc is the equivalent dc voltage Vac is the operating crest ac voltage

The hi-pot test can be applied either as a dielectric-absorption test or a step-voltage test. DC high potential tests are "go no-go" tests. The cable is required to withstand the specified voltage for the specified time duration. These tests will normally reveal major problems due to improper field handling, improperly installed accessories or mechanical damage. Recommended test voltages are given in standard tables for dc and ac. To perform the dc Hi-pot test the input voltage to the test set should be regulated. The current-sensing circuits in test equipment shall measure only the leakage current associated with the cable under test and shall not include internal leakage of the test equipment. Record wet-bulb and dry-bulb temperatures or relative humidity and temperature. The wet bulb temperature is defined as the temperature given by a thermometer bulb which is covered with an absorbent material (linen wet with distilled water) and exposed to the atmosphere so that evaporation will cool the water and the thermometer bulb. The dry-bulb temperature is defined as the temperature is defined as the temperature is defined. All shields must also be grounded. Terminations shall be adequately corona-suppressed by guard ring, field reduction

sphere, or other suitable methods as necessary. Precaution should be taken to insure that the maximum test voltage does not exceed the limits for terminations specified in IEEE Standard 48 or manufacturers specifications. When applied as a dielectric-absorption test, the maximum voltage is applied gradually over a period of from 60 to 90 seconds. The maximum voltage is then held for 5 minutes with leakage-current readings being taken each minute. In cables, high ambient temperature or humidity at the ends of improperly prepared cables can raise the dc leakage current to many times its normal value. When applied as a step-voltage test, the maximum voltage is applied in a number of equal increments, usually not less than eight, with each voltage step being held for an equal interval of time. A typical voltage versus time graph as shown in figure 2-2. The time interval between steps should be long enough to allow the leakage current to reach stability, approximately 1 or 2 minutes. A leakage-current reading is taken at the end of each interval before the voltage is raised to the next level.




Figure 2-2. Step-voltage versus time

A plot of test voltage versus leakage current or insulation resistance is drawn as the test progresses. A nonlinear increase in leakage current can indicate imminent failure, and the test should be discontinued. See figure 2-3.




Figure 2-3. Step-voltage high-potential test current

After the maximum test voltage is reached, a dielectric absorption test can be performed at that voltage, usually for a 5-minute period.

h. AC high-potential testing. Alternating-current high-potential tests are made at voltages above the normal system voltage for a short time, such as 1 minute. The test voltages to be used vary depending on whether the device or circuit is low or high voltage, a primary or control circuit, and whether it was tested at the factory or in the field. Manufacturers' instructions and the applicable standards should be consulted for the proper values.

Insulation power-factor testing. The power factor of an insulation is a measure of the energy component i. of the charging current. Power-factor testing is used to determine the power factor of an insulation system. Power-factor testing is a useful tool in evaluating the quality of insulation in power, distribution, and instrument transformers; circuit breakers; rotating machines, cables; regulators; and insulating liquids. The equipment to be tested should be isolated from the rest of the system, if practical, and all bushings or terminations should be cleaned and dried. The test should be conducted when the relative humidity is below 70 percent and when the insulation system is at a temperature above 32° F (0°C). The test equipment used should be such that the power factor or dissipation factor can be read directly or such that the charging volt-amperes and the dielectric losses can be read separately so that a ratio might be computed. The test equipment should also have sufficient electromagnetic interference cancellation devices or shielding to give meaningful test results even when used in an area of strong interference, such as an energized substation. Electromagnetic interference distorts the readings, yielding incorrect values. The desired measurements should be performed following the operating instructions supplied with the test equipment. A meaningful evaluation will include comparison to manufacturer's results taken at the factory and/or nameplate data. On transformer tests, obtain the power factor of each winding with respect to ground and each winding with respect to each other winding. In addition, tests should be made of each bushing with a rated voltage above 600 volts, either using the power factor or capacitance tap if the bushing is so equipped or by use of a "hot-collar" test using a test electrode around the outside shell of the bushing. On higher voltage circuit breakers, the power factor of each line-side and load-side bushing assembly complete with stationary contact and interrupters, with the circuit breaker open, and each pole of the circuit breaker with the breaker closed should be obtained. On ac rotating machines, the neutral connection on the stator should be removed and a test of each winding with respect to the other two windings and ground should be obtained. For cables, the power factor of each conductor with respect to ground should be obtained and a hot-collar test should be made of each pothead or termination. Power-factor testing of insulating oil should be performed in accordance with American Society for Testing and Materials (ASTM) D 924, Standard Test Method for Dissipation Factor (or Power Factor) and Relative Permittivity (Dielectric Constant) of Electrical Insulating Liquids.

2-5. Switch/circuit breaker testing

In addition to the insulation testing mentioned above, for large switches and circuit breakers the following tests can be applied.

a. Circuit breaker time-travel analysis. This test, used on medium and high-voltage circuit breakers provides information as to whether the operating mechanism of the circuit breaker is operating properly. This test can be used to determine the opening and closing speeds of the breaker, the interval time for closing and tripping, and the contact bounce. The test provides information that can be used to detect problems such as weak accelerating springs, defective shock absorbers, dashpots, buffers, and closing mechanisms. The test is performed by a mechanical device that is attached to the breaker. One device, a rotating drum with a chart attached, is temporarily connected to the chassis or tank of the breaker. A movable rod with a marking device attached is installed on the lift rod portion of the breaker. As the breaker is opened or closed, the marking device indicates the amount of contact travel on the chart as the drum rotates at a known speed. With another available device, a transducer is attached to the movable rod, and the breaker operation is recorded on an oscillograph.

b. Contact-resistance testing. This test is used to test the quality of the contacts on switches and circuit breakers. A test set designed for this purpose is available with direct-scale calibration in microhms, capable of reading contact resistances of 10 microhms or less. An alternate method is to pass a known level of direct current through the contact structures and to measure the dc millivolt drop across the contacts. The data obtained can then be converted to resistance by applying Ohm's Law. The alternate method requires a source of at least 100 amperes with a millivolt meter of approximately 0-20 mV range.

2-6. Transformer testing

Transformers are subject to the following tests in addition to the insulation testing mentioned above in paragraph 2-4. However, dry-type transformers would not be subject to fault-gas analysis and insulating liquid analysis due to the fact that these types of transformers usually feature a gaseous or dry compound insulating medium. Cast coil transformers, which are defined as a transformer with high-voltage coils cast in an epoxy resin, would also not be subject to fault-gas analysis and insulating liquid analysis due to the fact that the core and coils of these types of transformers are not immersed in an insulating liquid. Cast coil transformers are considered to be dry-type transformers.

a. Transformer turns-ratio and polarity tests. The turns-ratio test is used to determine the number of turns in one winding of a transformer in relation to the number of turns in the other windings of the same phase of the transformer. The polarity test determines the vectoral relationship of the various transformer windings. The tests are applicable to all power and distribution transformers. See figure 2-4 for a diagram of a typical fluid filled power transformers. Cast coil transformers are also subject to these tests. The turns-ratio test and the polarity test can be done on transformers of all sizes. The turns-ratio test is also commonly performed on instrument transformers. The test equipment used will ordinarily be a turns-ratio test set designed for the purpose, although, if not available, two voltmeters or two ammeters (for current transformers only) can be used. When two ac voltmeters are used, one is connected to the high-voltage winding and the other is connected to the low voltage winding. The high voltage winding is excited to a voltage not exceeding the rating of the voltmeter. Both voltmeters are read simultaneously. A second set of readings should be taken with the metering instruments interchanged. The values indicated should be averaged to calculate the ratio. A meaningful ratio measurement may be made using only a few volts of excitation. The transformer should be excited from the highest voltage winding in order to avoid possibly unsafe high voltages. Care should be taken during the application of voltage and during the measurement. It is important that simultaneous readings for both voltmeters be made. The voltmeters used should have accuracy's matching with the requirements of a 0.5 % ratio calculation. When a turns-ratio test is performed, the ratio should be determined for all no-load taps. If the transformer is equipped with a load-tap changer, the ratio should be determined for each load-tap changer position.

b. Fault-gas analysis. The analysis of the percentage of combustible gases present in the nitrogen cap of sealed, pressurized oil-filled transformers can provide information as to the likelihood of incipient faults in the transformer. Fault-gas analysis can be performed on mineral-oil-immersed transformers of all sizes. When arcing or excessive heating occurs below the top surface of the oil, some oil decomposes. Some of the products of the decomposition are combustible gases that rise to the top of the oil and mix with the nitrogen above the oil. The test set for this test is designed for the purpose. A small sample of nitrogen is removed from the transformer and analyzed.

c. Insulating-liquid analysis. Insulating-liquid analysis can be performed in the field on oil-immersed power transformers of all sizes. Regular tests, on a semiannual basis, should be made on insulating oils and askarels. Samples should be taken from the equipment and tested in accordance with the manufacturer's instructions. Typical tests include dielectric breakdown, acidity, color, power factor, interfacial tension, and visual examination.

d. Dissolved gas in oil analysis. Dissolved gas in oil analysis can be used to determine transformer operation. Gases are formed in oil when the insulation system is exposed to electrical, mechanical, and thermal stresses. Examples of gas in oil are hydrogen, oxygen, acetylene, etc. These gases are an indication of the insulation's integrity.

2-7. Rotating machine testing

The tests described below are for rotating machines such as motors and generators. These tests are applied based on the horsepower and kVA rating of the machine.

a. Insulation-resistance (megger) testing. The insulation resistance test as described in paragraph 2-4d is also applicable to rotating machines. This testing procedure applies to armature and rotating or stationary field windings. If the insulation resistance is below the established minimum, circuit components should be tested separately until the low insulation reading is located. Insulation-resistance history based on tests conducted on new motors or after rewinding, cleaning, or from recorded data made under uniform conditions form a very useful basis for interpretation of a machine winding condition. When comparing records of periodic tests any persistent downward trend is an indication of insulation trouble even though the values might be higher than the recommended minimum safe values.




Figure 2-4. Power transformer diagram (Reprinted from Department of the Army TM 5-686. Power Transformer Maintenance and Acceptance Testing 16 November 1998).

b. Dielectric-absorption testing. A dielectric absorption test for a rotating machine is performed as described in paragraph 2-4e. A more complete and preferred test than the insulation resistance test, the dielectric absorption test applies the voltage for 10 minutes or more to develop the dielectric-absorption characteristic. The curve obtained by plotting insulation resistance against time gives a good indication of moist or dirty windings. A steady rising curve is indicative of a clean, dry winding. A quickly flattening curve is the result of leakage current through or over the surface of the winding and is indicative of moist or dirty windings. If facilities are not available for a 10-minute test, a polarization index test can be performed by taking readings at 30 and 60 seconds. The ratio of the 60-to-30-second or the 10-to-1-minute ratio will serve as an indication of the winding condition. Table 2-2 lists recommended acceptable values.

Table 2-2.	Recommended minimum	values of polarization	index for all machine	components insulation
	classes.			

Thermal Class Rating	Minimum P.I.
Class 105	1.5
Class 130	2.0
Class 155	2.0
Class 180	2.0

The Polarization Index test is not applicable to noninsulated field windings (See IEEE Std. 43-2000 Section 12.2.1).

Note: The numbers in the thermal class rating are the hot-spot temperatures in degrees centigrade of the rotating machine. If the 1 min insulation resistance is above 5000 M Ω , the calculated P.I. may or may not be an indication of insulation condition and is therefore not recommended as an assessment tool. From IEEE Std. 43-2000. Copyright © 2000 IEEE. All rights reserved.

c. Over-potential testing. Overvoltage tests are performed during normal maintenance operations or after servicing or repair of important machines or during commissioning. Such tests, made on all or parts of the circuit to ground, ensure that the insulation level is sufficiently high for continued safe operation. Both ac and dc test equipment are available. The test overvoltages that should be applied will depend on the type of machine involved and level of reliability required from the machines. However, it should be of sufficient magnitude to search out weaknesses in the insulation that might cause failure. Standard ac over-potential test voltage when new is twice rated voltage plus 1000 volts ac. The dc over potential test is performed by applying a voltage and measuring the leakage current. The voltage applied during the acceptance test is a function of the equipment voltage rating as shown by the following equation:

dc acceptance test voltage in kV = 1.6[.8(2E + 1,000)] where E is the rated voltage in kV. dc maintenance test voltage in kV = 1.6[.6(2E + 1,000)] where E is the rated voltage in kV.

These values for test voltages are given in *A Stitch in Time, Manual on Electrical Insulation Testing for the Practical Man*, Biddle Instruments, 1981. The standard duration of the test is between 1 to 5 minutes. The dc acceptance test voltage is applied to each winding separately with the other windings grounded. The voltage is applied in steps. First one third of the dc acceptance test voltage is applied. Leakage current readings are taken at one minute intervals up to a maximum of ten minutes. Then the voltage is increased in 1 kV intervals recording the leakage current and applied voltage at each step. Sufficient time shall be allowed between steps for the leakage current to stabilize. The data shall be plotted leakage current versus applied test voltage. The plot will yield a smooth curve with a rising slope for a good insulation system. Any sudden changes in the curve characteristics are an indication of impending failure. A high-potential test made to determine the condition of the insulation up to a predetermined

voltage level is difficult to interpret. It is common practice to compare known good results against test specimens to determine what is acceptable and what fails the test.

2-8. Protective relays

Protective relays are used to sense abnormalities and cause the trouble to be isolated with minimum disturbance to the electrical system and the least damage to the equipment at fault. Protective relays should be set and acceptance tested prior to being placed in service and tested periodically thereafter to ensure reliable performance. In a normal industrial application, periodic testing should be done at least every 2 years. The person performing the test should be given the settings to be applied to each particular relay by the engineer. There are two types of protective relays addressed in this manual. The first types are solid state relays. These are electronic "black box" devices. As all electronic devices, solid state relays should never be subject to hi-pot or megger testing. They typically come equipped with internal testing capabilities. Any diagnostic tests shall be performed as indicated in the manufacturer's manual. The second type is induction disk relays. They are subject to the following tests.

a. Inspection. If recommended or desirable, each relay should be removed from its case (if relay design permits) for a thorough inspection and cleaning. If the circuit is in service, one relay at a time should be removed so as not to totally disable the protection. The areas of inspection are detailed in the manufacturer's instruction manual. These generally consist of inspection for loose screws, friction in moving parts, iron filings between the induction disk and permanent magnet, and any evidence of distress with the relay. The fine silver contacts should be cleaned only with a burnishing tool.

b. Settings. Prescribed settings should be applied or it should be ascertained that they have been applied to the relay.

c. *Pickup test.* In the case of a time-over-current relay, its contacts should eventually creep to a closed position with a magnitude of current introduced in its induction coil equal to the tap setting. The pickup is adjusted by means of the restraining spiral-spring adjusting ring. A pickup test on a voltage relay is made in much the same manner.

d. Timing test. A timing test should be made on most types of relays. In the case of a time-overcurrent relay, one or more timing tests are made at anywhere from two to ten times the tap setting to verify the time-current characteristic of the relay. Two timing points should be specified in the prescribed settings. Tests should be made with the relay in its panel and case (when primary current injection is used for testing), and the time test run at the calibration setting.

e. Instantaneous test. Some protective relays are instantaneous in operation, or might have a separate instantaneous element. In this context, the term instantaneous means "having no intentional time delay." If used, the specified pickup on the instantaneous element should be set by test. Again referring to the relay used in the example above, at two times pickup, its instantaneous element should have an operating time of between 0.016 and 0.030 seconds.

f. Test of target and seal-in unit. Most types of protective relays have a combination target and sealin unit. The target indicates that the relay has operated. The seal-in unit is adjustable to pickup at either 0.2 or 2.0 amperes. The pickup setting is established by the relay coordination study. The setting for the seal-in unit should be specified with the relay settings. It should be verified by test that the contacts will seal in with the minimum specified direct current applied in the seal-in unit.

g. Test of tripping circuit. A test should be made, preferably at time of testing the relays, to verify that operation of the relay contacts will cause the breaker to trip.

2-9. Ground system testing

In addition to the general component tests stated in the preceding paragraphs, there are tests to be performed on the system as a whole after the components are installed. They are as follows:

a. Equipment ground-impedance testing. This test is used to determine the integrity of the grounding path from the point of test back to the source panel or supply transformer. A low-impedance grounding path is necessary to facilitate operation of the overcurrent device under ground-fault conditions as well as provide a zero voltage reference for reliable operation of computers and other microprocessor-based electronic equipment. Instruments are available to measure the impedance of the grounding path. When using these instruments, the user should remember that, although a high-impedance value is an indication of a problem, for example a loose connection or excessive conductor length, a low-impedance readout does not necessarily indicate the adequacy of the grounding path. A grounding path that is found to have a low impedance by the use of relatively low test currents might not have sufficient capacity to handle large ground faults. Ground loop or grounding conductor impedance cannot be measured reliably in situations where metallic conduits are used or where metallic boxes or equipment are attached to metal building frames or interconnected structures. Such situations create parallel paths for test currents that make it impossible to measure the impedance of the grounding conductors; or even to detect an open or missing grounding conductor. Visual examinations and actual checking for tightness of connections are still necessary to determine the adequacy of the grounding path.

b. Grounded conductor (neutral) impedance testing. On solidly grounded low-voltage system (600 volts or less) supplying microprocessor-based electronic equipment with switching power supplies, this test is used to determine the quality of the grounded conductor (neutral) from the point of test back to the source panel or supply transformer. The same instruments used to perform the equipment ground-impedance tests can be used to perform grounded conductor (neutral) impedance tests.

c. Grounding-electrode resistance testing. Grounding-electrode resistance testing is used to determine the effectiveness and integrity of the grounding system. Periodic testing is necessary because changes in soil temperature, soil moisture, conductive salts in the soil, and corrosion of the ground connectors cause variations in soil resistivity. The test set used will ordinarily be a ground-resistance test set, designed for the purpose, using the principle of the fall of potential of ac-circulated current from a test spot to the ground connection under test.

d. Neutral-current testing. Situations exist where it is possible for the neutral current of three-phase systems to exceed the ampacity of the neutral conductor in normal operation. This is usually due to unbalanced phase loading, nonsinusoidal load currents (harmonics), or a combination of the two. Also nonlinear loads, such as rectifiers, computers, variable speed drives, electrical discharge lighting fixtures, and switching mode power supplies, cause phase currents that are not sinusoidal. The problem can be detected using a true root mean square (RMS) ammeter to measure the current flowing in the neutral conductor. The use of an average responding ammeter calibrated to read the RMS value of a sine wave should not be used as it will not yield valid results when used on nonsinusoidal waveforms. If the neutral current is found to be excessive, the current in each phase should be measured to determine if an abnormal condition exists. If excessive neutral current exists and the phase currents are not excessive, harmonic content is the most likely cause. A means of analyzing neutral current containing harmonic components is through the use of a wave or spectrum analyzer.

CHAPTER 3

COMPONENT TESTING

3-1. Introduction to component testing

The component inspection and checks are the key to the success of any commissioning program. Each component of the system should be initially checked for damage, deterioration, and failures by a procedure using inspections and tests as defined by the specific equipment manufacturer. The equipment manuals from the manufacturer identify the minimum required receipt inspections, handling and installation procedures, drawing and wiring verification, de-energized and energized component tests, minimum testing baseline and report requirements for on-going maintenance, and requirements for repair and retesting if certain checks and tests produce unsatisfactory results. After the systems components are interconnected, the system should be checked, using de-energized and energized methods, to verify the proper interconnection and operation of the components including on/off control, system process interlocks, and protective relaying functions. Once these tests are complete, the system can be energized and operational tests and measurements are performed. This chapter of the manual gives a typical listing of the commissioning test and testing procedures that are recommended (manufacturers' recommendations should always be incorporated into component testing) for each of the following system components before the interconnection and operation of the components as a system is verified and tested. The components/systems to be verified and tested are circuit switchers, transformers, switchgear – low voltage, switchgear – medium voltage, transfer switch, motors, ac/dc drives, generators, batteries, battery chargers, UPS systems, and cables. For equipment containing electronic components, megger testing must not be performed. However, this equipment should be tested according to manufacturer's specifications.

3-2. Circuit switchers

A circuit switcher is a device that consists of a disconnect switch and a circuit-breaking interrupter. They are used for switching and protecting equipment such as transformers, lines, cables, capacitor banks, and shunt reactors from short circuit currents. The first step towards acceptance of any device is verification of nameplate data and equipment conditions. All the equipment shall be checked against nameplate, oneline, schematic, and wiring diagrams. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. Upon receipt a visual inspection of the circuit switcher and associated hardware shall be made including nameplate, parts, drawings, and condition. Any discrepancies should be sent to the manufacturer for a resolution. After installation, the circuit switcher shall be checked to ensure that it has been bolted to its permanent foundation, all shipping braces have been removed, and that it has been properly grounded. The alignment of the disconnect should be checked to ensure that the blade tongue contact enters the jaw contact on center, rotates fully and comes to rest within 1/8" of the stop. The interrupter action should be checked for proper operation as described in the operation manual. The circuit switcher shall be manually operated to check that the mechanism works smoothly and correctly. The contact surfaces should be checked for proper lubrication. The control wiring installation shall be checked per the drawings. The low pressure indicator should be checked by measuring the pressure in psig (pounds per square inch gauge) and recorded along with the ambient temperature at the time the measurement was taken and then comparing this value with the manufacturer's data. Checks shall be made to insure that the grounding connections have been installed. Simulate a fault by activating the protective relay circuit and check electrical operation. Check key interlocks both mechanically and electrically. Testing shall include timing, contact resistance, contact

part time, and charging motor operation. Descriptions of these tests are found in paragraph 2-5. The timing test shall be performed at the normal operating voltage for both trip command and close command.

3-3. Transformers

There are two basic types of power transformers, oil-filled and dry-type. Both are subject to many of the same tests. Therefore, the following test procedures apply to both types unless otherwise noted. Since cast coil transformers are considered dry-type, the following tests also apply unless the test is noted to only apply to oil-filled transformers.

a. Inspection on receipt. A thorough inspection for the transformer shall be completed upon arrival and before unloading. This inspection shall include a detailed visual inspection of the external of the transformer. Since the largest transformer we are concerned with in this manual is 10 MVA, the transformers do not require impact recorder. The minimum size of transformer for impact recording is approximately 20 MVA. Oil-filled type transformers are typically shipped filled with either dry air or nitrogen. The pressure condition, nitrogen content, and dew point shall be measured before unloading of the transformer. A positive pressure should be maintained on nitrogen-blanketed transformers. The oxygen content should be less than one percent. The seals of the transformer shall be inspected to ensure that they are properly seated. For an acceptable transformer installation it is imperative that the foundation is level. This should be checked well in advance of receipt of the transformer. Upon completion of the equipment inspections, the transformer shall be unloaded and set into its final installation position. The shipping bracing shall be removed and it shall then be anchored to its foundation. The bolts (if used) securing the transformer to its foundation shall be checked to ensure that they are installed at the proper torque. Transformers shipped filled with oil will not need internal inspections unless the electrical testing described below indicates a problem. Then the oil must be drained, inspection performed, and repair completed. After the repair is inspected, the transformer shall be filled with clean dielectric fluid in strict accordance with the manufacturer's instructions. The purpose of this internal inspection is to determine that no displacement has occurred in transit or during unloading. Items to be verified include the tap-changer, end braces and current transformers. This inspection must be performed with dry air in the main tank. If the transformer has been delivered filled with nitrogen, it must be evacuated from the tank replaced with dry air. Personnel performing the inspection must wear clean cotton clothing, mouth covers and oil-resistant, clean, rubber soled shoes that contain no metallic parts. All transformer nameplates, wiring, and accessories shall be visually inspected and compared against the drawings. These accessories include but are not limited to radiators, fans, bushings, and instrument controls.

b. Installation checks. After the preceding inspections have been completed, the transformer shall be assembled. Transformer assembly includes but is not limited to, mounting of radiators, fans, bushings, thermometers, oil level indicators, relays and expansion tank. Transformer assembly must be in accordance with manufacturer's instructions and design drawings. After all of the accessories have been installed, protection circuits shall be wired and checked. A pressure test can now be performed and the transformer filled with oil. The alarm, control, and trip settings on temperature indicators shall be inspected to verify that they are set as specified. The cooling pumps shall operate correctly, and the fan and pump motors shall have correct overcurrent protection. Operation of all alarm, control, and trip circuits from temperature and level indicators, pressure relief device, and fault pressure relays shall be checked. Liquid level in all tanks and bushings shall be verified. Grounding shall be verified. Once the above is complete the following tests shall be performed on insulation resistance, dielectric absorption, polarization index, transformer turns ratio test, and power factor test. Descriptions of these tests are found in paragraphs 2-4 and 2-6. Once completed and passed, the transformer is ready for energization.

3-4. Switchgear - medium voltage

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. The switchgear shall be checked for completeness of assembly. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. A visual inspection of the area where the switchgear is installed should be performed to confirm that there is adequate aisle space at the front and rear of the equipment for proper ventilation, service and maintenance of the equipment. The switchgear should be checked to insure it is properly anchored to its foundation. Visually inspect that the high voltage connections are properly insulated. Electrically disconnecting contacts, machined parts, shutter, etc., should be checked for lubrication and operation. The breaker alignment and manual operation shall be checked. All blocking, supports and other temporary ties should be removed from breakers, instruments, relays, etc. The following checks should be compared to a one-line diagram. Verify proper fuses are correctly placed. Verify proper voltage and phase connections. Verify correct component and installation of potential and current transformers (PTs and CTs) and control fuse size and check continuity. Also check PT and CT polarity and transformer turns ratio. Temporary wiring jumpers should be removed. Verify ground connections properly made. Verify incoming primary and secondary connections properly made and checked for shorts or undesired grounds. Verify all equipment that has been removed during assembly has been replaced. Verify relays are coordinated with other relays and protective devices on the system. Refer to relay instructions before making any adjustments. Consult local utility before making any connections to the power supply. Verify storage battery fully charged and provided with charger. Verify interlocks performing properly. Circuit breakers should be checked and prepared per instruction book. All filters in vent areas are clean and free of shipping or construction material. Once complete, the insulation resistance and dc hi pot test should be performed. Descriptions of these tests are found in paragraph 2-4. Before performing insulation tests precautions should be made to eliminate damage to electronic controls/sensitive equipment attached to the bus. The insulation resistance test should be made on the high voltage circuit to be sure that all connections made in the field are properly insulated. A dielectric test should then be made on the high voltage circuit for one minute at the maximum test voltage. Once completed and passed, the switchgear is ready for energization.

3-5. Switchgear - low voltage

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. A visual inspection of the area where the switchgear is installed should be performed to confirm that there is adequate aisle space at the front and rear of the equipment for proper ventilation, service and maintenance of the equipment. The switchgear should be checked to insure it is properly anchored to its foundation. All switches, circuit breakers, and other operating mechanisms should be manually exercised to make certain they are properly aligned and operate freely. An insulation resistance test should be performed to make sure the switchgear is free from short circuits and grounds. This should be done both phase-to-ground and phase-to-phase and with the switches or circuit breakers both opened and closed. Any electrical relays, meters, or instrumentation should be checked to determine that connections are made properly and the devices function properly. Electrically exercise all electrically operated circuit breakers, and other mechanisms (but not under load), to determine that the devices operate properly. An auxiliary source of control power may be necessary to provide power to the electrical operators. Test the ground fault protection system (if furnished) in accordance with the manufacturer's instructions. Check the settings of the adjustable current and voltage trip mechanisms to confirm that they are at the proper values. Make certain that field wiring is clear of live bus and, where necessary, physically secured to withstand the effects of fault currents. Check to determine that all grounding connections are made properly. Remove all debris; scrap wire, etc., from the switchgear interior before closing the enclosure. Install covers, close doors, and make

certain that no wires are pinched and that all enclosure parts are properly aligned to be tightened. Once the above is complete perform an insulation resistance test. Before performing insulation tests precautions should be made to eliminate damage to electronic controls/sensitive equipment attached to the bus. The Insulation Resistance test is described in paragraph 2-4. Once completed and passed, the switchgear is ready for energization.

3-6. Transfer switch

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. The transfer switch shall be checked for completeness of assembly. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment such as loose parts and insulation damage. The Switch shall be checked for proper alignment and manual operation. The switch insulation resistance (phase-to-phase and phase-to-ground) shall be measured in normal and emergency positions. The wiring of the potential transformer to the control device should be checked for proper grounding. The timer settings should be checked against design parameters.

3-7. AC/DC drives

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. Drives are controllers used to vary the speed of a motor. Controllers are electronic devices that should never be megger tested. They typically come equipped with internal testing capabilities. Any diagnostic tests shall be performed as indicated in the manufacturer's manual. A visual inspection of the controller, enclosure, nameplates, connections, and drawings shall be performed. After removal of the controller enclosure cover, the controller shall be checked for physical damage and any debris from installation such as wire strands shall be removed using clean, dry, low-pressure air. All terminal connections shall be checked for tightness. The drive should be energized with no connection to the load and diagnostic test should be run. Motors should be tested separately as indicated in the motor paragraph.

3-8. Motors

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. A visual test of the motor shall be performed to ensure that the motor was not damaged in transit from the factory. Check that no loose items such as shaft keys, couplings, etc., are present. Check all connections for tightness and proper insulation. A mechanical test of the motor shall be performed to check that the motor is free from interference. This is accomplished by first uncoupling the motor from the driven machinery. The motor shaft is then manually rotated. The shaft should rotate freely. Once the above is complete, insulation resistance, power factor, dc hi-pot test, and polarization index tests shall be performed. The insulation resistance test (megger) shall be performed for motors less than or equal to 200 hp and 480V. For motors greater than or equal to 200 hp and 2400V the insulation resistance and polarization index are required. The insulation resistance, polarization index, and dc hi pot tests are required for motors exceeding 200 hp and 2400V. On ac rotating machines, the neutral connection on the stator should be removed and a test of each winding with respect to the other two windings and ground should be obtained. After insulation resistance readings have been made, the test voltage is returned to zero and the insulation is discharged. High pot each phase separately with the other two phases and the winding temp detectors grounded. Capacitors and surge arrestors should be disconnected during this test. Once completed and passed, the

motor is ready for energized checks. A phase check should first be performed by momentarily energizing or "bumping" the motor to confirm the proper direction of rotation. This will confirm that the correct phase connections have been made. Once the correct phasing is confirmed, the motor is ready for energization.

3-9. Generators

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. A visual inspection shall be made to check for any loose parts, connections, or foreign materials, nameplates/parts drawings. The clearance in the generator and exciter air gap shall be checked. Be sure the generator set turns over freely. Rotate the generator rotor by hand at least two revolutions to be sure there is no interference and it turns freely. Do not apply any mechanical force to generator fan when rotating generator rotor. The insulation on all wires shall be inspected. Insulation that is loose or frayed is unacceptable and should be repaired. All wiring should be checked against the equipment drawings and all connections should be secure. Loose or dirty connections are unacceptable and should be repaired. All leads should be supported or tied to keep them from being damaged by rotating parts or sharp corners. After installation, the generator shall be checked for proper mounting and grounding. Verify that the generator is connected for the required voltage. The equipment should be inspected for any foreign objects such as remaining packing materials, loose debris including, building materials, tools, hardware, rags, paper, leaves, etc., that could be drawn into the generator and removed. All bolts and fasteners should be checked for tightness. All covers and guards should be in place and secure. Always make a thorough visual inspection to check for any obvious problems before attempting to test and run the generator. If the generator is part of a motor generator (MG), uncouple the motor. Manually rotate the motor shaft to check that the motor is free from any interference and reconnect. Check that no loose items such as shaft keys, couplings, etc., are present. Check all connections for tightness and proper insulation. Insulation resistance, polarization index and dc overpotential tests shall be performed before the generator is energized.

a. Winding resistance test. The main stator winding resistance is very low. A meter capable of readings in the milli-ohm range would be required. A standard VOM can be used to check for continuity, shorts or grounds. The winding resistance is measured with a dc bridge and compared with the calculated design values. This value, corrected to operating temperature is also used to calculated stator I²R loss for efficiency determination.

b. DC overpotential test. Perform a dc overpotential (hi pot) test to assess the dielectric strength of the insulation of a generator. The ac voltage used in this test is the factory test value. For stator windings this value is typically calculated to be twice the rated voltage plus 1,000. High pot each phase separately with the other two phases and the winding temperature detectors grounded. Capacitors and surge arrestors should be disconnected during this test. Measure the voltages. Now the generator can be run with no load and tested by performing the constant excitation test and the current measurements.

c. No-load test. This test will determine whether a problem exists in the generator or regulator system. The theory behind this test is as follows. The output voltage of a generator is dependent on its speed, design, load, and exciter input current. If the speed and exciter input are known, the output voltage at no load can be measured and compared to the design value. With the generator shut down, connect voltmeter to the generator output. Disconnect the leads at the regulator and connect a 12-volt battery capable of supplying one amp to the leads. Check to make sure that the battery is connected to the leads with the correct polarity. With no load on the generator, (main breakers open) run the generator at rated speed. Measure generator output voltage. Shut the generator down. Compare the voltage reading with

design value, if they match the regulator is functioning properly (implement this procedure in accordance with manufacturers' recommendations).

d. Load test. This test will determine whether a problem with the sequence of the loading of the generator exists. With no load on the generator, (main breaker open) run the generator at rated speed. Gradually add load as sequenced. Standard procedures for commercial, routine and acceptance tests for determination of speed- governing performance characteristics of internal combustion engine-generator units can be found in ASME Power Test Codes (PTC) 26.

e. Operation of multiple generators in parallel. When operating multiple generators in parallel the operators must be aware of their operating sequence. For a system with three generators in parallel the operating sequence could be generator one then two then three or, two then one or three or, either one or two or three. A way to identify the scheme of a system is to functionally test the system by removing one generator from the system and verifying that the system operates. For example, when operating three generators in parallel, where two are normally operating and one is considered the backup generator the circuitry could be such that the first generator always acts as the starting generator and when it is up to speed, the second generator will synchronize to the first and following this, the third generator will synchronize to the second (one then two then three). In this arrangement if the first generator does not come up to speed (or is taken out of service), the second generator will not go on-line and subsequently neither will the third or, if the first generator does come up to speed but the second generator is down for service, the third will not go on-line since it is dependent on the third. A scheme where the first generator is the staring generator and either generator two or three synchronize to it is preferable over the first scheme since the probability of a second generator coming on-line is greater however you still stand the risk of the staring generator failing and thus halting the system. A preferred scheme is one where any of the three generators will perform as a starting generator and either of the remaining generators will synchronize to the generator on-line (one or two or three).

f. Speed control checks. When the alternating current generator sets are in parallel, load division between units is entirely controlled by the speed setting of the engine governors. Increasing the speed setting of one engine will cause it to absorb more load, and other generator sets in the system will be relieved of some load. Conversely, decreasing the speed setting of one engine will cause it to decrease load. Other generator sets will absorb that load. All load can be remove from a generator by slowly decreasing the speed setting. If the speed setting is moved lower than the no load point, that generator set will absorb power from other units which will continue to drive it at synchronous speed. It is impossible to have stable parallel operation if more than one unit in the system is set for zero speed droop (isochronous) operation unless the governors are the electronic load sharing type. When two or more units are operation in parallel, the regulator must control the excitation of the alternators so they share the reactive load. Two ways are: reactive droop compensation and reactive differential (cross current) compensation. Reactive droop compensation does not require wiring interconnection between regulators. During parallel droop compensation operation, the bus voltage droops (decreases) as the reactive lagging power factor load is increased. Reactive differential (cross current) compensation requires the addition of interconnecting leads between the current transformer secondaries and allows operation in parallel without voltage droop with reactive load. Cross current compensation can only be used when all the paralleling current transformers on all the generators delivering power to the bus are in the CT secondary interconnection loop. Because of this requirement, cross current compensation operation cannot be used when a generating system is operating in parallel with the utility power grid. Utility voltage can vary enough to cause high circulating current in a paralleled generator. KVAR controllers must be used to adjust generator voltage to match utility and minimize circulating current.

3-10. Batteries

Although battery type varies (e.g., NiCd, Lead Acid), the acceptance criterion remains generally the same. The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. Any apparent physical damage shall be recorded. If the battery is delivered filled, it shall be inspected to verify that no electrolyte has leaked during transit. If the battery cells are not delivered filled, it is recommended that they be filled according to manufacturer's recommendations before installation on racks. The individual cell condition check shall include visual inspection of cell integrity investigating evidence of corrosion at terminals, connections, racks, or cabinet. The general appearance and cleanliness of the battery, the battery rack or cabinet and battery area including accessibility shall be observed. The cells shall be checked for cracks in cell or leakage of electrolyte as well as the integrity of the cover. Electrolyte should be added to any cell in which the electrolyte level is below the top of the plates. Before installation, the voltage of each cell shall be measured. The voltage measured should be equal to or less than 0.05 V below the manufacturers open circuit voltage. If it is not, the manufacturer shall be contacted to determine the next course of action. The cell polarity for positive to negative connections shall be checked. The battery shall be assembled as shown on drawings. Each battery cell is then checked to ensure the electrolyte level is at the maximum level. The interconnection of the battery cells shall be checked for polarity. The connector bolts shall be checked to ensure that they have been tightened to the manufacturers recommended torque values. The cell internal ohmic values and the intercell connection resistances shall be then measured. This is accomplished by applying a load across the battery and measuring the step change in voltage and current for each cell taken between the positive and negative terminal posts of adjacent cells as well as the battery as a whole. The ohmic value is the change in voltage divided by the change in current. The resistance values for each cell shall then be averaged and any interconnection that varies more than 10% or 5 $\mu\Omega$ over the average shall be remade and then rechecked for its resistance value. These values shall become baseline values for comparison in future tests. The presence of flame arresters, adequacy of battery support racks, mounting, anchorage, grounding, and clearances, ventilation of battery room enclosure, and existence of suitable eyewash equipment shall be verified. After completion of the above inspections the battery is ready to be connected to the charger. After charging, the following should be measured: each cell voltage and total battery voltage with charger in float mode of operation; ripple current; specific gravity; electrolyte temperature; electrolyte fill level; overall float voltage measured at the battery terminals; charger output current and voltage; ambient temperature; condition of ventilation and monitoring equipment; and temperature of the negative terminal of each cell of the battery. When the battery is charged, use a voltmeter to check the polarity of the series connections. The total voltage shall be measured both across the battery and between adjacent cells and then shall be compared to the specified voltage. The total voltage should approximately be the resultant of the quantity of cells multiplied by the typical cell voltage. A variation is an indication that the battery may be improperly assembled.

a. Discharge test. The values for discharge time and end point voltage should be selected from the battery manufacturer's published ratings and the values used for the acceptance test should be approximately the same as that of the intended application. The discharge rate should be at a constant current or constant power load equal to the selected manufacturer's rating of the battery. The charging method used as the basis for the published data is an important factor. For a stationary float application, data based on prolonged constant potential charging should be used. If constant current charging has been used to establish the published data, appropriate float charging correction factors should be obtained from the manufacturer. Note that the test discharge current is equal to the rated discharge current divided by the temperature correction factor for the initial electrolyte temperature. Set up a load and the necessary instrumentation to maintain the test discharge rate determined in above. Disconnect the charging source, connect the load to the battery, start the timing, and continue to maintain the selected discharge rate. If the charging source cannot be disconnected, the current being drawn by the load has to

be increased to compensate for the current being supplied by the charging source to the battery. Read and record the individual cell voltages and the battery terminal voltage. The readings should be taken while the load is applied at the beginning and at the completion of the test and at specified intervals. There should be a minimum of three sets of readings. Individual cell voltage readings should be taken between respective posts of like polarity of adjacent cells so as to include the voltage drop of the intercell connectors. Maintain the discharge rate and record the elapsed time at the point when the battery terminal voltage decreases to a value equal to the minimum average voltage per cell as specified by the design of the installation times the number of cells.

b. Capacity check. The capacity of the battery is checked using the following equation:

Percent Capacity at the test rate at 25°C (77°F) = $(t_a / t_s) \ge 100$

Where:

- t_a is the actual time of the test to specified terminal voltage as corrected for temperatures
- t_s is the rated time to specified terminal voltage

3-11. Battery chargers

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. A visual inspection should be performed to verify the completeness of the equipment, correctness of installations, supports, grounding, and wiring. The rating plate shall be checked to ensure that both the ac supply to the charger and the battery to be connected corresponds to the charger's parameters. Confirm that all shipping and other debris in and around the charger cabinet have been removed. Check settings of the charger and calibrate per manufacturer's manual to match the battery (float and equalizing levels). If the battery charger has been factory set, check the charger float and equalizing voltage levels against drawings and specifications. If not, set the charger float and equalizing voltage levels to those listed on drawings and specifications. Before connecting to the battery, measure the output voltage provided by the charger and record. Verify that all charger functions and alarms operate correctly. Verification that the battery is connected to the battery charger properly is extremely important. The negative wire from the negative terminal of the battery must be connected to the negative terminal of the charger. Similarly, the positive wire from the positive terminal of the battery must be connected to the positive terminal of the charger. A battery charger is an electronic device that converts ac power to dc power. The charger supplies this dc power to the battery. As with all electronic devices, this device should not be megger tested.

3-12. UPS systems

The first step towards acceptance of any device is verification of nameplate data. The nameplate on all equipment shall be checked against one-lines and schematics. All equipment shall be carefully examined upon receipt to ensure that no damage has occurred during shipment. The Static UPS System consists of the battery charger, inverter, battery, transfer switch, circuit breakers, and cables. A picture of a typical UPS systems is seen in figure 3-1. Of the UPS system, the component testing for the battery charger, battery, transfer switch, circuit breakers, and cables are described individually in this manual. The inverter is similar in construction to the charger. It converts dc power to ac power using solid state electronics. Therefore, this device should not be megger tested. The completeness of the assembly shall be confirmed. A visual inspection should be performed to verify the correctness of installations, supports, grounding, and wiring. Verify that the air inlets are not obstructed. The interconnections shall be checked against the wiring schematic to ensure the proper phasing and voltage connections. For example, both the battery charger connections to the battery and the battery to the inverter should be checked to insure that

they have the correct polarity. Measure the input voltage provided by the battery and record. Measure the output voltage and current from the inverter and record. Verify that these values correspond to the design values.

3-13. Cables

For commissioning of cables, the receipt inspection and testing is performed while the cable is still on the reel. The exposed sections of the cables are visually inspected for signs of physical damage, the end caps are checked for tightness. The cable types and configuration are checked for correctness against drawings and purchasing documents. Continuity tests are performed on each conductor and the shield. For power cables, insulation resistance tests are performed between each conductor and each conductor and the shield. The cable installation shall be checked against one-lines and schematics. After installation, the cables are inspected for damage, proper trained bending radius, adequate spacing for ampacity, proper installation of fireproofing, proper size, termination, and identification. Next, conductors are checked for continuity. The following tests shall be performed before the cables are energized. They are the insulation resistance (megger) test and the dc hi pot test. For medium and high voltage shielded cables the acceptance is dependent on the dc hi pot test. A satisfactory test is the exponential decrease of current with time with a fixed dc voltage applied. Non-shielded cables are not




Figure 3-1. Static UPS system 150 to 750 kVA (courtesy of Liebert)

subject to the Hi-Pot test because only the sections of cable in contact with ground (such as cable tray rungs) are actually tested and therefore the test is not meaningful. Test duration should not exceed 5 minutes for non-shielded cable or 15 minutes for shielded cable. When performing a dc high potential test on cables, all precautions and limits as specified in the applicable NEMA/ICEA (Insulated Cable Engineers Association) standard for the specific cable should be followed. Tests should be performed in accordance with ANSI/IEEE Standard 400. Test voltages shall not exceed 80 percent of cable manufacturer's factory test value or the maximum test voltage in table 3.1 below. The test procedure should be as follows and the results for each cable test shall be recorded. Test each section of cable individually with all other conductors grounded. All shields must also be grounded. Terminations shall be adequately corona-suppressed by guard ring, field reduction sphere, or other suitable methods as necessary. Precaution should be taken to insure that the maximum test voltage does not exceed the limits for terminations specified in IEEE Standard 48 or manufacturers specifications.

Reduce the conductor test potential to zero and measure residual voltage at discrete intervals. Upon the completion of the test, apply grounds for a time period adequate to drain all insulation-stored charge. When new cables are spliced to existing cables, the dc high-potential test shall be performed on the new cable prior to splicing. After test results are approved for the new cable and the splice is completed, an insulation resistance test and a shielding continuity test should be performed on the length of the new and existing cable including the splice. After a satisfactory insulation resistance test, a dc high potential test shall be performed on the cable utilizing a test voltage acceptable to owner and not exceeding 60 percent of factory test value.

Insulation Type	Rated Cable Voltage	Insulation Level	Test Voltage kV (dc)
	5 kV	100 %	25
Elastomeric:	5 kV	133 %	25
	15 kV	100 %	55
Butyl and Oil Base	15 kV	133 %	65
	25 kV	100 %	80
	5 kV	100 %	25
	5 kV	133 %	25
	8 kV	100 %	35
	8 kV	133 %	45
Elastomeric: EPR	15 kV	100 %	55
Elastometic: EPK	15 kV	133 %	65
	25 kV	100 %	80
	25 kV	133 %	100
	28 kV	100 %	85
	35 kV	100 %	100
	5 kV	100 %	25
	5 kV	133 %	25
	8 kV	100 %	35
	8 kV	133 %	45
Polyethylene	15 kV	100 %	55
	15 kV	133 %	65
	25 kV	100 %	80
	25 kV	133 %	100
	35 kV	100 %	100

NEMA Table 10.6

Derived from ANSI/IEEE Standard 141-1993 Table 12-9 and by factoring the applicable ICEA/NEMA Standards.

NOTE: AEIC CS5 and CS6, and ANSI/IEEE Standard 400 do not differentiate cables based upon insulation thickness and, consequently, list differing test voltages.

Insure that the maximum test voltage does not exceed the voltage limits for potheads and terminators specified in IEEE Std. 48 (IEEE Standard Test Procedures and Requirements for High-Voltage AC Cable Terminations) or for molded rubber terminations specified in IEEE Std. 386 (IEEE Standard for Separable Insulated Connector Systems for Power Distribution systems Above 600 V), or manufacturer's published data.

Reprinted from NETA's Acceptance Testing Specifications, copyright 1999. Courtesy of the International Electrical Testing Association. All rights reserved.

CHAPTER 4

MAIN POWER SYSTEM

4-1. Description of main power system

The following is a sample main power system with associated one-line and wiring diagrams for use as a guide for implementing the test procedures described in the preceding chapters of this manual. The major equipment in this main power system includes 34.5 kV circuit switchers, 15,000 kVA oil filled transformers, and 13.8 kV metal clad switchgear including relays and controls. The equipment, accessories, interconnections, ratings, and cabling are shown in figures 4-1 through 4-7. All wiring connections and interconnected components should be verified during commissioning. Figure 4-1 diagrams the main power system single line on page 4-7. Figure 4-2 diagrams the main power system control cable block diagram on page 4-8. Figure 4-3 diagrams the main power system circuit switcher on page 4-9. Figure 4-4 diagrams the main power system switchgear load breaker on page 4-10. Figure 4-5 diagrams the main power system switchgear incoming breaker on page 4-11. Figure 4-6 diagrams the main power system switchgear incoming breaker on page 4-7 diagrams the main power system switchgear incoming breaker on page 4-11. Figure 4-6 diagrams the main power system switchgear incoming breaker on page 4-11. Figure 4-6 diagrams the main power system circuit switcher wiring diagram on page 4-12. Figure 4-7 diagrams the main power system incoming breaker wiring on page 4-13.

a. Switches. The 34.5 kV circuit switchers are outdoor vertical break, shunt trip with full momentary current capability and limited fault current interrupting for applications feeding power transformers. Each switch contains a high speed high torque power operator, interrupting units, disconnects, and post insulators. The operator receives a trip or open signal from relays or a control switch, trips the interrupter, and then opens the disconnect. If too much shunt current is available the relaying scheme will block the switch from opening until the current decreases to an acceptable level. Each circuit switcher has a 125 Vdc control circuit for control, relaying, and operator power. The circuit switcher is intended to operate on transformer overload, transformer secondary faults, transformer faults. The 12/15 MVA power transformers are outdoor oil filled with radiators and fans for cooling, temperature and fault indicating relays, bushing mounted current transformers, no load secondary tap changer, and a control and alarm panel. The control and alarm panel requires a 120/208V, three phase power source for the controls, cabinet heater, and alarms. The 13.8 kV switchgear is indoor; metal clad with individual spring operated vacuum circuit breakers and controls.

b. Breakers. The switchgear line-up contains two incoming, one tie, and eight load breakers. Each breaker has a relay/control compartment containing a control switch, indicating lights, relays, control wiring, and terminal blocks. The breakers have electrical and mechanical interlocks to prevent inadvertent operation, open/close springs, spring charging motors, position switches, and close and test positions. An auxiliary compartment in the switchgear is used to house the circuit switchers' control, indication, relays, and remote alarms; and the transformer remote alarms. For control, each circuit switcher and switchgear breaker has a control switch, indicating lights and relays. Each circuit switcher trip circuit contains overcurrent, differential current, transformer overload lockout, and transformer sudden pressure relays. The switchgear and load breakers have overcurrent relays. The tie breaker has no relaying, and is intended to be closed to the switchgear bus together when a transformer is out of service. It is interlocked to open or block closure if both of the incoming breakers are closed. There are potential transformers (PTs) on both sides of the switchgear and load circuit breakers. They are connected to undervoltage relays and sync check relays. The switchgear requires a 125 Vdc control and relay feed and 120 V single phase feed for space heaters.

4-2. Operation of main power system

Examples of operating modes for the main power system are as follows. These are some of the steps that would be included in a systems operation document (SOD). As a rule of thumb, all main power systems should be dynamically tested in all modes of operation.

a. Normal condition. Both utility feeders available, both circuit switchers closed, both transformers energized, both switchgear breakers closed, tie breaker open, and load breakers closed.

b. Abnormal condition. One utility feeder is not available. Associated circuit switcher and switchgear breaker open automatically, other circuit breaker and switchgear breaker remain closed, and tie breaker closes automatically into dead bus. Return to normal condition. Test abnormal condition again with the other utility feeder not available.

c. Maintenance condition. Manually open up main circuit breaker. Corresponding circuit switcher should operate, open, and tie circuit breaker should close. Return to normal condition. Repeat procedure with other main circuit breaker and circuit switcher.

NOTE: Automatic closing of the tie breaker during protective relay functions is a dead bus transfer. Manually closing of tie breaker or closing of incoming breaker with tie breaker closed will parallel both transformers and sync check relays will not permit breaker closing if the busses are not synchronized.

4-3. Commissioning test plan for main power system

A system verification and functional performance test should be performed on the main power system. These tests will include installation inspections, individual component testing, verification and continuity testing on wiring, control and interlock function checks, equipment energization, system operating measurements, functional tests, and a system test under all modes of operation including the pull-the-plug test.

4-4. Installation inspections and component testing of main power system

The following components are part of a typical main power system. These should be inspected and tested in accordance with information specified below and in chapter 3. The inspection can be considered part of prechecks and/or the functional performance tests (FPTs).

a. Circuit switcher. Verify nameplate data, sizing, and settings against drawings, completeness of assembly, loose parts and insulation damage, alignment and operation including limit switches and interlocks, insulation resistance test on each pole, interrupter time travel analysis and proper grounding. Figure 4-8 on page 4-14 shows a sample of a completed DA Form 7463-R for a circuit switcher.

b. Oil-filled transformer. Verify nameplate data, size and settings against drawings, completeness of assembly, loose parts and insulator damage, seals and oil levels, auxiliary device operation and settings for radiators, fans, cooling, alarms, gauges, tap changer, etc., proper grounding, insulating liquid analysis for dielectric breakdown, acidity, interfacial tension, power factor, color test, etc. Other tests should include insulation resistance phase-to-phase, phase-to-ground, current transformers, turns ratio – high-to-low windings at all taps, current transformers at all taps and impedance and polarity on current transformers. Figure 4-9 shows a sample of a completed DA Form 7464-R for a transformer.

c. Metal clad switchgear. Verify nameplate data, sizing, and settings against drawings, completeness of assembly, loose parts and insulation damage, breaker alignment and operation (leave open) including limit

switches and interlocks, bus insulation resistance (if not previously energized), relay calibration and settings including current transformer primary injection, insulator damage, proper grounding and current/potential transformer insulation resistance, turns ratio, and polarity. Figure 4-10 on page 4-16 shows a sample of a completed DA Form 7465-R for the switchgear.

d. Cabling. Verify proper use, voltage, labeling, and connections using drawings, tightness and neatness of terminations, and power cable insulation resistance (phase-to-phase and phase-to-ground). Figure 4-11 on page 4-17 shows a sample of a completed DA Form 7466-R for power cables.

e. Visual and electrical wiring inspections. The termination of each cable, shown on the cable block and wiring diagrams, should be checked to ensure each conductor matches the wiring and schematic diagrams. This is performed by yellowing each connection between components on the schematic and wiring diagrams; visually inspecting each connection for cable number, wire number/color, and terminal; and checking point-to-point continuity or "ringing out" each wire from end-to-end including grounds. Cables in similar diagrams to figures 4-2 through 4-7 should always be checked to verify that conductors match wiring diagrams. For example, Cable CIS from Circuit Switcher I to the Switchgear Control Panel should be checked to verify schematic diagrams (figure 4-6).

Equipment	Terminal No.
Circuit Switcher	2
Switchgear Control Panel	1

As this is done, the wire on each drawing should be colored or highlighted to show its termination has been checked. This process should be completed for all field wiring as a minimum and internal wiring if not previously performed at the factory.

4-5. Energizing and test of the main power system

The following are the steps to energize and test the main power system. These are some examples of the steps that should be included in a functional performance test (FPT).

a. Initial energization. The control circuits for each component shall be sequentially energized from the circuit switcher down to the switchgear load breakers with the utility fuses removed. The control and interlock functions for each circuit shall be verified by opening or closing the control switches, protective and lockout relay contacts, temperature switches, etc. with both circuit switchers closed, all switchgear circuit breakers closed, and the switchgear tie breakers open. For example, on a circuit switcher the functions as shown on table 4-1 should be performed and checked. Verify operation of transformer circuits as in (1) and (2) below.

Function	Action to Check
1) Energize Close/Trip Circuit	Green Light On
	Red Light Off
	Switcher Open
	Verify 86C/86I Normal
2) Close Control Switch	Red Light On
	Green Light Off
	Switcher Closed
3) Trip Control Switch	Green Light On
-	Red Light Off
	Switcher Closed
4) Reclose Circuit Switcher	Red Light On
	Green Light Off
	Switcher Closed
5) Trip 86C	Green Light On
-	Red Light Off
	Switcher Open
	86C Tripped
	Switcher Won't Reclose using Control Switch
6) Reset 86C	Green Light On
	Red Light Off
	Switcher Open
7) Close Control Switch	Red Light On
	Green Light Off
	Switcher Closed
8) Trip 86I	Green Light On
	Red Light Off
	Switcher Open
	86C Tripped
	Switcher Won't Reclose using Control Switch
9) Reset 86I	Green Light On
	Red Light Off
	Switcher Open
10) Close Circuit Switcher	Red Light On
	Green Light Off
	Switcher Closed

Table 4-1. Circuit switcher functional checklist

(1) Transformer trip. Verify circuit switchers and incoming breakers closed and tie breaker open. Simulate transformer trip by operating Transformer 87 relay. Verify 86's trip; and then associated circuit switcher and incoming breaker opens, and tie breaker closes transfer. Verify tie breaker transfer is "dead" bus by measuring continuity from high side of incoming breaker to unaffected bus. Reclose 86, circuit switcher, and incoming breaker. Open tie breaker. Repeat above process for other transformer.

(2) *Transformer maintenance*. Verify circuit switchers and incoming breakers closed and tie breaker open. Choose transformer to be removed from service. Close tie breaker. Open circuit switcher and incoming breaker for transformer to be maintained. Verify tie breaker transfer is "live" bus by measuring. Reclose circuit switcher and incoming breaker. Open tie breaker. Verify tie breaker transfer is "live" bus. Repeat above process for other transformer.

b. Energization of main power system. Individual components of the system shall be sequentially energized from the circuit switcher through the switchgear load breaker with the utility fuses installed as follows:

(1) Circuit Switcher 1 & 2. Verify main switchgear breaker open. Verify incoming voltage and phasing. Close circuit switcher. Measure voltage on secondary of transformer. Compare voltage and phasing on both transformer secondaries.

(2) 13.8 kV switchgear. Verify tie breaker and load breakers open. Close incoming breakers. Measure voltage on switchgear bus. Compare voltage and phasing across tie breaker, close and open tie breaker. Close load breakers one at a time. Measure voltage and current after closing each load breaker.

(3) Transformer trip test. Verify system energized with both circuit switchers closed, switchgear incoming and load breakers closed, and tie breaker open. Notify plant of impending transfer. Simulate transformer trip by operating 50/51 relay. Verify 86C trips and then associated circuit switcher and incoming breaker open and tie breaker closes. Measure voltage and current on switchgear buses and verify "dead" bus transfer of tie breaker. Reclose 86C circuit switcher, and incoming breaker. Open tie breaker. Verify tie breaker transfer is "live" bus by measuring bus voltages and current. Repeat above process for other transformer.

(4) Transformer maintenance test. Verify system energized with both circuit switchers closed, switchgear incoming and load breakers closed, and tie breaker opened. Notify plant of impending transfer. Choose transformer to be removed from service. Close tie breaker. Open circuit switcher and incoming breaker for transformer to be maintained. Verify tie breaker transfer is "live" bus by measuring voltage and current on switchgear buses. Reclose circuit switcher and incoming breaker. Open tie breaker. Verify tie breaker transfer is "live" bus. Repeat above process for other transformer.

(5) *Checklists*. The acceptance testing is complete when all test are performed satisfactorily and checklists for system components are complete. Figure 4-12 shows a sample of a completed DA Form 7467-R.

4-6. Possible failures and corrective actions of the main power system

Table 4-2 lists general problems that may arise during the testing of the equipment and systems along with possible troubleshooting techniques. For all problems, consult the equipment and component manuals for troubleshooting directions, check fuses/lights/breakers/etc. for continuity, check equipment calibration and settings, and look for faulty equipment or connections.

Circuit Switcher	Areas to Check
Devices will not	Mechanical alignment/Limit Switches
close/trip	Interlocks
	Relay and protective device settings and operation
	Check for mis-wired circuits
	Control circuit

Table 4-2. Possible failures and corrective actions of the main power system

Breaker	Areas to Check
Devices will not	Mechanical alignment/Limit Switches
close/trip	Interlocks
	Relay and protective device settings and operation
	Check for mis-wired circuits
	Control circuit
Devices trip	Relay and protective device settings and operation
inadvertently	Check for mis-wired circuits
	Control circuit
	System overload or short
	Ground on cable system

Transformer	Areas to Check
Transformer trips	System overload
	Cooling system
	Transformer internal short or bushing failure
	Transformer relay settings and operation
	Check for mis-wired circuits
	Transformer oil
Transformer overheats	System overload
	Cooling system

Main Power System	Areas to Check
Devices will not close	Mechanical alignment/Limit Switches
	Interlocks
	Check for mis-wired circuits
	Control circuit
Inadvertent trips	System overload
	Cable shorts or grounds
	Equipment shorts or grounds
	Transformer cooling
	Check for mis-wired circuits
	Relay and protective device settings




Figure 4-1. Main power system single line diagram




Figure 4-2. Main power system control cable block diagram




Figure 4-3. Main power system functional diagram circuit switcher (typical for 2)




Figure 4-4. Main power system functional diagram switchgear load breaker (typical for 8)




Figure 4-5. Main power system functional diagram switchgear incoming breaker (typical for 3)




Figure 4-6. Main power system circuit switcher wiring diagram (typical for 2)




Figure 4-7. Main power system incoming breaker wiring diagram

			SECTION A	-CUSTON	ER DATA							
1. PLANT/BUILDING		LOCATION			3. JOB NUMBER							
Bldg 1929	Fe	ort Tank					02-117	•				
4. EQUIPMENT Switcher	5. P	arcuit de 1	SIGNATION	l		6. DATE (YYYYMMDD) 200 20 82 3						
7. TEST EQUIPMENT TYPE/BRAND AND CALIBR/ Sparls test set		8. TESTED BY John Smith										
•			SECTION B	- EQUIPME	ENT DATA							
9. MANUFACTURER S & C	10. STYLES/ air/5673	S.O.		11. VO 35k V	DLTAGERA ⁻ /	ΠNG			12. CUF 2000 A	RENT RATI	ING	
13. INTERRUPTING RATING 500M V A				14. BL 500N	JS BRACINO /I V A	3						
	SECTIO	ON C - VISU	ALAND EL	CTRICAL/	MECHANIC	ALINSPE	CTION					
15. CHECK POINT	00	ND*	NOTES			CHECK	POINT			COND*		NOTES
EXTERIOR OF EQUIPMENT	A	1		EQUIP	MENTIDEN	TIFICATION				А		
COMPLETENESS OF ASSEMBLY	A	1		BRACI	BRACING					А		
ELECTRICALMECHANICAL INTERLOCKS	A	A			RPHASEO		A					
PROPER GROUNDING	A	A		HAZAI	RDOUSLOC	ATION				А		
ALIGNMENT AND ROTATION LIMITS	A	A		CONTA	ACT RESIST	ANCE				А		
TIGHTNESS OF BOLTED CONNECTIONS	A	A			ANCHORAGE							
PROPER LUBRICATION	A	1		RETER	REFERENCEDRAWINGS							
INTERRUPTER TIMETRAVEL	A	1		CONTR	CONTROL ORCUIT OPERATION							
MANUAL OPERATION	A	1		ENERG	IZED OPER/	ATION				A		
		s	ECTION D	ELECTRIC	ALTESTS							
16. INSULATION RESISTANCE		-GRD		GRD		RD		A-B		<u>ж</u>		CA
@ 5 k V 17.	50 m	negohm	/5 m	egohm		egohm	80 meg ENT MEASUF		85 m	egohm	80 1	negohr
MEASUREMENT DESCRIPTION			VOIT	AGE* *	VULIAGE				() IRF	ENT* *		
NA	A-N	B-N	CN	A-B	BC	СА	A	В			Ν	G
NA	A-N	B-N	CN	A-B	BC	СА	A	В		с	Ν	G
NA	A-N	B-N	CN	A-B	BC	СА	A	В		с	Ν	G
18. NOTES:	I											I

* CONDITION: A= ACCEPTABLE; R= NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C= CORRECTED; NA= NOT A PPLICABLE ** NOTE VALUE AND PHASING

** NOTE VALUE AND PHASING DA FORM 7463-R,

USAPA V1.00

XFMR-T1 CKT-A 7. TEST EQUIPMENT TYPE/BRAND AND CALIBRATION DATE AEMC Megger, DTR, Biddle DLRO, Power Factor Test Set SECTION B - EQUIPM 9. MANUFACTURER Cooper 10. STYLES/S.O. Oil-filled 11. 3450 9. MANUFACTURER Cooper 14. DRY BULB TEMPERATURE 85 F 15 SECTION C - VISUAL AND ELECTRICA 15 65 F SECTION C - VISUAL AND ELECTRICA 17. CHECK POINT COND* 17. CHECK POINT A PROPER GROUPMENT A PRO COD CONDITION OF EQUIPMENT A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX	VOLTAGE RATIN 00: 12470Y/7200 . ENCLOSURE TY AL/MECHANICAL CHECH PER PHASE CONN E ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING) (PE NSPECTION (POINT IECTION AND CC ON :E	YMMD 200 12. (25M 16. 60hz	020823 CURRENT RA V A FREQUENCY	
XFMR-T1 CKT-A 7. TEST EQUIPMENT TYPE/BRAND AND CALIBRATION DATE AEMC Megger, DTR, Biddle DLRO, Power Factor Test Set SECTION B - EQUIPMENT TYPE/BRAND AND CALIBRATION DATE AEMC Megger, DTR, Biddle DLRO, Power Factor Test Set SECTION B - EQUIPM 9. MANUFACTURER 10. STYLES/S.O. Oil-filled 11. 3450 13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15 65 F SECTION C - VISUAL AND ELECTRICA 17. CHECK POINT COND* NOTES EXTERIOR OF EQUIPMENT A PRO COMPLETENESS OF ASSEMBLY A HAZ PROPER GROUNDING A WOP CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR @ 5 k V 70 megohm 70 megohm	VOLTAGE RATIN 00: 12470Y/7200 . ENCLOSURE TY AL/MECHANICAL CHECH PER PHASE CONN E ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING	8. TESTED BY John Smith G (PE NSPECTION (POINT IECTION AND CC ON	200 12.0 25M 16. 60hz	020823 CURRENT RA V A FREQUENCY COND* A A	-
9. MANUFACTURER Cooper 10. STYLES/S.O. Oil-filled 11. 3450 13. WET BULB TEMPERATURE 65 F 14. DRY BULB TEMPERATURE 85 F 15 SECTION C - VISUAL AND ELECTRICA 17. CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES EXTERIOR OF EQUIPMENT A PRO COD COM PLETENESS OF ASSEMBLY A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR NINDING CONFIGURATION A AUX AUX SECTION D - ELECTR A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	VOLTAGE RATIN 00: 12470Y/7200 . ENCLOSURE TY AL/MECHANICAL CHECH PER PHASE CONNE ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING	John Smith G (PE NSPECTION (POINT IECTION AND CC ON :E	12. 0 25M 16. 60hz	VA FREQUENCY COND* A A	
9. MANUFACTURER Cooper 10. STYLES/S.O. Oil-filled 11. 3450 13. WET BULB TEMPERATURE 65 F 14. DRY BULB TEMPERATURE 85 F 15 SECTION C - VISUAL AND ELECTRICA 17. CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES 17. CHECK POINT A PRO COM PLETENESS OF EQUIPMENT A PRO CONDITION OF EQUIPMENT A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm 70 megohm	VOLTAGE RATIN 00: 12470Y/7200 . ENCLOSURE TY AL/MECHANICAL CHECH PER PHASE CONNE ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING) (PE NSPECTION (POINT IECTION AND CC ON :E	25M 16. 60hz	VA FREQUENCY COND* A A	
CooperOil-filled345013. WET BULB TEMPERATURE 65 F14. DRY BULB TEMPERATURE 85 F15SECTION C - VISUAL AND ELECTRICA17.CHECK POINTCOND*17.CHECK POINTCOND*NOTESEXTERIOR OF EQUIPMENTAPRO CODCOM PLETENESS OF ASSEMBLYAHAZPROPER GROUNDINGAWOFCONDITION OF INSULATIONAANCTIGHTNESS OF BOLTED CONNECTIONSAREFESEALS AND OIL LEVELSR3.TURWINDING CONFIGURATIONAAUXSECTION D - ELECTRA-GRDB-GRD@ 5 k V70 megohm70 megohm	200: 12470Y/7200 ENCLOSURE TY AL/MECHANICAL CHECH CHECH PER PHASE CONNE ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING) (PE NSPECTION (POINT IECTION AND CC ON :E	25M 16. 60hz	VA FREQUENCY COND* A A	
65 F 85 F SECTION C - VISUAL AND ELECTRICATION 17. CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES EXTERIOR OF EQUIPMENT A PRO COM PLETENESS OF ASSEMBLY A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	AL/MECHANICAL CHECH PER PHASE CONN E ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING	NSPECTION POINT IECTION AND CC ON	60hz	COND* A A	
17. CHECK POINT COND* NOTES EXTERIOR OF EQUIPMENT A PROCOD COMPLETENESS OF ASSEMBLY A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	CHECK PER PHASE CONN E ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING	EPOINT	DLOR	A A	NOTES
CHECK POINT COND* NOTES EXTERIOR OF EQUIPMENT A PRO COMPLETENESS OF ASSEMBLY A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	PER PHASE CONNE ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING	IECTION AND CC	DLOR	A A	NOTES
EXTERIOR OF EQUIPMENT A COD COM PLETENESS OF ASSEMBLY A HAZ PROPER GROUNDING A WOF CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	E ARDOUS LOCATI RKING CLEARANC HORAGE ERENCE DRAWING	ON E	DLOR	А	
PROPER GROUNDING A WOR CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	RKING CLEARANC HORAGE ERENCE DRAWING	E			
CONDITION OF INSULATION A ANC TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	HORAGE ERENCE DRAWING			А	
TIGHTNESS OF BOLTED CONNECTIONS A REFE SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	ERENCE DRAWING	38			───
SEALS AND OIL LEVELS R 3. TUR WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm		SS		А	
WINDING CONFIGURATION A AUX SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm				А	
SECTION D - ELECTR 18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	TURNS RATIO MEASUREMENTS			А	
18. INSULATION RESISTANCE A-GRD B-GRD @ 5 k V 70 megohm 70 megohm	ILIARY DEVICE O	PERATION			
@ 5 k V 70 megohm 70 megohm	C-GRD	A-B		B-C	C-A
	85 megohm	A-D	L	B-C	
	2.7				
TURNS RATIO TEST					
POWER FACTOR 0.5 0.5	0.45				
PROPER VOLTAGE					
19. NOTES:	1	I		I	
	a				
1. PERFORM GROUND RESISTANCE TESTS PRIOR TO ENER	GIZING EQUIP	MENT.			
2. GROUND RESISTANCE TESTS MUST BE PERFORMED IN I 48 HOURS AFTER RAINFALL.	DRY CONDITIO	ONS AND SHA	LL BI	E PERFORI	MED
3. REPLACE GASKET.					

DA FORM 7464-R,

USAPA V1.00

BUS AND SUPPORT INSULATORS	А			HAZ	ARDOUS	LUCATI	ON			A					
PROPER LUBRICATION	А			WOF	RKING CL	.EARANG	E			А					
CLEAN SWITCHGEAR	А	A ANCHORAGE A A ALL FILTERS AND VENTS CLEAR A A ALL FILTERS AND VENTS CLEAR A A CHECK PROPER EQUIPMENT GROUNDING A A CHECK INCOMING BUS A A CHECK INCOM ING LINE CONNECTIONS TO MAIN BUS A A CHECK INCOM ING LINE CONNECTIONS TO MAIN BUS A A VERIFY PROPER SIZE BREAKERS/FUSES A DLING HEAVY PARTS 19. VERIFY CORRECT OPERATION OF INDICATING LIGHTS, METERS GAUGES, ETC. A MANUFACTURER 21. VERIFY SPACE HEATER IS PROVIDED AND OPERATIONAL C-A VOLTAGE AND CURRENT MEASUREMENTS VOLTAGE AND CURRENT MEASUREMENTS VOLTAGE** CURRENT** VOLTAGE** VOLTAGE** CURRENT** VOLTAGE** VOLTAGE** VOLTAGE** VOLTAGE** VOLTAGE** VOLTAGE** VOLTAGE** VOLTAGE** VOLTAGE** <td< td=""></td<>													
CHECK MANUAL OPERATION OF CIRCUIT BREAKERS AND RELAYS	А			ALL	L FILTERS AND VENTS CLEAR										
TEST RELAYS (ACCORDING TO ELEC. STUDY RECOMMENDATIONS)	А	A WORKING CLEARANCE A A ANCHORAGE A A ALL FILTERS AND VENTS CLEAR A A ALL FILTERS AND VENTS CLEAR A A CHECK PROPER EQUIPMENT GROUNDING TO GROUNDING BUS A A SWITCHES FOR FREEDOM OF MOVEMENT A A CHECK INCOMING LINE CONNECTIONS TO MAIN BUS A A VERIFY PROPER SIZE BREAKERS/FUSES A ING HEAVY PARTS 19. VERIFY CORRECT OPERATION OF INDICATING LIGHTS, METE GAUGES, ETC. A ANUFACTURER 21. VERIFY SPACE HEATER IS PROVIDED AND OPERATIONAL VERIFY SPACE HEATER IS PROVIDED AND OPERATIONAL VOLTAGE AND CURRENT MEASUREMENTS VOLTAGE** CURRENT** N B-N C-N A N B-N C-N A B N B-N C-N A-B B-C N N B-N C-N A-B C N C N B-N C-N A-B C N C N B-N C-N A-B C N C													
CHECK INSTRUMENT AND RELAY COVERS	А	A ANCHORAGE A A ALL FILTERS AND VENTS CLEAR A A ALL FILTERS AND VENTS CLEAR A A CHECK PROPER EQUIPMENT GROUNDING TO GROUNDING BUS A A CHECK INCOMING LINE CONNECTIONS TO MAIN BUS A A CHECK INCOMING LINE CONNECTIONS TO MAIN BUS A A VERIFY PROPER SIZE BREAKERS/FUSES A LING HEAVY PARTS 19. VERIFY CORRECT OPERATION OF INDICATING LIGHTS, METER GAUGES, ETC. A IANUFACTURER 21. VERIFY SPACE HEATER IS PROVIDED AND OPERATIONAL E SECTION D - ELECTRICAL TESTS A VOLTAGE AND CURRENT MEASUREMENTS VOLTAGE AND CURRENT MEASUREMENTS VOLTAGE** CURRENT** VOLTAGE** CURRENT** CURRENT** N B-N C-N A N B-N C-N A B N B-N C-N A B C N MADE AFTER UTILITY SOURCE IS CONNECTED TO INCOMING BREAKED A A B C N													
CHECK CIRCUIT BREAKER INSULATING PARTS	А					А									
CHECK CIRCUIT BREAKER CONTACT SURFACES	А			VERI	FY PROP	ER SIZE	BREAKERS	S/FUSE	S	А					
18. VERIFY LIFT OR BUILT WINCH FOR H	ANDLING	G HEA	VY PARTS				TOPERAT	ION OF	INDIC	ATING	LIGHT	S, METERS,			
20. VERIFY BOLTED BUS CONNECTIONS RECOMMENDATIONS	ΓΟ ΜΑΝ	UFAC	TURER	21.	VERIFY	SPACEH	IEATER IS	PROVIE	DED A	ND OPE	ERATIO	NAL			
		SEG	CTION D - I	ELECTR	ICAL TES	STS									
22. INSULATION RESISTANCE	A-0	RD	B-G	RD	C-0	GRD	A-E	3		B-C		C-A			
@ 1000 V															
23.				VOL	TAGE AN		ENT MEAS	SUREME	ENTS						
MEASUREMENT DESCRIPTION			VOLTA							RENT*	*				
Main Secondary	A-N	B-N	C-N	A-B	B-C	C-A	A	В		С	N	G			
M 1	277	277	278	482	479	480	250	240		230	15	1.5			
	A-N														
			-		-					-					
	A-N	B-N	C-N	A-B	B-C	C-A	A	В		С	Ν	G			
WITH THE UTILITY BREAKER OPE	Ν.										ING B	REAKER			
* CONDITION: A= ACCEPTABLE; R= NEEDS ** NOTE VALUE AND PHASING	S REPAIR	R, REP	LACEMENT	OR AD	JUSTME	NT; C=	CORRECTI	ED; NA=	= NOT	A PPLI	CABLE				
DA FORM 7465-R,												USAPA V1.00			
	F :	4 10	<u>C</u>			F 7	465 D								

SECTION A - CUSTOMER DATA 1. PLANT/BUILDING 2. LOCATION 3. JOB NUMBER Bldg 316 Fort Tank 02-119 CIRCUIT DESIGNATION 5. CIRCUIT FED FROM 6. CIRCUIT FED TO 7. DATE (YYYYMMDD) F5 Main bus F220020823 8. TEST EQUIPMENT TYPE/BRAND AND CALIBRATION DATE 9. ENCLOSURE TYPE 10. TESTED BY AVO 414/ 5 Aug 2002 John Smith Air SECTION B - EQUIPMENT DATA 13. VOLTAGE RATING 11. MANUFACTURER 12. STYLES/S.O. 14. CURRENT RATING 600V 2000A Siemens 15. INTERRUPTING RATING 16. BUS BRACING 50 kA 50 M V A SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EQUIPMENT IDENTIFICATION EXTERIOR OF EQUIPMENT А А REFERENCE DRAWINGS BRACING А А ELECTRICAL/MECHANICAL DRAWOUT MECHANISM AND INTERLOCKS PROPER PHASE CONNECTION AND COLOR А А CODE BUS AND SUPPORT INSULATORS HAZARDOUS LOCATION A А RANCE А

SWITCHGEAR INSPECTION CHECKLIST For use of this form see TM 5-694; the proponent agency is COE.

4.

	For u				CTION CHECKLI					
		SE	CTIONA-C	บรา	TOM ER DATA					
1. PLANT/BUILDING Bldg M-1		2. LOCA Fort Tan	TION			3. JOB NUME 02-120	BER			
4. EQUIPMENT Cable		5. CIRCU F1	JIT DESIGNA	τιοι	Ν	6. DATE(YY)		DD) 0020823		
7. TEST EQUIPMENT TYPE/BRAND	AND C	ALIBRATION	DATE			8. TESTED BY John Smith	Y			
		SE	CTION B - EC	QUIF	PMENT DATA					
9. MANUFACTURER Rome										
13. WET BULB TEMPERATURE14. DRY BULB TEMPERATURE15. ENCLOSURE TYPE16. FREQUENCY65 F85 F60 hz										
	SECTI	ON C - VISUA	L AND ELEC	TRIC	CAL/MECHANICAL I	NSPECTION		1	1	
17. CHECK POINT		COND*	NOTES		CHECK	POINT		COND*	NOTES	
EXTERIOR OF CABLE RUN		А		BR	ACING AND SUPPO	RTS		A		
PROPER GROUNDING AT TERMINA LUGS TO BUS	L	А		СН	IECK PROPER SIZE (OF CABLE		А		
REFERENCE EXISTING 1-LINE DIAG	RAMS	А			GHTNESS AND NEA RMINATIONS	TNESS OF		А		
PROPER LUBRICATION A ANCHORAGE A										
CHECK GROUNDING AT SPLICE JC	DINTS	А			IECK PROPER SIZE T ATERIAL	ERMINAL LUGS	AND	А		
CHECK CABLE PHASE COLOR COD	Ε	А		СН	IECK CABLE PHASE	COORDINATION	N	А		
SHIELD CONTINUITY		R	2.	СА	BLE IDENTIFICATIC	N	A			
		A-GRD			C-GRD			D O	0.4	
18. INSULATION RESISTANCE APPLIED VOLTAGE 15 Kv		20 megohm	B-GRI a 30 meg			A-B		B-C	C-A	
19. NOTES		20								
1. PERFORM HIGH POTENT MANUFACTURER(S) RECOM 2. GROUND SHIELDS WERE	IMEND	DATIONS.				REQUIREME	NTS (OR		
* CONDITION: A= ACCEPTABLE; R	= NEED	S REPAIR, REPI	LACEMENTO	OR A	ADJUSTMENT; C= C	ORRECTED; NA	= NOT	APPLICABL	E	
DA FORM 7466-R,									USAPA V1.00	

TM 5-694

MAIN POWER ENERGIZATION CHECK	LIST
-------------------------------	------

For use of this form see TM 5-694; the proponent agency is COE.

				004, 11		ent agen	09 13 000	•					
		SEC	TION A -	CUSTO	MERDA	ТА							
1. PLANT/BUILDING Bldg 2582		LOCAT ort Tank	ON		3. JOB NUM BER 02-121								
	CIRCUIT F	ED FROM	l		CIRCUIT tput CB	FED TO	•	7.	7. DATE (YYYYMMDD) 20020823				
B. TEST EQUIPMENT TYPE/BRAND AND CALIBRATION DATE 9. TESTED BY Fluke 45/ 7 Aug 2002 John Smith SECTION B - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION													
:	SECTION B -	VISUAL	AND ELE	CTRICA	L/MECH	ANICAL	NSPECTIC	N					
10. CHECK POINT	CONE	* N	IOTES			СНЕСК		cc	ND*	NOTES			
COM PONENT INSPECTION/TESTING COM PLETED	A	A VERIFY SWITCHGEAR CONTROL FUNCTIONS							NS .	A			
WIRING VISUAL VERIFICATION	А			CHECK	FOR WO	ORKING	CLEA RA NO	CE		A			
VERIFY WIRING DIAGRAMS	A				ENERGIZE AND TEST SYSTEM					A			
VERIFY CIRCUIT SWITCHER CONTRO FUNCTIONS	A	TRANSFORMER TRANSF					FER CONT	ROL		A			
ENERGIZE AND TEST SYSTEM FOR A CONDITIONS	A A	A CHECK FOR UNL ENERGIZING					SOUNDS	AFTER		A			
CHECK BUSHING OR TERMINALS	A	A CHECK ANCHORING OF TI SWITCHGEAR AND SWITC							RE A				
CHECK FOR REMOVAL OF PAINT OR HEAVY DENTS	A	A CHECK FOR NORMAL/ABNORMAL SWITCHING OPERATION								A			
		SECT	TION C -	ELECTR	CAL TES	TS							
11. MEASUREMENT DESCRIPTION					AGEAN	D CURR	ENT MEAS	SUREMEN	тs				
			-	AGE* *					URRENT				
Main Feed	A-N	B-N	C-N	A-B	B-C	C-A	A	B	C	N	G		
	7630	7630	7630	13kV	13kV	13kV	1200	1150	1200 C	125	5		
F1	A-N	B-N	C-N	A-B	B-C	C-A	A	В	C	N	G		
F2	A-N	B-N	C-N	A-B	B-C	C-A	Α	В	С	N	G		
F3	A-N	B-N	C-N	A-B	B-C	C-A	Α	В	С	N	G		
	A-N	B-N	C-N	A-B	B-C	C-A	A	В	С	N	G		
12. NOTES													

12. NOTES

1. Main circuit breaker did not open manually.

2. Voltage/current measurements should be compared with switchgear meters.

* CONDITION: A= ACCEPTABLE; R= NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C= CORRECTED; NA= NOT APPLICABLE ** NOTE VALUE AND PHASING

DA FORM 7467-R,

USAPA V1.00

CHAPTER 5

STANDBY POWER SYSTEM

5-1. Description of standby power system

The following is a sample standby (back-up) power system with associated one-line and wiring diagrams for use as a guide for implementing the test procedures described in the preceding chapters of this manual. A system functional performance test shall be performed on the system. The system shall be operated through all modes of systems operation including every interlock and conditional control logic, full load and part load conditions, and simulation of all abnormal conditions where there is a specific condition response. The system consists of the following equipment: 480V switchgear with utility, generator switchgear, and 500 KW, 480V generators with control panel, and synchronizing/paralleling panel. The equipment, accessories, interconnections, ratings, cabling, etc. are shown on figures 5-1 through 5-3 (figures show only part of a typical diagram). Figure 5-1 is the standby power system single line diagram on page 5-6. Figure 5-2 is the standby power system block diagram on page 5-7. Figure 5-3 is a diagram of the standby power system wiring on page 5-8. The system provides normal and standby 480V power to the Facility. Under normal conditions power is supplied from the utility through the Utility Power Center to the Facility Plant Load Center which feeds the facility loads. When utility power is lost, the diesel generators will supply power through the utility load center until normal power is restored. The 480V switchgear is metal enclosed and free standing with drawout air power circuit breakers. The main utility, generator breakers, and the facility load breaker are electrically/manually operated. The breakers have instantaneous short time and long time settings. Breaker controls and indication are located on the door of each breaker compartment. The main bus and incoming line have potential transformers connected to a synchronizing check (25) relay, and an undervoltage (27) relay. The 25 relay will not allow the utility breaker to be closed unless the switchgear bus and utility line are synchronized. The 27 relay opens the utility line breaker upon a loss of power (i.e. undervoltage). The 500 kW, 480 V generator sets include air cooled individual four cycle diesel engines, three phase, four wire generators, and paralleling/synchronizing control systems. The control system allows starting, stopping, loading, paralleling, and synchronizing of the generator to the system in the auto or manual mode while monitoring for equipment and system problems.

5-2. Operation of standby power system

The standby power system should be tested in all modes of system operation. The operating modes for the systems are as follows. These steps would be included in the systems operating document (SOD).

a. Normal condition. Under normal conditions, the utility power supply is energized, the utility breaker is closed, the load center circuit breaker is closed and the circuit breakers for the individual generators are open. The generators are not operating.

b. Loss of power. In the event of the loss of utility power, the utility power center 27 relay sends an open signal to the utility breaker, the load center circuit breaker, and a start signal to the generators. The generators operate either automatically or manually depending on mode selected. The generators will follow each other for load sharing and phasing. In the automatic mode, when the first generator is at the proper operating voltage and frequency, the control system sends a close signal to that generator's breaker. This generator becomes the lead machine. As the next generator picks up speed, the control system compares the outputs from that generator's potential transformers and the bus potential transformer and when the voltage and frequency are synchronized, a close signal is sent from the

synchronizer to the second generator breaker. This process is again repeated for the third generator. When all available generators are operating in parallel, a signal is sent to close the load center circuit breaker. In manual operation, the operator controls the diesel generator voltage and speed until the diesel generator is synchronized with other generators and then manually closes the diesel generator breaker. The operator repeats this process for each diesel generator set and then manually closes the load center circuit breaker. The process should proceed even if a generator fails to start or trips off line before load center breaker is closed. All possible scenarios should be tested.

c. Paralleling with utility. In the event that it is desired to parallel with the utility, the system will operate in either the automatic or manual mode. In the auto mode, the generators will automatically synchronize with the utility bus and their breakers will close. In auto/manual mode, the generators will automatically synchronize with the utility bus but the breakers will be manually closed. In manual operation, the operator controls the generator voltage and speed until the diesel generator is synchronized with the bus voltage and then manually closes the diesel generator breaker. The operator repeats this process for each diesel generator set.

d. Restoration of utility. In the event of a loss of utility power the generators are running and supplying the load. The utility breaker is open and all of the generator breakers are closed. When the utility power is restored, the operator manually adjusts the generator speed and voltage very slowly until the sync check relay on the utility power center is energized and illuminates the sync check light. The operator manually closes the utility breaker and then manually trips the generator breakers at the generators control panels. For systems that employ automatic synchronizing devices, it is possible for the system to synchronize to the utility and transfer power from the generator sets to the utility without operator intervention. The automatic synchronizing devices adjust the generator speed and voltage until the generator is in sync with the utility. Then the utility breaker is automatically closed and the generator breaker is automatically tripped.

5-3. Commissioning plan for standby power system

A system verification and functional performance test should be performed on the standby power system. These tests will include installation inspections and individual component testing verification and ring out of wiring, control and interlock function checks, equipment energization, and system operating measurements and functional tests. The system operation should be verified for each mode of operation identified in the SOD and ascertain that system will operate as designed as components operate normally and/or abnormally.

5-4. Installation inspections and component testing of standby power system

The following components are part of a typical standby power system. These components should be inspected/tested in accordance with information specified below and in chapter 3. These checks can be considered part of the pre-checks or functional performance tests (FPTs).

a. Generator. Verify completeness of assembly, proper nameplate data, loose parts and insulation damage, generator air gap and free rotation, generator insulation resistance (phase-to-phase and phase-to-ground), generator polarization index, grounding and proper voltage and phase connections. Figure 5-5 on page 5-10 and 11 shows a sample of a completed DA Form 7468-R for the generator inspection.

b. Engine. Verify completeness of assembly, proper nameplate data, loose parts, and proper lubrication.

c. Switchgear. Verify completeness of assembly, proper nameplate data, loose parts and insulation damage, breaker alignment and manual operation, proper relay settings, bus insulation resistance (phase-to-phase and phase-to-ground), grounding, proper voltage and phase connections and potential transformer and control fuse size and continuity. See figure 4-10 on page 4-16 for sample checklist (DA Form 7465-R).

d. Cabling. Verify proper connections, tightness and neatness of terminations, power cable insulation resistance (phase-to-phase and phase-to-ground). See figure 4-11 (DA Form 7466-R) for sample checklist.

e. Visual and electrical wiring inspections. The termination of each cable, shown on the cable block diagram, shall be checked to ensure each conductor matches the wiring and schematic diagram. This is performed by yellowing each connection between components on the schematic and wiring diagrams; visually inspecting each connection; and checking the continuity or "ringing out" each wire end to end including grounds. For example Cable PWR1 from Diesel Generator 1 to the 480V Load Center should be checked to verify that the "black" wire is terminated as follows which is shown on figure 5-3:

Equipment	Terminal No.
Diesel Generator 1	L1
480V Load Center	T1

As this is done, the wire on each drawing should be colored or highlighted to show its termination has been checked. This process should be completed for all field wiring as a minimum and internal wiring if not previously performed at the factory where practical.

f. Check control functions. Individual circuits of each component shall be energized and checked for proper function.

(1) Generator. Energize control circuit with outgoing circuit breaker open and verify correct operation of indicating lights, alarms, analog outputs and status outputs (list). Locally start the generator following the manufacturer's instructions for energizing and starting. Verify machine comes up to speed and correct operation of indicating lights, alarms, analog outputs and status outputs. Measure output voltage and frequency. Check remote stop and then remote start functions, external load set function, watt/VAR/voltage outputs, trip and circuit breaker interlocks and other no-load functions specifically required by the generator instruction manual, if any. Energize and verify the operation of any accessory circuits (i.e. generator heaters, fuel heaters, battery chargers).

(2) 480V switchgear. Verify manual operation and local position indication of the main and generator breakers with feeder cables disconnected or breakers racked out. Check the calibration of under voltage, sync-check, and other relays in the main breaker control circuit per the manufacturer's instructions. Energize the main breaker control circuit and close the breaker electronically using the control switch. Verify proper operation of lights. Trip the main circuit breaker using the control switch and the undervoltage relay. Verify the 27 relay is not engaged when the switchgear bus is de-energized and verify sync-check relay prohibits out of phase operation of main breaker.

5-5. Energizing and test of the standby power system

In order to energize and test the standby power systems the following procedures must be completed.

a. Initial set-up. Verify that generator circuit breakers are open and the generators are ready to start

TM 5-694

b. Bus test. Close 480V switchgear main and feeder breakers, check voltage on bus, and verify 27 relay is energized. Read voltage and current on bus.

c. Manual sync/paralleling test. While 480 V switchgear bus is energized, place each generator in the manual sync mode. Start the first generator and verify it comes up to speed and voltage and is ready to take load (a load bank should be used). Manually adjust the speed and voltage of the first generator to be in sync with the 480V switchgear, verify with phase meters that both are in sync and close the first generator's circuit breaker. Verify that the generator picks up load. Measure voltage, current and frequency. Repeat this process for the other two generators. As each generator is connected, verify load is shared equally between the generators. Measure the voltage, current and frequency for each generator as it is connected. Repeat the entire process starting with the second generator and then again starting with the third generator to ensure that any one of the three generators can act as the starting generator.

d. Auto sync/paralleling test. Repeat the previous step with each generator in the auto sync mode. Each generator should automatically synchronize and close into the 480V switchgear bus. The process should proceed even if a generator fails to start or trips off line before load center breaker is closed. All possible scenarios should be tested.

e. Utility trip load test. Verify that the 480V main breaker is closed and the switchgear is energized. Measure voltage and current on the bus. Verify that the generator breakers are open and the synchronizers are in the auto mode. Trip the 480V main breaker (remove normal power supply). This causes the load center circuit breaker to open. Verify that all three generators start, synchronize, and pick up load (load center circuit breaker closes). Add load until each generator is fully loaded. Run the system for at least 4 hours powered only by the generators. Reconnect utility power and note if sync check relay in the 480V utility breaker is picked up. If not, slowly adjust the speed and voltage of the first generator until the relay is picked up indicating the generators are in sync with the utility. The speed and voltage of the second and third generators should follow the first generator as it is adjusted. Verify that the 480V switchgear bus voltage is in sync with the utility with a phase/voltage meter and close the 480V main breaker.

f. Checklists. In addition to the component test forms discussed above, checklists for utility and generator circuit breaker inspection (see figure 5-6 for completed sample of DA Form 7469-R) and back-up power system inspection (see figure 5-7 for completed sample DA Form 7470-R) must be satisfactorily completed.

g. Modified sequence of operations. The standby power system should be operated in all possible modes of operations. This should include normal and abnormal operations that a system will encounter; for example, simulate that a breaker has tripped.

5-6. Possible failures and corrective actions of standby power system

Table 5-1 lists general problems that may arise during the testing of the equipment and systems along with possible troubleshooting techniques. For all problems, consult the equipment and component manuals for troubleshooting directions, check fuses/lights/breakers/etc. for continuity, check equipment calibration and settings, and look for faulty equipment or connections. Engine manufacturers typically provide a fault tree for troubleshooting problems. Figure 5-4 is a typical fault tree. The fault tree tracks the symptoms of the problems to identify the most probable cause. For example, if the engine will not run and the starter turns the engine slowly then there is a problem with the battery. The causes of the problem are either loose or dirty connections or a discharged battery.

Engine Problem	Areas to Check
Will not start	Starter, battery, and connections; fuel system, level, pump, injectors, internal
	engine (valves, tappets, pistons), ignition system (gas engines) control system
	interlocks/permissives, mis-wired circuits
Poor	Fuel system and cleanliness, injectors or carburetor, internal engine, control and
Performance/Will not	ignition system, system kW requirements
handle load	

Table 5-1. Possible failures and corrective actions of standby power system

Generator Problem	Areas to Check
No Output	Check stator and rotor continuity, battery fluid level, diode pack, voltage regulator,
Voltage/Current	control system and interlocks, miss-wired circuits
Failure to synchronize	Mis-wired circuits, blown PT fuses, governor/regulator not calibrated properly
Failure to share load	Mis-wired circuits, governor/regulator not calibrated properly

480V Switchgear	Areas to Check
Problem	
Breakers won't close	Mechanical alignment/ interlocks, control circuit operation, relay and protective device settings and operation, close coil and mechanism, mis-wired circuits.
	Check control voltage.
Breakers won't trip	Trip coil and mechanism, control circuitry operation, mis-wired circuits
Breakers trip	Ground on bus or outgoing cable, relay and protective device settings and
inadvertently	operation, control circuitry operation, mis-wired circuits. Check control voltage.

Back-Up Power	Areas to Check
System Problem	
Generator Breakers	Control circuitry operation, auto/manual sync system, generator control system,
will not close	mis-wired circuits. Check control voltage.
Generator will not	Engine fuel and control system, generator voltage regulator, generator control
pick up load or	system, auto/manual sync system, protective device settings, mis-wired circuits
stalls/trips	
Generators don't share	Paralleling control system, mis-wired circuits, interconnecting unit control wiring
load	governor control systems, voltage regulating systems
Main switchgear	Generator sync system, breaker sync check relay, breaker control circuitry, mis-
breaker won't re-close	wired circuits. Verify "as builts" reflect actual circuit conditions.
on diesel generator	
powered system	




Figure 5-1. Standby power system single line diagram




Figure 5-2. Standby power system block diagram




Figure 5-3. Standby power system wiring diagram




Figure 5-4. Engine fault tree

			STOMER DATA				
. PLANT/BUILDING	2. LOCATION			3. JOB NUMBE	R		
Sldg 1929	Fort Tank			02-122			
. EQUIPMENT Genset	5. ORCUIT DE	SIGNATION		6. DATE (YYYY		0020823	
. TEST EQUIPMENT TYPE/BRAND AND CALIBRATIC	N DATE			8. TESTED BY			
iddle Insulation Tester/ 5 July 2002				John Smith	1		
MANUFACTURER	10. STYLES/S.O.		JIPMENT DATA 11. VOLTAGERATING		12 1	WRATING	
	Diesel 3416		4160		500		
3. ORCUIT BREAKER SIZE/INTERRUPTING RATING $00A/50kA$			14. Wetbulbtemperatur 65 F		15. DRYB 85 F	ULB TEMPERATUR	Æ
	SECTION C-VISU/	ALAND ELECTR	CAL/MECHANICALINSPEC	TION			
6. CHECK POINT	COND*	NOTES	CHECK	POINT		COND*	NOTES
XTERIOR OF EQUIPMENT	А	E	EQUIPMENT ID ENTIFICATION			A	
OMPLETENESS OF ASSEMBLY	A	E	BRACING			А	
QUIPMENT ROTATION	А	F	PROPER PHASE CONNECTION		A		
HEOK OIL LEVEL	A	F	REFERENCEDRAWINGS		A		
HECKFUELLEVEL	A	1	MORKING CLEARANCE		A		
ROPER EQUIPMENT GROUNDING	A	1	ANCHORAGE		А		
HECKMETERS/GAUGES	А	1	ALL FILTERS AND VENTS OLE		А		
IGHTNESS OF BOLTED CONNECTIONS	А	(CHECK EQUIPMENT ENVIRONN	ATION	А		
ERIFY GOVERNOR AND REGULATOR	Α	(CHECK FOR PROMISIONS OF S		А		
HEOK VIBRATION	A	(CONTROL SYSTEM		А		
HECK BATTERES	Α	(CHECK FUEL FILTER		А		
HECKRADIATORFLUID	А		CHECK ALA RM INDICA TORS: 1 FUNCTION	PROPERCOLOR FC	REACH	А	
ROPER SYSTEM GROUND	Α						
			CTRICALTESTS			•	•
7. INSULATION RESISTANCE @ 2500 V	A-GRD	BGRD	CGRD	A-B		BC	СA
₩ 2 <i>3</i> 00 γ	10 megohm	12 megol	hm 14 megohm				
POLARIZATION INDEX RATIO= 10 MINUTE/1 MINUTE	2.1	2.2	2.3				
DCOVERPOTENTIAL TEST @ V	notes 1 & 2						
8. NOTES	+	1	, I			I	
. PERFORM 5 MEASUREMENT . DC HIPOT MEASUREMENTS S QUAL INTERVALS.	SHOULD BEGIN	AT 20% C	OF MAXIMUM TES	T VOLTAG	E AND	INCREASE	E IN
MAX DC TEST VOLTAGE			ATING) x 1.6 = .8 FOR DC TEST	ON DIGT : T	1 4 57 7	N.N.T.	

(TEST MEASUREMENTS SHOULD NOT EXCEED MANUFACTURER'S RECOMMENDATION)

DA FORM 7468-R, AUG 2002

Figure 5-5. Sample of completed DA Form 7468-R (side1)

				SECTIO	ND-ELEC	TRICALTE											
19.	MEASUREMENT DESCR	PTION					VOLTAGE	GEAND CURRENT MEASUREMENTS									
				VOLTAGE**					CURRENT**								
			A-N	B-N	CN	A-B	BC	GA	A	В	С	N	G				
20. LOAD	TESTS AS A PERCENTAGE	EOF GENERATOR RAT	TING														
	NOLOAD	25 %		75 %		100 %		110% (PRIMEENGINEONLY)									
A-N	2400	2400		2395		238	39										
BN	2400	2400		2395		239	95										
GN	2400	2400		2392		2390											
A-B	4160	4160		4158		158 415											
BC	4160	4160		4157		4157		4157		415	50						
СА	4160	4160	4158			410	50										
А	0	17.5A	52A		52A			70	A								
В	0	17A		49A		69	A										
С	0	17A		50A		68	A										
Ν	0	0.5A		1.4A		1.5A											
G	0	0.3A		0.4A		0.5	A										

21. NOTES

1. VOLTAGE MEASUREMENT TO BE MADE AFTER GENERATOR IS STARTED AND CONNECTED TO LOAD (CAN USE LOAD BANK).

2. DURING COMMISSIONING OF GENERATOR SETS OR ANY EQUIPMENT, A REPRESENTATIVE OF THE MANUFACTURING COMPANY OR SUPPLIER MUST BE PRESENT TO WITNESS AND/OR PERFORM THE TESTS.

3. ENGINE GENERATOR TESTING IS A VERY INTENSIVE PROCESS AND REQUIRES A 10 TO 14 HOUR DAY DEPENDING ON THE EQUIPMENT BEING COMMISSIONED. SUPPLIER/MANUFACTURER NORMALLY SUPPLY GENERATOR TESTING LOAD REQUIREMENTS.

4. VERIFY ALL SYSTEM CHECK POINTS DURING LOAD CHANGES AND RECORD PER SPECIFIED REQUIREMENTS AND/OR EQUIPMENT MANUFACTURER.

5. PERFORM AND RECORD ENGINE MANUFACTURER'S RECOMMENDED CHECKS AND INSPECTIONS.

* CONDITION: A= ACCEPTABLE; R= NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C= CORRECTED; NA= NOT A PPLICABLE

** NOTEVALUEAND PHASING DA FORM 7468-R. AUG 2002

PAGE2 OF2 USAPA V1.00

ហា					KER INSPECTION proponent agency is CO					
		•	SECTION A-C	CUSTOM	ER DATA	1				
1. PLANT/BUILDING Bldg 358		2. LOCATION Fort Tan				3. JOB NUMBER 02-123				
4. EQUIPMENT			DESIGNATION	6. DATE (YYYYMMDD			(IDD)	D)		
CB1		Feeder 1				- · · ·	20	0020823		
7. TEST EQUIPMENT AND CALIBRATION DATE A V O Tester/7 Mar 2002		•				8. TESTED BY John Smith				
			SECTION B-E			•			-	
9. MANUFACTURER A V O	10. STY	1£5/S.O.		600 V			12. O 2000			
13. OROUIT BREAKER SIZE AND INTERRUPTING RA 200A/50kA				Air	UIPMENT CLASSIFICAT			15. F 60h	REQUENCY z	
16.	SE	ECTION C-VIS	SUAL AND ELEC		MECHANICALINSPEC	TION			1	
CHECK POINT		COND*	NOTES		CHECK	POINT		COND*	NOTES	
EXTERIOR OF EQUIPMENT		А		BRACIN	NG			А		
COMPLETENESS OF ASSEMBLY		А		PROPE	R PHASE CONNECTION	SAND COLOR CODE		А		
EXECTRICAL/MECHA NICAL IN TERLOOKS		А		HAZAF	DOUSLOCATION			А		
PROPER GROUNDING		А		WORKI	ING CLEARNACE			А		
CONTACT RESISTANCE		А		ANCHORAGE				А		
AUXILIARY WIRING		А		REFERENCE DRAWINGS				А		
PROPERLUBERICATION		А		CHECK RELAYS	MANUAL OPERATION	AND	А			
TIGHTNESS OF BOLTED CONNECTIONS		А			STESTED (ACCORDING MENDATIONS)	TO ELECTRICAL STU	DY	А		
EQUIPMENT ID ENTIFICATION		А								
		4.000	SECTION D-E					50		
17. INSULATION RESISTANCE	1	A-GRD	BGR					BC	СА	
@ 1000 V 18. NOTES	1	0 megohm	12 meg	onm	12 megohm					
1. MANUFACTURER'S INSTAL										
* CONDITION: A= ACCEPTABLE; R= NEEDS REPAIR, F ** NOTE VALUE AND PHASING	€PLACEV	IENT ORADJU	SIMENT; C= CC	KRECTED	; NA= NOT A PPLICABL	F				
DA FORM 7469-R, AUG 2002									USAPA V1.00	

			SECTION A	-CUSTON	IER DATA								
1. PLANT/BUILDING B1dg 316		2. LOCATION3. JOB NUMBERFort Tank02-131											
4. EQUIPMENT Switchgear/ controls	-	5. CIRCUIT DESIGNATION 6. DATE (YYYMMDD) Main 2) 2002082	23			
7. TEST EQUIPMENT AND CALIBRATION DATE Fluke 45/7 Aug 2002							8. TESTE John S						
			SECTION B				•						
9. MANUFACTURER Siemens	10. STYLES	S.O.		11. VC	LTAGERAT	ING		12. Q 2000	JRRENT RATIN A	NG			
	14. FREQUEN 60hz	NCY		15. W 65 F	ETBULBTE	EMPERATU	Æ	16. DI 85 F	RY BULB TEM	PERATURE			
•	SECTIO	ONC-VIS	UAL AND ELE	CTRICAL	MECHANIC	CALINSPE	CTION		ſ				
17. CHECK POINT	ω	ND*	NOTES			CHECK	POINT		α	ND*	NOTES		
COMPONENT INSPECTION/TESTING	A	A		WRING	GVISUALV	ERIFICATIO	N		I	A			
ENERGIZEAND TEST SYSTEM	A	\		பாபா	YTRIP/GEN	IERATOR BL	JILDING LOAD	TEST	A	A			
INSTALLATION INSPECTION/TESTING	A	\		TIGHT	NESSOFEC	OLTED CON	NECTIONS		ŀ	A			
GENERATOR CONTROLS AND FUNCTIONS	A	4		CHECK FOR PROPER SIZE BREAKER						A			
MRING CONTINUITY TESTING	A	\		REFERENCEDRAWINGS						A			
NORKING CLEARANCE	A	\	PROPER PHASING CONNECTIONS AND COLOR CODE A							A			
SWITCHGEAR CONTROL FUNCTIONS	A	A											
PERFORM AUTOMATIC TRANSFER SYSTEM (ATS) FUNCTIONS UNDER THEA DJACENT CONDITIONS.	A. OPE	RATENOR	MALPOWER						I	A			
	B. ALLO	GENERATO	ORS OPERATE						ŀ	4			
	C. GENI	ERA TORS 1	AND 2 OPE	ATE					1	A			
	D. GEN	ERATORS 2	2 AND 3 OPE	ATE					/	A			
	E GENE	FRATORS 1	AND 3 OPE	ATE						2	2.		
	F. RETU	JRN TO NC	RMAL POWE	RAFTERE	ACH OF THE	EABOVETE	STS						
	G. PAR					ALPOWE	R(ITEMSBTH	ROUGH E)					
8.			SECTION D-	ELECTRIC			ENT MEASUR						
MEASUREMENT DESCRIPTION			VOLT	\GE <u>*</u> *					CURRENT* *				
Fotal at Output	A-N	BN	CN 27.5	A-B	BC	CA	A	В	C	N	G		
L ·	277 A-N	277 BN	275 GN	480 A-B	480 BC	478 GA	600 A	600 B	600 C	1.5 N	0.5 G		
19. NOTES 1. CHECK FOR PROPER GROUN 2. DOES NOT OPERATE WITH T				PRIOR	TO ENI	ERGIZI	NG.						

DA FORM 7470-R, AUG 2002

USAPA V1.00



CHAPTER 6

UNINTERRUPTIBLE POWER SUPPLY SYSTEMS

6-1. Description of uninterruptible power supply (UPS) system

The following is a sample uninterruptible power supply (UPS) system with associated one-line and wiring diagrams for use as a guide for implementing the test procedures described in the preceding chapters of this manual.

a. Figure description. The uninterruptible power supply system consists of the following equipment: 480V utility feeder breaker, 480V generator and feeder breaker, 480V transfer switch, 200 kVA redundant UPS (two 200 kVA modules), 125 Vdc NiCad battery and a 208/120V UPS switchboard panel. Each 200 kVA UPS module consists of the following equipment: 480V incoming breaker, 125 Vdc rectifier, redundant 120/208 VAC inverters, static switches, bypass switches and miscellaneous breakers. The equipment, accessories, interconnection, ratings, cabling, etc. are shown on figures 6-1 through 6-3. Figure 6-1 is the uninterruptible power system single line diagram on page 6-9. Figure 6-2 shown on page 6-10 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system block diagram and figure 6-3 shown on page 6-11 is the uninterruptible power system wiring diagram (figures only show part of typical diagrams).

b. Switching. The utility and generator breakers are metal enclosed free standing, manually operated, air power circuit breakers. The breakers have instantaneous, short time, and long time trip settings with manual control and position indication on the door of the breaker compartment. The 480V transfer switch is metal enclosed, break before make, dead bus transfer, automatic on loss of voltage, solenoid operated, and mechanically held complete with microprocessor controls and indication, four pole switch. Transfer time and time delay settings are adjustable. The transfer switch will supply start and stop signals to the back-up diesel generator upon loss of and restoration of utility power. These controls are timed and must be coordinated with the diesel generator manufacturer for start-up, loading, and cool down times. Remote indication, control, alarm, etc. functions are also available.

c. UPS operation. The UPS is a static solid state system with a battery for back-up power. The rectifiers convert ac to dc power for supply to the redundant inverters and for charging the battery. The inverters receive power from either the rectifier or battery, and convert it from dc to ac. The inverters also include power conditioning equipment and circuits to remove harmonics developed in the system. Because the input power is converted from ac to dc to ac, power system disturbances are also removed from the UPS output. This makes UPSs ideal for use with sensitive electronic equipment and computers. The rectifiers and inverters are constructed with power diodes or silicon control rectifiers along with controls and filtering circuitry. The UPS also contains thermal magnetic molded case circuit breakers and two bumpless static switches. The switches will transfer the output of the UPS from one redundant inverter to the other upon failure of the lead inverter. The transfer between the inverters is accomplished with absolutely no loss of continuity of power to the load. In the sample system, as shown in figure 6-1, the two UPS modules are both sized to supply the entire load independent of one another. The 208/120 V switchboard is a metal enclosed, wall-mounted distribution panel with incoming and feeder unadjustable thermal magnetic molded case circuit breakers. The switchboard also receives a backup power supply from the utility power center for use during the maintenance of the UPS through two bypass switches.

d. Battery description. The nickel cadmium (NiCad) batteries are individual 1.2 volt cells in plastic or steel cases with nickel and cadmium plates in a potassium hydroxide solution. The cells are sealed, maintenance free and connected together in series on racks to supply 125 Vdc. The 120/208V UPS

switchboard panel contains two main and numerous molded case thermal magnetic circuit breakers to distribute the power. The breakers have instantaneous and overcurrent element trip characteristics. The UPS system provides normal and uninterruptible regulated power to sensitive emergency plant loads, like computers, communications, radar, security systems, lighting, etc.

6-2. Operation of uninterruptible power supply system

The UPS system should be tested in all modes of operation. Examples of operating modes for the UPS system are as follows:

a. Normal condition. Utility breaker closed, diesel generator not running but in auto mode, diesel generator breaker closed, transfer switch connected to utility, inverter A, primary module, connected through UPS static switch to UPS bus, all module circuit breakers closed, and UPS switchboard connected to the UPS (module A).

b. Loss of module one (primary. Loss of circuit breaker, rectifier, or inverter results in static switch changing to module two. Test should be performed with each component of module one malfunctioning.

c. Loss of module two (primary). Loss of circuit breaker, rectifier, or inverter results in static switch changing to module one. Test should be performed with each component of module two malfunctioning.

d. Loss of utility power. Battery supplies power to UPS bus through inverter A or B, transfer switch supplies start signal to diesel generator, diesel generator starts and ramps up to speed and transfer switch connects to diesel generator.

e. Restoration of utility. Utility power restored, transfer switch changes position to utility bus and diesel generator shuts down after a pre-set time.

6-3. Commissioning test plan for the UPS system

A system verification and functional performance test should be performed on the UPS system. These tests will include installation inspections, individual component testing, testing on wiring, control and interlock functional checks, equipment energization and system operating measurements and functional checks. The system operation should be verified for each mode of operation identified in the SOD and ascertain that system will operate as designed as components operate normally and/or abnormally (e.g., the pull-the-plug test).

6-4. Installation inspections and component testing of the UPS system

The following components are part of a typical UPS system. These components should be inspected and/or tested in accordance with information specified below and in chapter 3. The checks can be considered part of the pre-checks or functional performance tests (FTPs).

a. Utility and generator circuit breakers. Check completeness of assembly, verification of nameplate, sizes and settings against drawings. Check for loose parts and insulation damage, breaker alignment and manual operation (leave circuit breaker open) and bus insulation resistance (if not previously energized). Figure 5-6 (DA Form 7469-R) shows a completed checklist for circuit breakers.

b. Transfer switch. Check completeness of assembly, verification of nameplate, sizes and settings against drawings. Check for loose parts and insulation damage, switch alignment and manual operation, switch insulation resistance (phase-to-phase and phase-to-ground), PT and control fuse size and

continuity, ground connection and check timer settings. Figure 6-4 on page 6-12 shows a completed DA Form 7471-R for a transfer switch inspection.

c. UPS. Check completeness of assembly, verification of nameplate, sizes and settings against drawings, loose parts and insulation damage, proper settings, control fuse size and continuity, ground connection, proper neutral connection, proper phase and voltage connections (incoming, battery, inverter A, and inverter B) and manual operation of circuit breakers (leave open). Figure 6-5 on page 6-13 shows a completed DA Form 7472-R for the UPS inspection.

d. NiCad battery. Check completeness of assembly, verification of nameplate, sizes and connection against drawings, check loose parts, leaks, or damage, electrolyte level, vents sealed and plugs installed, grounding and measure voltage. Figure 6-6 on page 6-14 shows a completed DA Form 7473-R for a battery inspection.

e. UPS switchboard. Check completeness of assembly, verification of nameplate, sizes and settings against drawings, loose parts and insulation damage, ground connection, proper phase and voltage connections and manual operation of circuit breakers (leave open). Figure 6-7 on page 6-14 shows a completed DA Form 7474-R for the switchboard inspection.

f. Cabling. Verify proper use, voltage, labeling, and connection using drawings. Check tightness and neatness of termination and power cable insulation resistance (phase-to-phase and phase-to-ground). See figure 4-11 on page 4-17 (DA Form 7466-R) for sample of completed checklist.

g. Visual and electrical wiring inspections. The termination of each cable, shown on the cable block and wiring diagrams, should be checked to insure each conductor matches the wiring and schematic diagrams. This is performed by yellowing each connection between components on the schematic and wiring diagrams; visually inspecting each connection for cable number, wire number/color, and terminal; and checking point-to-point continuity or "ringing out" each wire from end to end including grounds. For example (figure 6-3) Cable BGATS1 from Automatic Transfer Switch to the Backup Generator should be checked to verify that the "black" wire is terminated as follows as shown on the schematic and wiring diagrams:

Equipment	Terminal No.
Automatic Transfer Switch	B1
Backup Generator	T1

As this is done, the wire on each drawing should be colored or highlighted to show its termination has been checked. This process should be completed for all field wiring as a minimum and internal wiring if not previously performed at the factory where practical.

6-5. Energizing and test of the UPS system

The following steps are performed to energize and test the UPS system.

a. Initial energization. Individual components of the UPS system should be sequentially energized from the source through the loads. As each item is energized, control functions, interlocks, and alarms should be checked for proper operation. Voltage, phasing, and current measurements should be made at each step.

b. Utility breaker. Verify diesel generator breaker opens. The system operation should be verified for each mode of operation identified in the SOD and ascertain that system will operate as designed as

components operate normally and/or abnormally. Verify incoming voltage, manually close the utility breaker, measure outgoing voltage and phasing of breaker, measure incoming voltage of transfer switch and note position of transfer switch and manually open breaker.

c. Diesel generator breaker. Verify utility breaker opens, start diesel generator, verify diesel generator voltage, verify diesel generator and utility voltage have same magnitude and phasing, manually close diesel breaker, measure outgoing voltage and phasing, measure voltage at transfer switch and note position of transfer switch, manually open breaker and stop diesel generator and place in auto.

d. Transfer switch. Verify diesel generator stopped and in auto, verify utility bus energized, manually close utility breaker. Verify position of transfer switch and indication light status, measure input and output voltage of transfer switch, check phasing of utility bus to output of transfer switch. Manually open utility breaker. Diesel generator should start and switch should transfer to diesel generator. Note timing of diesel generator start and transfer from opening of utility breaker. Manually close utility breaker. Switch should transfer to utility and diesel generator should stop after a preset time (verify timing). Note timing of transfer and diesel generator stop from closing of utility breaker. Push test switch to simulate normal source failure. Verify diesel generator starts and transfer switch changes to diesel generator power, return switch to utility feed and verify diesel generator stops.

e. UPS (rectifier/ battery charger/battery). Verify UPS incoming breaker open. Verify utility feed closed through to input of UPS and measure voltage and phasing. Verify rectifier/battery charger output A breaker open. Verify rectifier/battery charger output B breaker open. Verify battery breaker A open and measure battery voltage and polarity. Verify battery breaker B open and measure battery voltage and polarity. Verify battery breaker B open and measure battery voltage and polarity. Verify inverter A and inverter B incoming breakers open. Close UPS incoming breaker A and measure rectifier/battery charger A output voltage, check dc output meter. Press battery "pre charge" button, if available, and close rectifier/battery charger A output breaker and close battery breaker A. Measure battery charger voltage. Allow unit to run until battery fully charged or for a minimum of 24 hours. Record time. Measure rectifier/battery charger A output strenger until minimum voltage recorded (1 to 4 hours). Open battery breaker A. Close UPS incoming breaker B and measure rectifier/battery charger B output voltage, check dc output meter. Press battery charger B and measure rectifier/battery charger B output voltage, check dc output meter. Press battery charger B and close rectifier/battery charger B output breaker and close battery breaker B. Measure battery charger voltage. Allow unit to run until battery breaker B. Measure battery charger voltage. Allow unit to run until battery threaker B. Measure battery charger Voltage. Allow unit to run until battery fully charged or for a minimum of 24 hours. Record time. Measure rectifier/battery charger B output current and read meter every 4 hours.

f. UPS (inverter/static switch). Verify UPS operational through rectifier/battery charger and battery.

(1)Verify UPS normal condition operation. (Conduct all procedures below with module one as primary. Repeat procedures with module two as primary.)

- (a) Verify battery charged and on float.
- (b) Measure float voltage
- (c) Verify inverter A and inverter B breakers open.
- (d) Verify static switch switched to inverter A.
- (e) Close inverter A and B input breakers.
- (f) Measure inverter A and inverter B output voltage and read meters.

- (g) Verify inverter A and inverter B outputs in phase.
- (*h*) Verify static switch in inverter A position.
- (2) Verify proper operation of static switches.
 - (a) Open inverter A incoming breaker.
 - (b) Verify static switch switches to inverter B.
 - (c) Measure voltage and ensure bumpless.
 - (d) Close inverter A incoming breaker and verify static switch switches to A.
 - (e) Measure voltage and ensure bumpless.
 - (f) Open inverter B incoming breaker and verify static switch stays connected to inverter A.
 - (g) Measure voltage and ensure bumpless.
- (3) Verify low voltage trip.
 - (a) Open rectifier/battery charger output breakers.
 - (b) Open battery breakers.
 - (c) Verify inverter A and B trip on low voltage.
 - (d) Close rectifier battery charger B output breaker and battery breakers.
 - (e) Close inverter A and B input breakers.
 - (f) Open UPS incoming breakers.
 - (g) verify inverter A and B output (feed from battery).
 - (*h*) Measure voltage and current.
 - (i) Close rectifier battery charger A output breaker and battery breakers.
 - (*j*) Open UPS incoming breaker.
 - (k) Verify inverter A and B output present (feed from battery).
 - (*l*) Measure voltage and current.

g. Loading UPS. Close incoming breaker to UPS bus. Verify UPS is energized through static switch. Verify all UPS loads connected properly and ready to start Close load breaker on UPS bus sequentially. Measure voltage and read UPS meters at each step. Add load until UPS loads equal normal design load. Run for 4 hours and check for overheating.

h. Utility trip test. Verify UPS is loaded and connected to utility. Manually open utility breaker. Verify battery picks up load. Read current. Verify diesel generator starts, transfer switch transfers to diesel generator, diesel generator picks up load, and battery returns to float charge mode. Measure voltage and current at UPS and ensure bumpless transfer. Close utility breaker. Verify transfer switch transfers to utility, battery picks up load during transfer, diesel generator stops, and battery returns to float charge after utility picks up load. Measure voltage and current at UPS bus and ensure bumpless transfer.

i. Inverter A to inverter B loaded transfer test. Verify UPS loaded and connected to utility. Open inverter A incoming breaker. Verify static switch switches to inverter B. Measure voltage and current at UPS bus and ensure bumpless transfer. Close inverter A incoming breaker. Verify that static switch switches to inverter A. Measure voltage and current at UPS bus and ensure bumpless transfer.

j. Battery discharge test. Verify UPS loaded and connected to utility. Notify plant of pending UPS trip. Open diesel generator breaker and block auto and manual start. Open utility breaker. Verify battery picks up load. Measure battery voltage and current. Measure UPS voltage and current and ensure bumpless transfer. Operate UPS from battery until battery minimum voltage reached (1 to 4 hours). Record voltage. Verify inverter A and B trip when batteries reach minimum voltage. Notify plant of pending UPS re-energization. Reclose utility breaker. Close diesel generator breaker and return to auto start mode. Verify battery on float and charging, measure current. Verify when battery fully charged and record time to charge.

k. Checklists. The inspection is considered complete when the UPS System Inspection and Test (see figure 6-8 on page 6-16 for completed sample of DA Form 7475-R) is satisfactorily completed.

6-6. Possible failures and corrective actions

Table 6-1 lists general problems that may arise during the testing of the equipment and systems along with possible troubleshooting techniques. For all problems, consult the equipment and component manuals for troubleshooting directions, check fuses/lights/breakers/etc. for continuity, check equipment calibration and settings, and look for faulty equipment or connections.

Utility and Generator Circuit Breaker Problem	Areas to Check
Breakers will not close/trip	Mechanical alignment/ interlocks
	Relay and protective device settings and operation
	Mis-wired circuits
Breaker trips inadvertently	Ground on cable or system
	Relay and protective device settings and operation
	System overload
	Mis-wired circuits

Transfer Switch	Areas to Check	
Switch will not transfer	Solenoid operating mechanism	
	Time delay settings	
	Control panel	
	Mis-wired circuits	

UPS-Rectifier/ Battery Charger	Areas to Check		
No output voltage/ current	Input voltage/ breaker		
	Rectifier (SCR) and rectifier fuse		
	Input transformer		
	Control board		
Low output voltage	Dead input phase		
	Rectifier (SCR) and rectifier fuse		
	Voltage control settings or potential		
	Control board		

High output voltage	Input voltage high
	Voltage control settings or potential
	Control board
Output voltage not adjustable	Voltage control potential
	Control board
High output current	System overload/ short
	Current limit setting
	Control board
Low output current	Current limit setting
	Control board

UPS- Battery	Areas to Check	
Low battery voltage/ current/ capacity	Battery and cell connections	
	Electrolyte level	
	Cell voltage	
	Cell condition, cleanliness, and age	
	Float voltage/ current	
	Battery room temperature	
	Battery design versus actual load	
	Battery/ system ground	
Breaker trip	Battery / system short	
	System overload	

UPS- Inverters/ Static Switch	Areas to Check			
No output voltage/ current	Input voltage/ breaker			
	SCR or diode			
	static switch			
	constant voltage transformer			
	control boards			
Low output voltage	Input voltage			
x 0	System overload			
	System frequency			
	Control board			

UPS- Inverters/ Static Switch	Areas to Check
High/Low output frequency	Input voltage
	Alternate source
	Frequency control setting
	Control board

No transfer from Inverter A to Inverter B	Primary/alternate source
	Static switch
	Synchronizing circuit
	Control board

UPS System	Areas to Check
No output voltage/ current	Incoming voltage
	Circuit breakers
	System components

No transfer to Diesel generator	Diesel generator equipment/ breaker	
	Transfer switch	
Low/high output voltage/ current	Incoming voltage	
	System components	
	Battery sizing/ capacity	
	System sizing/ capacity	
Transfers not bumpless	Battery connection	
	Static switch	
	Control board	
Inadequate UPS capacity	UPS sizing/ capacity	
	Battery sizing/ capacity	




Figure 6-1. Uninterruptible power supply system single line diagram




Figure 6-2. Uninterruptible power supply system block diagram




Figure 6-3. Uninterruptible power supply system wiring diagram

			INSPECTION CHECK 694; the proponent agency				
SECTION A-CUSTOMER DATA 1. PLANT/BUILDING 2. LOCATION 3. JOB NUMBER							
Bldg 1928	Fort T			02-125			
4. EQUIPMENT Switch	5. ORO. F 1	JIT DESIGNATION		6. DATE (YY	6. DATE (YYYYMMDD) 20020823		
7. TEST EQUIPMENT AND CALIBRATION DATE Biddle/14 May 2002	·			8. TESTED B John Smi			
		SECTION B-E	EQUIPMENT DATA	ł			
Russell Electric	. STYLES/S.O.		11. VOLTAGERATING 12. OURRENT RATING 600 V 1 200 A				
13. SWITCH RATING 4 Pole			14. ENCLOSURETYPE			15. FRB 60hz	QUENCY
16.	SECTION C	-VISUALAND ELEC		SPECTION			1
CHECK POINT	COND*	NOTES	a	HECK POINT		COND*	NOTES
EXTERIOR OF EQUIPMENT	А		EQUIPMENT ID ENTIFICA	TION		А	
COMPLETENESS OF ASSEMBLY	A		BRACING			А	
INDICATING LIGHTS	A		PROPER PHASE CONNEC	TIONS AND COLOR CODE		А	
SWITCH FOR FREEDOM OF MOVEMENT	A		ENMRONMENTAL CLASS	BIFICATION		А	
ELECTRICAL/MECHANICAL INTERLOOKS	A		WORKING CLEARANCE	WORKING CLEARANCE		А	
ADJUST TIMING SETTINGS	A		ANCHORAGE			А	
PROPER EQUIPMENT GROUNDING	A		REFERENCEDRAWINGS			А	
CONTACT RESISTANCE	A		PROPERLUBRICATION			А	
TIGHTNESS OF BOLTED CONNECTIONS	A		PT AND CONTROL FUSE	SIZE		А	
			LECTRICALTESTS			-	·
17. INSULATION RESISTANCE A-GRD BGRD CGRD A-B BC CA @ V Image: Comparison of the c							
3. AUXILIARY CONTACTS OPER A *CONDITION: A= ACCEPTABLE R= NEEDS REPAIR REPI DA FORM 7471-R, AUG 2002							USAPAV1.00

			-694; the proponent agency is COE.				
. PLANT/BUILDING	2. LOCATI		CUSTOMER DATA	10	. JOB NUMBE	Ð	
31dg 358	Fort Ta	nk		0	2-126		
I. EQUIPMENT JPS	5. ORCUIT Main	DESIGNATION	ED TO 6. CIRCUIT DESIGNATION FROM Main	FED 7.	. DATE (YYY)	MMDD) 20020823	
8. TEST EQUIPMENT AND CALIBRATION DATE Fluke 45/7 Aug 2002	·			-	. TESTED BY ohn Smit	h	
		SECTION B-	EQUIPMENT DATA				
0. MANUFACTURER 11. Liebert	STYLES/S.O.		12. VOLTAGERATING 600 V		13. kV 130 1	A RATING KV A	
	SECTION C - V	ISUALAND ELEC	TRICAL/MECHANICALINSPECTIO	N	I		
4. CHECK POINT	COND*	NOTES	CHECK POIN	Л		COND*	NOTES
XTERIOR OF EQUIPMENT	А		EQUIPMENT ID ENTIFICATION			А	
COMPLETENESS OF ASSEMBLY	А		BRACING			А	
NDICATINGLIGHTS	А		PROPER PHASE CONNECTIONS AN	ID COLOR COI	DE	А	
SWITCH FOR FREEDOM OF MOVEMENT	А		ENVIRONMENTAL CLASSIFICATION	N		А	
MANUAL OPERATION OF CIRCUIT BREAKERS	А		WORKING CLEARANCE			А	
TIMING SETTINGS	А		ANCHORAGE			А	
PROPER GROUNDING	А		REFERENCEDRAWINGS			А	
ROPER VOLTAGE CONNECTIONS	А		CONTROL FUSESIZEAND CONTIN	UITY		А	
TIGHTNESS OF BOLTED CONNECTIONS	А		VERIFY ALL TRANSFER SWITCH OF	PERATIONS		А	
TEST CIRCUIT BREAKERS WITH CURRENT INJECTION TESTER	А						
			LECTRICALTESTS				
5. VAC(OUTPUT)	A-GRD	BG	D GGRD	A-B		BC	CA
16. NOTES	ONE POIN'	ΓONLΥ).					

* CONDITION: A= ACCEPTABLE, R= NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C= CORRECTED; NA= NOT A PPLICABLE

DA FORM 7472-R, AUG 2002

USAPA V1.00

			5-694; the proponent agency is (
			-CUSTOMER DATA		_		
1. PLANT/BUILDING B1dg 358	2. LOCATIO Fort Tai			3. JOB NUMB 02-133	R		
4. EQUIPMENT BAT-1	5. ORCUIT CKT-2	DESI GNATION		6. DATE (YYY)20823	
7. TEST EQUIPMENT AND CALIBRATION DATE Fluke 87, Hydrometer, Thermometer,	Load bank			8. TESTED BY John Smit			
		SECTION B	- EQUIPMENT DATA				
	D. STYLES/S.O. D 5		11. VOLTAGERATING 3 V olts per cell		12. CURREN	T RATING	
	4. FREQUENCY 0 hz		15. WET BULBTEMPERATI	JRE	16. DRYBUL 85 F	B TEMPERATU	RE
	SECTION C-VI	SUAL AND ELE	ECTRICAL/MECHANICALINSP	ECTION			
17. OHEOK POINT	COND*	NOTES	CHE	XPOINT		COND*	NOTES
EXTERIOR OF EQUIPMENT	А		EQUIPMENT ID ENTIFICATIO	N		А	
COMPLETENESS OF ASSEMBLY	А		BRACING			А	
ELECT ROLYTELEVEL	А		ENMRONMENTAL CLASSIFI	CATION		А	
VENTS SEALED AND PLUGS INSTALLED	А		WORKING CLEARANCE			А	
PROPER POLARITY CONNECTIONS	А		ANCHORAGE			А	
TIGHTNESS OF BOLTED CONNECTIONS	А		CHECK FOR EXHAUST FAN ENVIRONMENT	IF IN ENCLOSED		А	
PROPER GROUNDING	A		REFERENCEDRAWINGS			А	
CHECK FOR SHOWER AND EVEWASH STATION	А		CHECK FOR ACCESS TO BA	TTERIES FOR		А	
TEST CIRCUIT BREAKERS WITH CURRENT INJECTION TESTER	А		CHECK UPS CONTROL PAN	ELALARMS		А	
TEST CIRCUIT BREAKERS	А		TEST TRANSFER SWITCH			А	
	·	SECTION D	ELECTRICALTESTS				
18. MEASUREMENT DESCRIPTION			VOLTAGEAND CUR	RENT MEASUREMEN			
		VOLI	AGE* *		- CURF	NT**	
BATTERY VOLTAGE& CURRENT	POSIT	ΤVE	NEGATIVE	POSITIVE	NEG	ATIVE	GROUND

1. MEASURE RESISTANCE BETWEEN CELL CONNECTIONS.

2. MEASURE VOLTAGE ACROSS EACH CELL.

3. CHECK SPECIFIC GRAVITY OF EACH CELL.

4. TEST AND MAINTAIN BATTERY (CELLS) IN ACCORDANCE WITH MANUFACTURERS RECOMMENDATIONS.

* CONDITION: A= ACCEPTABLE, R= NEEDS REPAIR, REPLACEMENT OR ADJUST MENT; C= CORRECTED; NA= NOT A PPLICABLE

** NOTE VALUE AND PHASING DA FORM 7473-R, AUG 2002

USAPA V1.00

Figure 6-6. Sample of completed DA Form 7473-R

UNINTER						TCHBOARD INSP proponent agency is CC		IST		
			SEC	CTIONA-C	USTOM	ER DATA				
1. PLANT/BUILDING B1dg 1930		2. LOCATIO Fort Tan					3. JOB NUMBER 02-128			
4. EQUIPMENT Switchboard		5. ORCUITI Main	DESIG	ENATION			6. DATE (YYYYMN		0020823	
7. TEST EQUIPMENT TYPE/BRAND AND CALIBRATI Biddle	ON DATE	1					8. TESTED BY John Smith			
			SEC	CTION B-E	QUIPME	NT DATA				
9. MANUFACTURER Siemens	10. STY	LES/S.O.			11. VO 600 V	LTAGERATING		12. Q 2000	JRRENT RATIN) A	G
13. BUS RATING/CBINTERRUPTING RATING 2000 A/ 50k A								1		
	SE	CTION C-VIS	SUAL	AND ELEC	RICAL/N	IECHANICALINSPE	TION			
14. CHECK POINT		COND*	١	NOTES		CHECK	POINT		COND*	NOTES
EXTERIOR OF EQUIPMENT		А			BRACIN	IG			А	
COMPLETENESS OF ASSEMBLY		А			PROPE	RPHASECONNECTION	AND COLOR CODE		А	
INDICATINGLIGHTS		А			ENMRC	NMENTAL CLASSIFICA	TION		А	
MANUAL OPERATION OF CIRCUIT BREAKERS		А			WORKIN	NG CLEARANCE			А	
PROPER GROUNDING		А			ANCHC	RAGE			А	
CONDITION OF INSULATION		А			REFERE	NCEDRAWINGS			А	
PROPER VOLTAGE CONNECTIONS		A			VERIFY	PROPERSIZESOFBRE	AKERS AND FUSES		А	
TIGHTNESS OF BOLTED CONNECTIONS		А			CHECK BUS	PROPER EQUIPMENT (ROUNDING TO GROU	INDING	А	
EQUIPMENT IDENTIFICATION		А								
		•	SEC	TIOND-EL						
15. BUS INSULATION RESISTANCE		A-GRD		BGR		CGRD	A-B		BC	GA
@ 1000 V 16. NOTES	10	0 megohm	n	12 meg	ohm	12 megohm				
1. TEST ALL CIRCUIT BREAKE *CONDITION: A= ACCEPTABLE, R= NEEDS REPAIR DA FORM 7474-R, AUG 2002			-		-			TION 5	S.	USAPAV1.00

	For 5. Crit	CATION t Tank RCUIT DE tical	BECTION A- BIGNATION ALAND ELEC NOTES			CHECK	8. TESTE John S TION) (YYYY <i>MMDD)</i> DBY	2002082		
A. EQUIPMENT U.P.S. System 7. TEST EQUIPMENT N.A 3. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.	5. Cl Crit SECTION	RCUIT DES tical	ALAND ELEC		/IECHANIC		6. DATE 8. TESTE John S	(YYYYMMDD) DBY	2002082		
UPS System 7. TEST EQUIPMENT NA	SECTION CONC	tical IB-VISU	ALAND ELEC		/IECHANIC		8. TESTE John S TION	DBY	2002082		
N A CHECK POINT COMPONENT INSPECTION/TESTING NSTALLATION INSPECTION/TESTING	CONE				<i>IECHANIC</i>		John S				
CHECK POINT COMPONENT INSPECTION/TESTING INSTALLATION INSPECTION/TESTING	CONE				/IECHANIC						
OHECK POINT		*	NOTES			CHECK	POINT				
NSTALLATION INSPECTION TESTING	A								- u	ND*	NOTES
				ENERGI	ZEAND TE	ST SYSTEM	I		A	L .	
	А			ராயா	TRIP TEST	-			A		
	А			LOADE RETUR		RTEST (NC	RMAL, EMEF	RGENCY &	A		
GENERATOR CONTROL FUNCTIONS	A			тіднті	NESS OF BO	LTED CON	IECTIONS		А		
.CADING UPS TEST	А			BATTE	RY DISCHAI	RGETEST			А		
DISCONNECT RECTIFIERS & INVERTIERS SEPARATELY. DOES SYSTEM OPERATE CORRECTLY?	А			TEST A	LLUPSDIA	GNOSTICF	AULT INDICA	TORS	А		
•			ECTION D-				•				
0. UPSINPUT	A-N 277	BN 277	CN 277	A-B 465	BC 465	CA 465	A 100	B 150	C 100	N	G 4
	A-N	BN	CN	A-B	BC	СА	А	В	С	Ν	G
										20 N	4 G
UPS SWITCHBOARD HARMONIC (THD)	3%	3%	4%				38%	42%	40%		
	277 A-N 277 A-N	277 BN 277 BN	277 GN 277 GN	465	465	465	100 A 100 A	150 B 150 B	100 C 100 C	N 20	

Figure 6-8. Sample of completed DA Form 7475-R

CHAPTER 7

HIGH ALTITUDE ELECTROMAGNETIC PULSE (HEMP) AND HIGH POWER MICROWAVE (HPM) EQUIPMENT AND CONTROLS

7-1 General HEMP protection systems

Command, control, communications, computer, intelligence, surveillance, and reconnaissance (C4ISR) facilities contain miniature solid-state electronics. These devices will fail when subjected to voltages that exceed the dielectric strength of the component or when the device melts as a result of heating from currents induced by a radio frequency (RF) pulse. Most people are familiar with the effects of lightning upon solid-state equipment. Other sources are high power microwave (HPM), ultra wide band (UWB) waveforms, and high altitude electromagnetic (EM) pulse (HEMP). A nuclear weapon detonated 300 km above the United States can blanket the entire continental United States with the HEMP effects.

7-2 HEMP protection systems

Traditional methods of electromagnetic interference (EMI) isolation often use metal enclosures to prevent unwanted radiation from entering the circuit. These shields provide effective protection along with good grounding techniques; therefore, HEMP protection systems are static as they do not have any moving parts. An exception to this is finger stock material that springs into place when doors or windows are closed. Only during an electromagnetic pulse (EMP) environment does the system function to shield the hardened facility. HEMP protection system components should not be disturbed or disconnected. The following should be inspected/tested to verify that installation is correct and magnetic pulses will not causes damage to the mission or render it inoperative.

a. Electronic surge arresters. An area in which care must be taken to ensure compatibility in EM integration is surge protection. Some surge arresters used for lightning do not clamp fast enough to protect against HEMP. Some used for HEMP may not have great enough current carrying capacity for lightning protection in all situations. Check for bonding, shielding, and grounding.

b. Shielding. For HEMP-hardened facilities, some kind of EM shielding is essential. Shielding involves the use of a barrier or series of barriers to reduce the magnitude of the EM energy incident upon the electronic or electrical system to be protected. Shielding philosophy can be developed around different approaches. Check for bonding, shielding, and grounding.

(1) Global shielding (or hardening) is a protection concept that uses an overall shield to encompass the entire facility. In this approach, all conducting penetrations and all apertures are protected at the shield. The intent is to keep all HEMP fields and HEMP-induced transients outside the protected volume. The global shield could be placed on the entire outer walls, ceiling, and floor (surface) of the facility, or it could be reduced to a smaller volume that contains all

sensitive equipment to be protected. The most common shield material for global shielding of ground-based facilities is sheet steel with welded seams, although other designs can provide adequate global HEMP shielding.

(2) Tailored shielding is a protection concept in which shielding is designed and constructed according to specific protection requirements for the equipment involved. After defining the system to be protected, its possible operating configurations, the expected HEMP environment, coupling paths, equipment sensitivities, and subsystem/system criticalities, the required protection levels for various subsystems or groups of subsystems can be defined. Tradeoff studies may be performed for comparing various shielding arrangements to verify that they meet safety margins in protection, cost-effectiveness, maintainability, survivability, flexibility, and other requirements. The objective is to optimize protection for the specific mission-critical system. Tailored shielding options may include global shielding, zonal shielding, shielding of cabinets or components, or combinations thereof. In a typical tailored protection design, discrete protection will be provided to eliminate specific, localized deficiencies.

(3) Zonal or topological shielding is a concept in which a facility is divided into zones, with shielding barriers located topologically in a shield within a shield configuration. The outer zone is designated zone zero; zone one is inside shield one but outside shield two. Zones and shields are assigned increasingly larger numbers as they progress toward the more deeply nested areas.

(4) The term "system configuration" identifies which way the cables, wires, equipment, and subsystems are laid out in relationship to each other, as well as the relationship of these items to the topological boundaries. In some instances, the cables, connectors, and equipment casings are actually part of the topological protection. System configuration as defined does not directly attenuate the environment, but it is an important element in the topological protection concept. The system configuration influences protection design requirements since some configurations are easier to protect than others (e.g., co-location of all mission-critical equipment). Thus, the system configuration should be coordinated with the protection design and the protection topology will be optimal for a specific configuration. During the facility life cycle, the protection design may be required to accommodate some changes in configuration. To ensure that the configuration's design modifications do not compromise or defeat the protection, careful configuration management is necessary. The topology should be designed to tolerate configuration changes that are totally within a boundary. The boundary can never be violated (for example, opened), only extended. All modifications must be subjected to review by HEMP experts to ensure continual compliance with the HEMP hardening requirements. Check for bonding, shielding, and grounding.

(5) Conductive or metallic cable shielding or conduit is used in the zonal/topological protection concept to extend the boundary formed by equipment enclosures and thus provide a way to interconnect elements while maintaining boundary continuity. Cable shielding is also used to protect a wire or wires as they travel from one boundary to another. This would be the case with a shielded RF signal traveling from its entrance into a building to the RF receiver. From a HEMP standpoint, the shielding attenuates coupling of radiated energy within the first boundary as the signal travels to the receiver. Of course the shield is somewhat reciprocal in that it also prevents signals from radiating out of the cable. The main feature of cable shielding is continuity of the boundary provided by the cable shield/connector combination that may require special joints.

(a) Another way to maintain this continuity and provide cable shielding is by using steel conduit to house all wires and cables. The steel conduit will provide substantially higher shielding levels than the cable shields. Check for continuous welds of pipe to shielding

(b) Both cable shields and conduit connected to a shielded zone must have equal or greater shielding effectiveness than the shield.

c. Grounding. The grounding system for a HEMP protected facility shall use an equipotential ground and is connected to a welded stud that does not penetrate the shield. Another stud welded to the opposite side of the shield then will be connected to the exterior grounding system.

d. Shield penetration protection. All shielded zones will require penetrations to allow entry of equipment, personnel, electric power, communications, control signals, ventilation, water, fuel, and various fluids. Without protection, these penetrations compromise the shield.

(1) Large access doors are often necessary to provide an entry for equipment, supplies, or vehicles into HEMP hardened facilities. In facilities that require blast overpressure protection, large blast doors are used. These doors generally use one or more thick steel plates to provide protection. The door's inherent shielding ability is thus high, but its large size presents a difficult gasketing problem. If blast protection is not required, it is still necessary to design the door with a high degree of structural strength. This step is to ensure that the door can provide the necessary gasket compression force and that proper mechanical alignment of closure contact surfaces is maintained.

(2) Two concepts are commonly used for personnel entrances: conventional HEMP/radio frequency interference (RFI) shielded doors and personnel tunnels that act as waveguides below cutoff. The shielded doors generally use metal fingerstock or EMI/RFI gaskets to provide an EM seal around the door jamb periphery. Currently available gasket and fingerstock doors require regularly scheduled maintenance and/or replacement to maintain required shielding levels. The gaskets are relatively easily damaged and also require replacement. Air-expandable doors may also be used, although they typically have more maintenance problems. These doors generally use a movable subassembly of two shielding plates on a framework that is moved on rollers in and out of a steel-framed opening. When closed, air expansion tubes cause the two shielding plates to make uniform surface contact with the frame inner surfaces.

e. Electrical penetrations. A common feature for electrical penetrations in a global protection approach is a cable entry vault to prevent large currents on external conductors from being conducted into the facility. Ideally, all penetrations should enter a single vault. In some cases, however, it may be necessary to separate the vault into two compartments or to use two vaults for penetrations by different types of lines: power, signal and control, and antenna. The vault must be connected directly to the external facility ground system. Conductive penetrations, such as a conduit, waveguide, or shielded cable, must have a circumferential weld or other means of providing good electrical connection at the intersection with the entry vault. The cable entry vault serves three purposes:

(1) To insure that penetrating conductors do not cause conducted HEMP energy to enter the protected topology.

(2) To contain and divert penetrator-conducted HEMP energy to the boundary exterior.

(3) To contain or divert radiant EM energy resulting from the activation of transient suppression devices subjected to a conducted pulse.

Transient suppression devices and filters. Transient suppression devices fill a critical gap f. in the concept of topological protection. The necessity to supply power to a facility and to communicate over cables or antennas are two major factors contributing to their use. Power lines entering a facility are typically connected to an unshielded power grid so that large, conducted currents must be bled off to prevent their entry into a facility. These currents are diverted to the exterior boundary of the topology. This boundary can be an overall external shield or an enclosed entrance vault. Antennas, such as for high-frequency (HF) communications, are designed to gather EM signals (at wavelengths in the HEMP frequency spectrum). Then they apply these signals to the center conductor of a shielded cable. The HEMP transients associated with an HF antenna can be, by far, the largest single signal entering a facility. Transient suppressors often are used in conjunction with filters. Filters are frequency-selective whereas surge suppressors are amplitude-selective. Filters often are used to attenuate transients associated with the non-linear operation of surge arresters. They also are used for selectively passing (or stopping) frequency bands as in the case of antenna cable penetrations. Transient suppressors are an integral part of the EM topology, demanding specific installation techniques as will be seen later. A spark gap is a surge suppressor that provides a conducting path to ground when the voltage across the device exceeds the gap breakdown level. Spark gaps with a high current capacity do not operate quickly enough to block all HEMP energy transients entering the vault. For this reason, it may be necessary to use other protection devices in conjunction with the spark gap.

g. Electromagnetic isolation. The EM isolation concept involves the use of elements either immune to interaction with EM radiation or which provide a current path interruption. Optical fibers are examples of elements immune to EM radiation that can be used to reduce the number of conductive penetrations. For practical purposes, optical fibers can be used for long communications links without signal interference from HEMP. Further, they can be used to enter shielded zones through waveguide below cutoff penetrations without compromising the EM shielding effectiveness.

h. Dielectric isolation. Other isolation techniques include using dielectric isolators for shield penetration when external metallic EM energy collectors are involved. Examples are control rods or cables (normally metallic), piping systems for fluids, and metallic duct systems for air. Dielectric sections are installed at or near the shield to prevent the energy induced on the external metallic part from being conducted through the shield. Dielectric control rods can enter through a shield in the same way as optical fibers, that is, through a waveguide-below-cutoff section.

i. Isolation switching. Although not recommended now, isolation switching has been provided at facilities so they can use commercial electric power during routine operation, but can switch to internal generators or power systems in the event of an emergency such as nuclear attack. Since the commercial power wiring is a source of significant HEMP energy injection through a shield, switching to internally generated power is an obvious advantage when advance warning of impending nuclear attack is received and throughout the entire nuclear attack cycle. This concept applies to communications lines and control lines as well as power lines. Switching used in past facility designs has been called "alert attack" switching. Such switching must provide adequate switch contact separation to prevent arcing, and must be designed to reduce coupling interactions between wiring and switch contacts to acceptable levels.

APPENDIX A

REFERENCES

REQUIRED PUBLICATIONS

Government Publications

Department of the Army:

TM 5-686

Power Transformer Maintenance and Commissioning, Department of the Army, Washington, DC, November, 1998 (cited in figure 2-3).

Department of Energy

Building Commissioning Guide, version 2.2, Department of Energy, Washington, D.C., July 1998 (cited in table 1-1).

Non-Government Publications

American Society of Mechanical Engineers (SAME) Three Park Avenue, New York, NY 10016-5990

ASME Power Test Codes (PTC) 26 (cited in paragraph 3-9d)

American Society for Testing and Materials (ASTM) 100 Barr Harbor Drive, West Conshohocken, PA 19428-2959

ASTM D-924 "Standard Test Method for Dissipation Factor (or Power Factor) and Relative Permittivity (Dielectric Constant) of Electrical Insulating Liquids," ASTM, PA, 1999 (cited in paragraph 2-4i).

Biddle Instruments 510 Township Line Rd., Blue Bell, PA 19422

"A Stitch in Time...", Manual on Electrical Insulation Testing for the Practical Man, 1981 (cited in paragraph 2-7c)

Institute of Electrical and Electronic Engineers (IEEE) 445 Hoes Lane, P.O. Box 1331, Piscataway, NJ 08855-1331

ANSI/IEEE-Std 57.104-1995 "IEEE Guide for the Interpretation of Gases Generated in Oil-Immersed Transformers," IEEE, Inc., New York, 1995. (cited in paragraph 3-3e).

ANSI/IEEE-Std 141-1993 Red Book, "Electrical Power Distribution for Industrial Plants," IEEE, Inc., New York, NY, 1993 (cited in table 3-2) **IEEE 400**

"IEEE Guide for Making High-Direct-Current-Voltage Tests on Power Cable Systems in the Field", 1991 (cited in paragraph 3-13 and table 3-2)

IEEE-Std 43-2000 "IEEE Recommended Practice for Testing Insulation Resistance of Rotating Machinery," IEEE, Inc., New York, 2000 (cited in paragraph 2-7).

IEEE Std. 48-1996 "IEEE Standard Test Procedures and Requirements for Alternating Current Cable Terminations 2.5 KV through 765 KV", IEEE, Inc., New York, 1996 (cited in paragraph 2-4g and 3-13).

IEEE-Std 62-1995 "Guide for Diagnostic Field Testing of Electric Power Apparatus – Part 1: Oil Filled Power Transformers, Regulators, and Reactors," IEEE, Inc., New York, NY, 1995. (cited in table 3-1)

IEEE-Std 100-1996 PTC 26-1962 "Speed-Governing Systems for Internal Combustion Engine-Generator Units," ASME, New York, 1962 (cited in paragraph 3-9d).

IEEE-Std 386-1995 "IEEE Standard for Separable Insulated Connector Systems for Power Distribution Systems Above 600 V", IEEE, Inc., New York, 1995 (cited in paragraph 3-13).

InterNational Electrical Testing Association (NETA) P.O. Box 687, Morrison, CO 80645 www.netaworld.org

IETA 2

"Acceptance Testing Specifications for Electric Power Distribution Equipment and Systems," NETA, CO, 1991 (cited in paragraph 3-13).

NETA-STD-ATS 1999 "Commissioning Specifications for Electrical Power Distribution Equipment and Systems," National Electrical Testing Association (cited in paragraph 2-4f and table 3-2)

Mechanical Engineering Handbook, T. Baumeister (ed.) and E. Avallone (ed.), McGraw-Hill Book Company, Inc, New York, 1978. (cited in paragraph 3-9d).

RELATED PUBLICATIONS

Non-Government Publications

American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) 1791 Tullie Circle NE, Atlanta, GA 30329

ASHREA Guideline 1-1989 "Commissioning of HVAC Systems, *Institute of Electrical and Electronics Engineers (IEEE)* 445 Hoes Lane, P.O. Box 1331, Piscataway, NJ 08855-1331.

ANSI/IEEE 944-1986

"Recommended Practice for the Application and Testing of Uninterruptible Power Supplies for Power Generating Stations", IEEE, Inc. New York, NY, 1986.

IEEE 450-1995

"Recommended Practice for Maintenance, Testing, and Replacement of Vented Lead-Acid Batteries for Stationary Applications", IEEE, Inc., New York, N.Y., 1995.

IEEE 484-1996

"Recommended Practice for Installation Design and Installation of Vented Lead-Acid Batteries for Stationary Applications", IEEE, Inc., 1996.

IEEE-Std 57.12.80-1995 "Standard Terminology for Power and Distribution Transformer," IEEE, New York, 1995.

IEEE-Std 95-1977

"Insulation Testing of Large AC Rotating Machinery with High Direct Voltage," IEEE, Inc., New York, 1977.

IEEE Std 242-1991 Buff Book, Protection and Coordination of Industrial and Commercial Power Systems," IEEE, Inc., New York, NY, 1991.

IEEE-Std 446-1995 Orange Book, "Emergency and Standby Power Systems for Industrial and Commercial Applications," IEEE, Inc., New York, NY, 1996.

IEEE Std. 1106-1995

"Recommended Practice for Installation, Maintenance, Testing, and Replacement of Vented Nickel-Cadmium Batteries for Stationary Applications", IEEE, Inc., New York, NY 1995.

IEEE Std. 1115-1992 "Recommended Practice for Sizing Nickel-Cadmium Batteries for Stationary Applications", IEEE, Inc., New York, NY 1992.

IEEE-Std. 1187-1996 "Recommended Practice for Installation Design and Installation of Valve-Regulated Lead-Acid (VRLA) Batteries for Stationary Applications", IEEE, Inc., New York, N.Y., 1996.

IEEE-Std. 1188-1996

"Recommended Practice for Maintenance, Testing, and Replacement of Valve-Regulated Lead-Acid (VRLA) Batteries for Stationary Applications", IEEE, Inc., New York, N.Y., 1996.

"IEEE Standard Dictionary of Electrical and Electronic Terms," IEEE., New York, 1996. Department Guide Book No. EE-31 Vol. C, "Electrical Engineering Guides and Data," Ebasco Services Inc., New York, 1993. IEEE Transactions on Industry Applications, Vol.24, No. 6, November/December 1988 "Commissioning of Electric Motors and Generators", Paul S. Hamer.

National Fire Protection Association (NFPA): One Batterymarch Park, P.O. Box 9101, Quincy, MA 02269-9101

NFPA 70B

"Electrical Equipment Maintenance", National Fire Protection Association, Quincy, MA, 2002.

NFPA 110

"Emergency and Standby Power Systems," National Fire Protection Association, Quincy, MA, 1996.

NFPA 111

"Standard on Stored Electrical Energy Emergency and Standby Power Systems," National Fire Protection Association, Quincy, MA, 2001.

Standard Handbook for Electrical Engineers, D. G. Fink (ed.). and J. M. Carroll (ed.), McGraw-Hill Book Company, New York, 1968.

The J&P Transformer Book, S. Austen Stigant and A.C. Franklin, John Wiley & Sons, New York, 1973.

PRESCRIBED FORMS

The following forms are printed in the back of this manual and are also available on the Army Electronic Library (AEL) CD-ROM (EM 0001) and the USAPA web site (www.usapa.army.mil)

DA Form 7463-R Circuit Switcher Inspection Checklist (Cited in paragraph 1-6 and 4-4a)

DA Form 7464-R Transformer Inspection Checklist (Cited in paragraph 1-6 and 4-4b)

DA Form 7465-R Switchgear Inspection Checklist (Cited in paragraph 1-6, 4-4c, and 5-4c)

DA Form 7466-R Power Cable Inspection Checklist (Cited in paragraph 1-6, 4-4d, 5-4d, and 6-4f)

DA Form 7467-R Main Power System Energization Checklist [Cited in paragraph 1-6 and 4-5b(5)]

DA Form 7468-R Engine Generator Set Inspection Checklist (Cited in paragraph 1-6 and 5-4a) DA Form 7469-R Backup Power System Inspection Checklist (Cited in paragraph 1-6 and 5-5f)

DA Form 7470-R Utility and Generator Circuit Breaker Inspection Checklist (Cited in paragraph 1-6, 5-5f, and 6-4a)

DA Form 7471-R Transfer Switch Inspection Checklist (Cited in paragraph 1-6 and 6-4b)

DA Form 7472-R Uninterruptible Power Supply (UPS) Inspection Checklist (Cited in paragraph 1-6 and 6-4c)

DA Form 7473-R Battery Inspection Checklist (Cited in paragraph 1-6 and 6-4d)

DA Form 7474-R Uninterruptible Power Supply (UPS) Switchboard Inspection Checklist (Cited in paragraph 1-6 and 6-4e)

DA Form 7475-R Uninterruptible Power Supply (UPS) System Inspection Checklist (Cited in paragraph 1-6 and 6-5k) The proponent agency of this publication is the Chief of Engineers, United States Army. Users are invited to send comments and suggested improvements on DA Form 2028 (Recommended Changes to Publications and Blank Forms) directly to HQUSACE, (ATTN: CEMP-OS-P), Washington, DC 20314-1000.

By Order of the Secretary of the Army:

Official:

Sandra R. Rilu SANDRA R. RILEY

Administrative Assistant to the Secretary of the Army

PETER J. SCHOOMAKER General, United States Army Chief of Staff

Distribution:

To be distributed in accordance with Initial Distribution Number (IDN) 344745, requirements for non-equipment TM 5-694.

			VITCHER rm see TM 5									
		5	ECTION A	CUSTO	MER DA	ТА						
1. PLANT/BUILDING		2. LOC/	ATION				3. JOB	NUMB	ER			
4. EQUIPMENT		5. CIRC	UIT DESIGN	IATION			6. DAT	Ε (ΥΥΥ	YMME	DD)		
7. TEST EQUIPMENT TYPE/BRAND AN	ND CALIBI	RATION	DATE				8. TES	TED BY	ſ			
		s	ECTION B -	EQUIP	IENT DA	ТА	1					
9. MANUFACTURER	10. STY	YLES/S.C).	11. \	/OLTAGE	ERATING	6		12.	CURRE	NT RATI	NG
13. INTERRUPTING RATING				14. E	BUS BRA	CING						
SE		: - VISUA	L AND ELE	CTRICA	L/MECH/	ANICAL II	NSPECTIC	ON				
15. CHECK POINT	С	OND*	NOTES			CHECK	POINT			COI	ND*	NOTES
EXTERIOR OF EQUIPMENT				EQU	IPMENT	IDENTIFI	CATION					
COMPLETENESS OF ASSEMBLY				BRA	CING							
ELECTRICAL/MECHANICAL INTERLOC	ж				PER PHA OR CODE		NECTION	AND				
PROPER GROUNDING				HAZ	ARDOUS	LOCATIO	N					
ALIGNMENT AND ROTATION LIMITS				CON	TACT RE	SISTANC	ЭE					
TIGHTNESS OF BOLTED CONNECTION	NS			ANC	HORAGE							
PROPER LUBRICATION				REFI	ERENCE	DRAWIN	GS					
INTERRUPTER TIME TRAVEL				CON	TROL CI	RCUIT OF	PERATION	١				
MANUAL OPERATION				ENE	RGIZED	OPERATI	ON					
		SI	CTION D -	ELECTR	ICAL TE	STS						
16. INSULATION RESISTANCE @ V		A-GRD	B-C	GRD	C-0	GRD	A-B	5		B-C		C-A
@ V 17.					TAGE AN		ENT MEAS		IENTS			
MEASUREMENT DESCRIPTION			VOLT	AGE**					-	RENT*	*	
	A-I	N B-	N C-N	A-B	B-C	C-A	A	В		С	Ν	G
	A-I	N B-	N C-N	A-B	B-C	C-A	А	В		С	Ν	G
	A-I	N B-	N C-N	A-B	B-C	C-A	А	В		С	Ν	G
18 NOTES												
18. NOTES:												
*CONDITION: A=ACCEPTABLE; R=NEE	EDS REPA	NR, REP	LACEMENT	OR ADJ	USTMEN	IT; C=CO	RRECTEL	D; NA=	NOT A	PPLICA	BLE	
**NOTE VALUE AND PHASING												

					ION CHECK				
		S	ECTION A - C	USTON	ER DATA				
1. PLANT/BUILDING		2. LOCA	TION			3. JOB NUMB	ER		
4. EQUIPMENT		5. CIRCI	UIT DESIGNA	TION		6. DATE (YYY	YMME	DD)	
7. TEST EQUIPMENT TYPE/BRAND	AND CALI	BRATION	DATE			8. TESTED B	Y		
		S	ECTION B - E		ΝΤ ΠΔΤΔ				
9. MANUFACTURER	10. S ⁻	TYLES/S.C		-	OLTAGE RATIN	G	12.	CURRENT R	ATING
13. WET BULB TEMPERATURE	14. DRY 6	BULB TEM	PERATURE	15.	ENCLOSURE T	YPE	16.	FREQUENC	Y
	SECTION	C - VISUA	L AND ELEC	TRICAL	MECHANICAL	INSPECTION			
17. CHECK POINT		COND*	NOTES			K POINT		COND*	NOTES
EXTERIOR OF EQUIPMENT				-	ER PHASE CON R CODE	NNECTION AND			
COMPLETENESS OF ASSEMBLY					RDOUS LOCAT	ION			
PROPER GROUNDING				WORK	ING CLEARAN	CE			
CONDITION OF INSULATION				ANCH	ORAGE				
TIGHTNESS OF BOLTED CONNECT	IONS			REFE	RENCE DRAWI	NGS			
SEALS AND OIL LEVELS				TURN	S RATIO MEAS	UREMENTS			
WINDING CONFIGURATION					IARY DEVICE C	PERATION			
18. INSULATION RESISTANCE		A-GRD	CTION D - EL B-GF		C-GRD	A-B		B-C	C-A
@ V		A-GRD	B-Gr		C-GRD	A-B		<u>B-C</u>	
POLARIZATION INDEX									
TURNS RATIO TEST									
POWER FACTOR									
PROPER VOLTAGE									
19. NOTES:									
 ΠΕΡΦΟΡΜ ΓΡΟΥΝΔ ΡΕΣΙΣΤ ΓΡΟΥΝΔ ΡΕΣΙΣΤΑΝΧΕ ΤΕΣ 48 ΗΟΥΡΣ ΑΦΤΕΡ ΡΑΙΝΦΑΛΛ 	ΤΣ ΜΥΣ						Λ ΒΕ	ПЕРФОРМ	ſΕΔ

*CONDITION: A=ACCEPTABLE; R=NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C=CORRECTED; NA=NOT APPLICABLE

	For u	-		EAR INS			-	-					
			SE	CTION A -	CUSTO	MER DA	ТА						
1. PLANT/BUILDING		2. L	OCAT					3. JOB N	IUMBEF	२			
4. CIRCUIT DESIGNATION	5. CIRCI	UIT FEI	D FRO	М	6.	CIRCUIT	FED TO		7.	DATE (Y	YYYMME	D)	
8. TEST EQUIPMENT TYPE/BRAND /	AND CAL	_IBRAT	ION D/	ATE	9. ENC	CLOSURE	E TYPE		10. TE	STED BY	/		
			SEC	CTION B -	EQUIP	IENT DA	ТА						
11. MANUFACTURER	12. \$	STYLES	S/S.O.		13. \	/OLTAGE	RATING	5		14. CURI	RENT RA	TING	3
15. INTERRUPTING RATING					16. E	BUS BRA	CING		i				
	SECTIO	N C - VI	SUAL	AND ELE	CTRICA	L/MECH/	ANICAL II	NSPECTIO	N				
17. CHECK POINT		CONE	D *	NOTES			CHECK	POINT		C	COND*	N	OTES
EXTERIOR OF EQUIPMENT					EQU	IPMENT	IDENTIFI	CATION					
REFERENCE DRAWINGS					BRAG	CING							
ELECTRICAL/MECHANICAL DRAWO	UT					PER PHA OR CODE		NECTION A	ND				
BUS AND SUPPORT INSULATORS					HAZA	ARDOUS	LOCATIO	ON					
PROPER LUBRICATION					WOR	KING CL	EARANC	E					
CLEAN SWITCHGEAR ANCHORAGE													
CHECK MANUAL OPERATION OF CIRCUIT BREAKERS AND RELAYS								NTS CLEAR					
TEST RELAYS (ACCORDING TO ELE STUDY RECOMMENDATIONS)	C.					CK PROF ROUNDI		IPMENT GF	ROUND	ING			
CHECK INSTRUMENT AND RELAY COVERS					-		-	DOM OF M	-				
CHECK CIRCUIT BREAKER INSULAT PARTS						CK INCO I BUS	MING LIN	IE CONNEC	CTIONS	то			
CHECK CIRCUIT BREAKER CONTAC SURFACES	Т				VERI	FY PROP	PER SIZE	BREAKER	S/FUSE	S			
18. VERIFY LIFT OR BUILT WINCH F	OR HAN	IDLING	HEAV	Y PARTS		/ERIFY C GES, ET(OPERATIO	ON OF I	INDICATI	NG LIGH	TS, N	/IETERS,
20. VERIFY BOLTED BUS CONNECT RECOMMENDATIONS	TIONS TO) MANL	JFACT	URER	21. \	/ERIFY S	PACE HE	EATER IS P	ROVIDI	ED AND (OPERATI	ONA	L
			SEC	TION D - I	ELECTR	ICAL TES	STS						
22. INSULATION RESISTANCE		A-G	RD	B-G	GRD	C-0	GRD	A-B		B-C		C	C-A
@ V													
23. MEASUREMENT DESCRIPTION	. –				-	AGE AN	D CURRE	ENT MEASU	-	-			
			B-N	C-N	AGE** A-B	B-C	C-A	•	В	CURREN	NT**		G
		A-N	D-IN	C-IN	А-Б	B-C	C-A	A	В	C			G
		A-N	B-N	C-N	A-B	B-C	C-A	A	В	С	N	_	G
		A-N	B-N	C-N	A-B	B-C	C-A	А	В	С	Ν	_	G
24. NOTES													
24. ΝΟΤΕS 1. _C OΛΤΑΓΕ ΜΕΑΣΥΡΕΜΕΝΤΣ ΩΙΤΗ ΤΗΕ ΥΤΙΛΙΤΨ ΒΡΕΑΚΕΡ 2. ΙΝΣΥΛΑΤΙΟΝ ΡΕΣΙΣΤΑΝΧΕ	OHEN.	•										EAK	EP
*CONDITION: A=ACCEPTABLE; R=NE **NOTE VALUE AND PHASING	EEDS RE	EPAIR,	REPLA	CEMENT	OR ADJ	USTMEN	IT; C=CO	RRECTED;	; NA=NC	OT APPLI	CABLE		

SECTION A - CUSTOMER DATA 1. PLANT/BUILDING 2. LOCATION 3. JOB NUMBER 4. EQUIPMENT 5. CIRCUIT DESIGNATION 6. DATE (YYYYMMDD) 7. TEST EQUIPMENT TYPE/BRAND AND CALBRATION DATE 8. TESTED BY 9. MANUFACTURER 10. STUESS.0. 11. VOLTAGE RATING 12. CURRENT RATING 13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY 14. DRY BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS PROPER CONDING AT TERMINAL CHECK PROPER SIZE CABLE REFERENCE EXISTING 1-LINE TERMINATIONS PROPER LUBRICATION ANCHORAGE CHECK RADE PHASE COORDINATION CHECK RADE PHASE COORDINATION CHECK CABLE PHASE COORDINATION SECTION D - ELECTRICAL TESTS 18. INSULATION RESISTANCE A-ORD						TION CHECKL proponent agenc					
4. EQUIPMENT 5. CIRCUIT DESIGNATION 6. DATE (YYYYMMDD) 7. TEST EQUIPMENT TYPE/BRAND AND CALIBRATION DATE 8. TESTED BY SECTION B - EQUIPMENT DATA 9. MANUFACTURER 10. STYLES/S.O. 11. VOLTAGE RATING 12. CURRENT RATING 13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN PROPER GROUNDING AT TERMINAL CHECK PROPER SIZE OF CABLE Image: Cond Cond Cond Cond Cond Cond Cond Cond			S	ECTION A - C	USTO	MER DATA					
7. TEST EQUIPMENT TYPE/BRAND AND CALIBRATION DATE 8. TESTED BY SECTION B - EQUIPMENT DATA 9. MANUFACTURER 10. STYLES/S.O. 11. VOLTAGE RATING 12. CURRENT RATING 13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS PROPER GROUNDING AT TERMINAL CHECK PROPER SIZE OF CABLE REFERENCE EXISTING 1-LINE TIGHTNESS AND NEATNESS OF DIAGRAMS TERMINATIONS PROPER LUBRICATION ANCHORAGE CHECK GROUNDING AT SPLICE JOINTS CHECK PROPER SIZE TERMINAL LUGS CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION CHECK CABLE PHASE COORDINATION SHELD CONTINUITY CABLE IDENTIFICATION SECTION D - ELECTRICAL TESTS 18. INSULATION RESISTANCE A-GRD G-GRD A-B B-C C-A IN OTES 19. NOTES I. TEPPOOPM HIITH ITOTENTIAA TESTE IN AXXOPAANXE QITH STIEXIØLEA PEGYIPEMENTE OP	1. PLANT/BUILDING		2. LOCA	TION			3. JOB NUMB	ER			
SECTION B - EQUIPMENT DATA 9. MANUFACTURER 10. STYLES/S.O. 11. VOLTAGE RATING 12. CURRENT RATING 13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN PROPER GROUNDING AT TERMINAL CHECK PROPER SIZE OF CABLE Image: Check Proper Size of CABLE Image: Check Rooper Size of CABLE Image: Check Grounding AT TERMINAL CHECK PROPER SIZE OF CABLE Image: Check Grounding AT TERMINAL Image: Check Grounding AT TERMINAL SIZE OF CABLE Image: Check Grounding AT TERMINAL Image: Check Grounding AT SPLICE JOINTS Image: Check Grounding AT SPLICE JOINTS Image: Check Grounding AT SPLICE JOINTS Image: Check CABLE PHASE COORDINATION Image: Chec	4. EQUIPMENT		5. CIRCI	JIT DESIGNA	TION		6. DATE (YYY	YMME	DD)		
9. MANUFACTURER 10. STYLES/S.O. 11. VOLTAGE RATING 12. CURRENT RATING 13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS PROPER GROUNDING AT TERMINAL CHECK PROPER SIZE OF CABLE REFERENCE EXISTING 1-LINE IGHTNESS AND NEATNESS OF DIAGRAMS TIGHTNESS AND NEATNESS OF TERMINATIONS PROPER LUBRICATION ANCHORAGE CHECK GROUNDING AT SPLICE JOINTS CHECK PROPER SIZE TERMINAL LUGS AND MATERIAL CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION SHIELD CONTINUITY CABLE IDENTIFICATION CABLE IDENTIFICATION SHIELD CONTINUITY CABLE IDENTIFICATION Insulation RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE II. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A 19. NOTES I. II. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A	7. TEST EQUIPMENT TYPE/BRAND	AND CALI	BRATION	DATE			8. TESTED BY	ſ			
13. WET BULB TEMPERATURE 14. DRY BULB TEMPERATURE 15. ENCLOSURE TYPE 16. FREQUENCY SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS PROPER GROUNDING AT TERMINAL LUGS TO BUS CHECK PROPER SIZE OF CABLE Image: Check Cable Proper Size of Cable Image: Check Cable Proper Size of Cable Image: Check Cable Phase Color Cobe Image: Check Cable Phase Coordination Image: Cable Identification Image: Cable Identification Image: Cable Phase Cocrect Proper Size OF Cable Image: Cable Identification Image: Cable Phase CoordInation Image: Cable Identification Image: Cable Phase Cocrect Proper Size OF Cable Image: Cable Phase Cocrect Phase Cocrect Proper Size OF Cable Image: Cable Phase Cocrect Phase Cocre Phase Cocre Phase Cocrect Phase Cocrect Phase Cocre P			S	ECTION B - E		ENT DATA					
SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION 17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS E CHECK PROPER SIZE OF CABLE Image: Check cable proper size of cable Image: Check proper size of cable proper size of cable	9. MANUFACTURER	10. S	TYLES/S.C).	11. V	OLTAGE RATING	3	12.	CURRENT	RATI	NG
17. CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS Image: Check proper size of cable Image: Check cable proper size of cable Image: Check proper size of cable Image: Check cable proper size of cable Image: Check proper size of cable proper size of cable proper size of cable Image: Check cable proper size of cable proper size of cable proper size of cable Image: Check cable proper size of cable Image: Check cable proper size of cable	13. WET BULB TEMPERATURE	14. DRY 6	BULB TEM	PERATURE	15.	ENCLOSURE TY	(PE	16.	FREQUEN	CY	
CHECK POINT COND* NOTES CHECK POINT COND* NOTES EXTERIOR OF CABLE RUN BRACING AND SUPPORTS Image: Check proper size of cable Image: Check prote Image: Check prote Im		SECTION	C - VISUA	L AND ELEC	TRICA	/MECHANICAL I	NSPECTION				
PROPER GROUNDING AT TERMINAL LUGS TO BUS CHECK PROPER SIZE OF CABLE REFERENCE EXISTING 1-LINE DIAGRAMS TIGHTNESS AND NEATNESS OF TERMINATIONS PROPER LUBRICATION ANCHORAGE CHECK GROUNDING AT SPLICE JOINTS CHECK PROPER SIZE TERMINAL LUGS AND MATERIAL CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION SHIELD CONTINUITY CABLE IDENTIFICATION SHIELD CONTINUITY CABLE IDENTIFICATION 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD III IPENDER III IPENDER III IPENDER IIII IPENDER	17. CHECK POINT		COND*	NOTES		CHECK	POINT		COND'	r	NOTES
LUGS TO BUS CHECK PROPER SIZE OF CABLE REFERENCE EXISTING 1-LINE TIGHTNESS AND NEATNESS OF DIAGRAMS TIGHTNESS AND NEATNESS OF PROPER LUBRICATION ANCHORAGE CHECK GROUNDING AT SPLICE JOINTS CHECK PROPER SIZE TERMINAL LUGS AND MATERIAL CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION SHIELD CONTINUITY CABLE IDENTIFICATION SECTION D - ELECTRICAL TESTS 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE Image: State of the state	EXTERIOR OF CABLE RUN				BRAC	CING AND SUPPO	DRTS				
REFERENCE EXISTING 1-LINE TIGHTNESS AND NEATNESS OF DIAGRAMS TERMINATIONS PROPER LUBRICATION ANCHORAGE CHECK GROUNDING AT SPLICE JOINTS CHECK PROPER SIZE TERMINAL LUGS AND MATERIAL CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION SHIELD CONTINUITY CABLE IDENTIFICATION SHIELD CONTINUITY CABLE IDENTIFICATION 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE Image: Comparison of the second sec		L			CHEC	CK PROPER SIZE	OF CABLE				
CHECK GROUNDING AT SPLICE JOINTS CHECK PROPER SIZE TERMINAL LUGS AND MATERIAL CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION SHIELD CONTINUITY CABLE IDENTIFICATION SHIELD CONTINUITY CABLE IDENTIFICATION 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE Image: Comparison of the second s							TNESS OF				
CHECK GROUNDING AT SPLICE JOINTS AND MATERIAL CHECK CABLE PHASE COLOR CODE CHECK CABLE PHASE COORDINATION SHIELD CONTINUITY CABLE IDENTIFICATION SECTION D - ELECTRICAL TESTS 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE Image: Comparison of the second s	PROPER LUBRICATION				ANCH	IORAGE					
SHIELD CONTINUITY CABLE IDENTIFICATION SECTION D - ELECTRICAL TESTS 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE Image: Comparison of the second sec	CHECK GROUNDING AT SPLICE JOI	NTS					TERMINAL LUG	iS			
SECTION D - ELECTRICAL TESTS 18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE Image: Color of the state	CHECK CABLE PHASE COLOR COD	E			CHEC	CK CABLE PHASE	E COORDINATIO	N			
18. INSULATION RESISTANCE A-GRD B-GRD C-GRD A-B B-C C-A APPLIED VOLTAGE 19. NOTES 19. NOTES 11. ΠΕΡΦΟΡΜ ΗΙΓΗ ΠΟΤΕΝΤΙΑΛ ΤΕΣΤΣ ΙΝ ΑΧΧΟΡΔΑΝΧΕ ΩΙΤΗ ΣΠΕΧΙΦΙΕΔ ΡΕΘΥΙΡΕΜΕΝΤΣ ΟΡ	SHIELD CONTINUITY				CABL	E IDENTIFICATIO	N				
APPLIED VOLTAGE Image: Constraint of the second seco			SE	CTION D - EL	ECTR	CAL TESTS					
 19. NOTES 1. ΠΕΡΦΟΡΜ ΗΙΓΗ ΠΟΤΕΝΤΙΑΛ ΤΕΣΤΣ ΙΝ ΑΧΧΟΡΔΑΝΧΕ ΩΙΤΗ ΣΠΕΧΙΦΙΕΔ ΡΕΘΥΙΡΕΜΕΝΤΣ ΟΡ 			A-GRD	B-GR	RD	C-GRD	A-B		B-C		C-A
1. ΠΕΡΦΟΡΜ ΗΙΓΗ ΠΟΤΕΝΤΙΑΛ ΤΕΣΤΣ ΙΝ ΑΧΧΟΡΔΑΝΧΕ ΩΙΤΗ ΣΠΕΧΙΦΙΕΔ ΡΕΘΥΙΡΕΜΕΝΤΣ ΟΡ	APPLIED VOLTAGE										
	1. ПЕРФОРМ НІГН ПОТЕNTIA			ΧΟΡΔΑΝΧ	E ΩIT	Η ΣΠΕΧΙΦΙΕΔ	PE@YIPEME	ΝΤΣ Ο)Р		

F	MAIN or use of th				TION C								
		SEC		- CUSTO	MER DA	ТА							
1. PLANT/BUILDING	2. L	OCATIO	NC				3. JOB	NUMBER					
4. CIRCUIT DESIGNATION 5. CI	RCUIT FE	D FROM	1	6.	CIRCUIT	FED TO		7. DA	ΓΕ (ΥΥ)	YYMMDI	D)		
8. TEST EQUIPMENT TYPE/BRAND AND	CALIBRAT	ION DA	TE	Į			9. TEST	TED BY					
SEC ⁻	TION B - V	ISUAL A	AND ELE	CTRICA	L/MECH/	ANICAL II	NSPECTIC	ON					
10. CHECK POINT	COND*	N	IOTES			CHECK	POINT		со	ND*	NOTES		
COMPONENT INSPECTION/TESTING COMPLETED				VERIF FUNCT		HGEAR C	ONTROL						
WIRING VISUAL VERIFICATION	G VISUAL VERIFICATION CHECK FOR WORKING CLEARANCE												
VERIFY WIRING DIAGRAMS													
VERIFY CIRCUIT SWITCHER CONTROL FUNCTIONS	TRANSFORMER TRANSFER CONTROL FUNCTIONS												
ENERGIZE AND TEST SYSTEM FOR ALL CONDITIONS				CHEC		NUSUALS	SOUNDS	AFTER					
CHECK BUSHING OR TERMINALS							TRANSFO	ORMER NCLOSURE					
CHECK FOR REMOVAL OF PAINT OR HEAVY DENTS					k for NC Hing of		BNORMAI N	<u> </u>					
		SECT	ION C -	ELECTR	ICAL TES	STS							
11. MEASUREMENT DESCRIPTION				VOLT	AGE AN	D CURRE	ENT MEAS	UREMENTS					
			-	AGE**					RRENT	1	_		
	A-N	B-N	C-N	A-B	B-C	C-A	A	В	С	N	G		
	A-N	B-N	C-N	A-B	B-C	C-A	A	В	С	Ν	G		
	A-N	B-N	C-N	A-B	B-C	C-A	A	В	С	N	G		
	A-N	B-N	C-N	A-B	B-C	C-A	А	В	С	N	G		
	A-N	B-N	C-N	A-B	B-C	C-A	А	В	С	N	G		
12. NOTES					1	1							

				SPECTION CH					
	S	ECTION A - C	USTO	MER DATA					
1. PLANT/BUILDING	2. LOCA	TION			3. JOB NU	JMBE	R		
4. EQUIPMENT	5. CIRCI	UIT DESIGNA	TION		6. DATE (YYYY	YMMDD)		
7. TEST EQUIPMENT TYPE/BRAND AND CA	LIBRATION [DATE			8. TESTEI	D BY			
		ECTION B - E							
9. MANUFACTURER 10.	STYLES/S.O			OLTAGE RATING	3		12. kW F	RATING	
13. CIRCUIT BREAKER SIZE/INTERRUPTIN	G RATING		14. N	VET BULB TEMPE	ERATURE	15.	DRY BUI	_B TEM	PERATURE
SECTIO	ON C - VISUA	L AND ELEC	TRICA	L/MECHANICAL I	NSPECTION				
16. CHECK POINT	COND*	NOTES		CHECK	POINT		(COND*	NOTES
EXTERIOR OF EQUIPMENT			EQU	PMENT IDENTIFI	CATION				
COMPLETENESS OF ASSEMBLY			BRAG	CING					
EQUIPMENT ROTATION			PRO	PER PHASE CON	NECTIONS				
CHECK OIL LEVEL			REFE	ERENCE DRAWIN	GS				
CHECK FUEL LEVEL			WOR	KING CLEARANC	E				
PROPER EQUIPMENT GROUNDING			ANC	HORAGE					
CHECK METERS/GAUGES			ALL I	FILTERS AND VE	NTS CLEAR				
TIGHTNESS OF BOLTED CONNECTIONS				CK EQUIPMENT E	NVIRONME	NTAL	-		
VERIFY GOVERNOR AND REGULATOR				CK FOR PROVISIO	ONS OF SPIL	_L			
CHECK VIBRATION			CON	TROL SYSTEM					
CHECK BATTERIES			_	CK FUEL FILTER					
CHECK RADIATOR FLUID				CK ALARM INDIC OR FOR EACH FU		PER			
PROPER SYSTEM GROUND									
		CTION D - EL							
17. INSULATION RESISTANCE @ V	A-GRD	B-GR	RD	C-GRD	A-B		B-C		C-A
e v									
POLARIZATION INDEX RATIO = 10 MINUTE/1 MINUTE									
DC OVERPOTENTIAL TEST									
@ V									
 18. NOTES 1. ΠΕΡΦΟΡΜ 5 ΜΕΑΣΥΡΕΜΕΝΤΣ Α΄ 2. ΔΧ ΗΙΠΟΤ ΜΕΑΣΥΡΕΜΕΝΤΣ ΣΗΟ ΙΝΤΕΡςΑΛΣ. ΜΑΞ ΔΧ ΤΕΣΤ ςΟΛΤΑΓΕ = Ρ 	ΟΥΛΔ ΒΕΓΠ	N AT 20% (ΕΠΛΑΤΕ ΡΑ ΩΗΕΡΕ Ρ =	ОФ М ATINI = .8 Ф	ΑΞΙΜΥΜ ΤΕΣΊ	Ν ΙΝΣΤΑΛ	лат	ΓΙΟΝ	ΕΑΣΕ Ι	Ν ΕΘΥΑΛ
(ΤΕΣΤ ΜΕΑΣΥΡΕΜΕΝΤΣ ΣΗΟΥΛΔ Ν	OT EEXEE					-			

			SEC		- ELEC	TRICAL T	ESTS (C	ontinue	d)				
19. ME	ASUREMENT DESC	CRIPTION				VOLT	AGE AND	O CURRI	ENT MEAS		NTS CURRENT	**	
			A-N	B-N	C-N	A-B	B-C	C-A	A	В	CURRENT	N	G
20. LOA	D TESTS AS A PER	CENTAGE OF C	GENERA	TOR RAT	ring								
	NO LOAD	25 %		75 %		100	%		110)% (PRIM	E ENGINE	ONLY)	
A-N													
B-N													
C-N													
A-B													
B-C													
C-A													
А													
В													
С													
Ν													
G													
21. ΝΟΤ 1. ςΟΛ ΛΟΑΔ	ΤΑΓΕ ΜΕΑΣΥΡΕ	EMENT TO BI	Ε ΜΑΔΙ	Ε ΑΦΤΕ	ер гер	NEPATO	Ρ ΙΣ ΣΤ.	ΑΡΤΕΔ	ΑΝΔ ΧΟ	ONNEX	ΓΕΔ ΤΟ Λ	ΔΟΑΔ (ΧΑ	Ν ΥΣΕ
	ΙΝΓ ΧΟΜΜΙΣΣΙΟ ΦΑΧΤΥΡΙΝΓ ΧΟ												ΤΣ.
ΔΕΠΕΝ	ΙΝΕ ΓΕΝΕΡΑΤΟ ΔΙΝΓ ΟΝ ΤΗΕ Ε ΑΤΟΡ ΤΕΣΤΙΝΓ	ΘYIΠMENT	BEINC	XOMM	ΝΣΙςΙ ΙΣΣΙΟ	Ε ΠΡΟΧΙ ΝΕΔ. ΣΥ	ΈΣΣ ΑΝ. ΥΠΠΛΙΕ	Δ ΡΕΘΥ EP/MAĭ	ΥΙΡΕΣ Α ΝΥΦΑΧΊ	10 ТО 1 ГҮРЕР М	4 HOYP Δ NOPMAΛ	ΔΑΨ ΛΨ ΣΥΠΙ	ΊΛΨ
	ΦΨ ΑΛΛ ΣΨΣΤΕ Ρ ΕΘΥΙΠΜΕΝΤ Ν			ΔYPIN	ΓΛΟ	AΔ XHA	ΝΓΕΣ Α	NA PE	ХОРД П	ΕΡ ΣΠΕ	ΧΙΦΙΕΔ Ρ	ΈΘΥΙΡΕΝ	<i>ί</i> εντς
5. ПЕР	ΦΟΡΜ ΑΝΔ ΡΕΧ	ΚΟΡΔ ΕΝΓΙΝΕ	E MAN	ΥΦΑΧΤ	YPEP	эΣ ΡΕΧΟ	OMMEN	ΔΕΔ Χ	ΗΕΧΚΣ .	ANA IN	ΣΠΕΧΤΙΟ	ΝΣ.	

*CONDITION: A=ACCEPTABLE; R=NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C=CORRECTED; NA=NOT APPLICABLE **NOTE VALUE AND PHASING

UTILITY AND G For	-			AKER INSPE		KLIS	Г	
	S	ECTION A - C	USTON	IER DATA				
1. PLANT/BUILDING	2. LOCA	TION			3. JOB NUMB	ER		
4. EQUIPMENT	5. CIRC	UIT DESIGNA	TION		6. DATE (YYY	YMMD	D)	
7. TEST EQUIPMENT AND CALIBRATION D	DATE				8. TESTED BY	,		
	S	ECTION B - E	QUIPM	ENT DATA				
9. MANUFACTURER 10.	STYLES/S.C		1	OLTAGE RATING	3	12. C	URRENT R	ATING
13. CIRCUIT BREAKER SIZE AND INTERRU	JPTING RATII	NG	14. E	QUIPMENT CLAS	SSIFICATION		15. F	REQUENCY
SECTION	ON C - VISUA	L AND ELEC	TRICAL	/MECHANICAL I	NSPECTION			
16. CHECK POINT	COND*	NOTES		CHECK	POINT		COND*	NOTES
EXTERIOR OF EQUIPMENT			BRAC	ING				
COMPLETENESS OF ASSEMBLY				PER PHASE CON PR CODE	NECTIONS AND			
EXECTRICAL/MECHANICAL INTERLOCKS			HAZA	RDOUS LOCATIO	NC			
PROPER GROUNDING			WOR	KING CLEARNAC	E			
CONTACT RESISTANCE			ANCH	IORAGE				
AUXILIARY WIRING			REFE	RENCE DRAWIN	GS			
PROPER LUBERICATION				K MANUAL OPE	RATION OF CIRC /S	TIU		
TIGHTNESS OF BOLTED CONNECTIONS				YS TESTED (ACC TRICAL STUDY F	CORDING TO RECOMMENDATI	ONS)		
EQUIPMENT IDENTIFICATION								
	SE	CTION D - EL	ECTRI	CAL TESTS				
17. INSULATION RESISTANCE	A-GRD	B-GF	RD	C-GRD	A-B		B-C	C-A
@ V								
18. NOTES 1. ΜΑΝΥΦΑΧΤΥΡΕΡ϶Σ ΙΝΣΤΑΛΛΑΤ	ΓΙΟΝ ΤΕΣΤΙ	Σ/ΧΗΕΧΚΣ	ΣΗΟΥ	ΆΔ ΒΕ ΙΜΠΑΙ	ΕΜΕΝΤΕΔ.			
						107 :		
*CONDITION: A=ACCEPTABLE; R=NEEDS F **NOTE VALUE AND PHASING	KEPAIR, REPI	LAGEMENT C	IK ADJU	JSIMENT; C=CC	KRECIED; NA=	NUTAF	PLICABLE	

		SF	CTION A -	CUSTO		ТΔ							
PLANT/BUILDING	2	2. LOCAT					3. JOB N	IUMBER					
EQUIPMENT			IT DESIGN				6 DATE	(YYYYMM	וחס	וחו			
EQUIFMENT		D. CIRCO	II DESIGN	0. DATE	(<i>DD)</i>							
TEST EQUIPMENT AND CALIBRATIO					8. TESTI	ED BY							
		SE	CTION B -	EQUIPN	IENT DA	TA							
MANUFACTURER	10. STY	LES/S.O.		11. V	OLTAGE	RATING		12. CU	RRENT F	RATING	i		
. EQUIPMENT CLASSIFICATION	14. FRE	QUENCY		15. V	VET BUL	B TEMPE	ERATURE	16. DR	Y BULB 1	FEMPE	RATURE		
SE	CTION C	- VISUAL	AND ELE	CTRICA	L/MECH/	ANICALI	NSPECTIO	N					
CHECK POINT	C	OND*	NOTES			CHECK	POINT		CON	ND*	NOTES		
OMPONENT INSPECTION/TESTING				WIRI	NG VISU	AL VERIF	FICATION						
IERGIZE AND TEST SYSTEM				UTIL TEST		/GENERA	ATOR BUILI	DING LOAI)				
STALLATION INSPECTION/TESTING				TIGH	TNESS (OF BOLTI	ED CONNE	CTIONS					
ENERATOR CONTROLS AND				CHECK FOR PROPER SIZE BREAKER									
RING CONTINUITY TESTING			REFERENCE DRAWINGS										
ORKING CLEARANCE				PROPER PHASING CONNECTIONS AND COLOR CODE									
VITCHGEAR CONTROL FUNCTIONS													
RFORM AUTOMATIC TRANSFER (STEM (ATS) FUNCTIONS UNDER THI DIACENT CONDITIONS.	POWER DPERAT												
	C. G	ENERAT	ORS 1 AN	D 2 OPE	RATE								
	D. G	ENERAT	ORS 2 AN	D 3 OPE	RATE								
	E. G	ENERAT	ORS 1 ANI	D 3 OPE	RATE								
	F. R TES		O NORMA	L POWE	R AFTER	R EACH (OF THE AB	OVE					
			- WITH UT ROUGH E)	ILITY UF	ON RET	URN TO	NORMAL P	OWER					
		SEC	TION D - E	-	-								
MEASUREMENT DESCRIPTION			VOLT		AGE AN	D CURRE	ENT MEASU		S IRRENT*	*			
	A-N	B-N	-	AGE A-B	B-C	C-A	А	В	C	Ν	G		
	A-N	I B-N	C-N	A-B	B-C	C-A	A	В	С	Ν	G		

				CTION CHEC							
		SECTION A - (CUSTO	MER DATA							
1. PLANT/BUILDING	2. LOC	ATION			3. JOB N	IUMBEF	२				
4. EQUIPMENT	5. CIRC	CUIT DESIGN	ATION		6. DATE	6. DATE (YYYYMMDD)					
7. TEST EQUIPMENT AND CALIBRATION			8. TEST	IED BY							
		SECTION B - E		ENT DATA							
9. MANUFACTURER 10	. STYLES/S.	0.	11. VOLTAGE RATING 12. CURRENT						RATING		
13. SWITCH RATING			14. E	NCLOSURE TYP	PE	I	15. FREQUENCY				
16. SECT	ION C - VISU	AL AND ELEC	TRICA	/MECHANICAL	INSPECTION						
CHECK POINT	COND*	NOTES		CHEC	K POINT		CONI	D*	NOTES		
EXTERIOR OF EQUIPMENT			EQUI	PMENT IDENTIF	ICATION						
COMPLETENESS OF ASSEMBLY			BRAC	CING							
INDICATING LIGHTS			PROPER PHASE CONNECTIONS AND COLOR CODE								
SWITCH FOR FREEDOM OF MOVEMENT			ENVI								
ELECTRICAL/MECHANICAL INTERLOCKS	ECTRICAL/MECHANICAL INTERLOCKS				CE						
ADJUST TIMING SETTINGS			ANCH	IORAGE							
PROPER EQUIPMENT GROUNDING			REFERENCE DRAWINGS								
CONTACT RESISTANCE			PROPER LUBRICATION								
TIGHTNESS OF BOLTED CONNECTIONS			PT AI	ND CONTROL FU	JSE SIZE						
	-	ECTION D - E									
17. INSULATION RESISTANCE @ V	A-GRD	B-GI	RD	C-GRD	A-B		B-C		C-A		
 18. ΝΟΤΕS 1. ΣΩΙΤΧΗ ΤΡΑΝΣΦΕΡΣ ΟΝ ΛΟΣΣ (2. ΣΩΙΤΧΗ ΤΡΑΝΣΦΕΡ ΒΑΧΚ ΤΟ Ν ΔΕΛΑΨ. 3. ΑΥΞΙΛΙΑΡΨ ΧΟΝΤΑΧΤΣ ΟΠΕΡΑ 	ЮРМАЛ П	ΟΩΕΡ ΟΝ Ρ	ETYPI	N ОФ NOPMA	Λ ΠΟΩΕΡ ΣΕ						

*CONDITION: A=ACCEPTABLE; R=NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C=CORRECTED; NA=NOT APPLICABLE

				•	UPS) INSPEC		ECKLI	ST			
		s	ECTION A - (CUSTO							
1. PLANT/BUILDING		2. LOCA					3. JOB	NUMBER			
4. EQUIPMENT		5. CIRCI FED TO	JIT DESIGN/	ATION	6. CIRCUIT DES	SIGNATION	N 7. DATE (YYYYMMDD)				
8. TEST EQUIPMENT AND CALIBRATION	N DATE	_					9. TES	TED BY			
		9	ECTION B - E								
10. MANUFACTURER	11. ST	YLES/S.C			OLTAGE RATIN	G	1	3. kVA RATING			
SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION											
14. CHECK POINT		COND*	NOTES			< POINT					
EXTERIOR OF EQUIPMENT				EQUI	PMENT IDENTIF	ICATION					
COMPLETENESS OF ASSEMBLY				BRAC	CING						
INDICATING LIGHTS				_	PER PHASE CON DR CODE	INECTIONS	AND				
SWITCH FOR FREEDOM OF MOVEMENT	Г			ENVI	RONMENTAL CL	ASSIFICATI	ON				
MANUAL OPERATION OF CIRCUIT BREAKERS				WOR							
TIMING SETTINGS				ANCH							
PROPER GROUNDING				REFE		NGS					
PROPER VOLTAGE CONNECTIONS				CON							
TIGHTNESS OF BOLTED CONNECTIONS	6				FY ALL TRANSFI RATIONS						
TEST CIRCUIT BREAKERS WITH CURRENT INJECTION TESTER											
		-	CTION D - E	-			I		<u>.</u>		
15. VAC (OUTPUT)		A-GRD	B-GI	GRD C-GRD A-B B-C		B-C	C-A				
16. NOTES											
*CONDITION: A=ACCEPTABLE; R=NEED DA FORM 7472-R, AUG 2002	S REP	AIR, REPI	ACEMENT	DR ADJ	USTMENT; $C = \overline{CC}$	DRRECTED;	NA=NO	T APPLICABLE	USAPA V1.0		

				694; the proponent ager						
1. PLANT/BUILDING		S 2. LOCA		CUSTOMER DATA	3. JOB NU	IMBER				
	-									
4. EQUIPMENT	UIT DESIGNA	ATION	6. DATE (YYYYMME	D)					
7. TEST EQUIPMENT AND CALIBRATIC		8. TESTED BY								
9. MANUFACTURER	10. ST	YLES/S.C).	11. VOLTAGE RATIN	IG	12. CUR	RENT RATI	T RATING		
13. ENCLOSURE TYPE	14. FR	EQUENC	Y	15. WET BULB TEM	PERATURE	16. DRY	BULB TEM	PERATURE		
SE		C - VISUA	L AND ELEC		INSPECTION					
17. CHECK POINT	(COND*	NOTES	CHEC	K POINT		COND*	NOTES		
EXTERIOR OF EQUIPMENT				EQUIPMENT IDENTI	FICATION					
COMPLETENESS OF ASSEMBLY				BRACING						
ELECTROLYTE LEVEL				ENVIRONMENTAL C						
VENTS SEALED AND PLUGS INSTALLE	D			WORKING CLEARAN						
PROPER POLARITY CONNECTIONS				ANCHORAGE						
TIGHTNESS OF BOLTED CONNECTION	IS			CHECK FOR EXHAU ENCLOSED ENVIRO						
PROPER GROUNDING				REFERENCE DRAW						
CHECK FOR SHOWER AND EYEWASH STATION		CHECK FOR ACCESS TO BATTERIES FOR O & M								
TEST CIRCUIT BREAKERS WITH CURRENT INJECTION TESTER				CHECK UPS CONTROL PANEL ALARMS						
TEST CIRCUIT BREAKERS				TEST TRANSFER SV	VITCH					
		SE	CTION D - E	LECTRICAL TESTS			1	1		
18. MEASUREMENT DESCRIPTION				VOLTAGE AND CUR	RENT MEASUF					
			VOLTA			CURRENT**				
BATTERY VOLTAGE & CURRENT		POSI	IIVE	NEGATIVE POSITIVE			GATIVE	GROUND		
19. NOTES										
 ΜΕΑΣΥΡΕ ΡΕΣΙΣΤΑΝΧΕ ΒΕΤΩ ΜΕΑΣΥΡΕ ςΟΛΤΑΓΕ ΑΧΡΟΣΣ ΧΗΕΧΚ ΣΠΕΧΙΦΙΧ ΓΡΑςΙΤΨ Ο ΤΕΣΤ ΑΝΔ ΜΑΙΝΤΑΙΝ ΒΑΤΤΕ 	EAXH ΟΦ EA	I ХЕЛЛ. ХН ХЕЛ	л.		ΥΦΑΧΤΥΡΕΙ	ΡΣ ΡΕΧΟ	PMMENΔA	ΤΙΟΝΣ.		

*CONDITION: A=ACCEPTABLE; R=NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C=CORRECTED; NA=NOT APPLICABLE **NOTE VALUE AND PHASING

UNINTERRUPTIBLE Fo			-	S) SWITCHBOARD		CHE	CKLIST				
SECTION A - CUSTOMER DATA											
1. PLANT/BUILDING		2. LOCA	TION		3. JOB NUMBE	ĒR		-			
4. EQUIPMENT		5. CIRCI	JIT DESIGNA	TION	DD)						
7. TEST EQUIPMENT TYPE/BRAND AND (DATE		8. TESTED BY	,							
9. MANUFACTURER 10). ST	YLES/S.O		QUIPMENT DATA	i	12. CURRENT RATING					
13. BUS RATING/CB INTERRUPTING RAT	ING										
SECT		C - VISUA	L AND ELEC	TRICAL/MECHANICAL IN	NSPECTION						
14. CHECK POINT	SECTION C - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION CHECK POINT COND* NOTES CHECK POINT CHECK POINT							NOTES			
EXTERIOR OF EQUIPMENT				BRACING							
COMPLETENESS OF ASSEMBLY				PROPER PHASE CONI COLOR CODE	NECTION AND						
INDICATING LIGHTS				ENVIRONMENTAL CLA							
MANUAL OPERATION OF CIRCUIT BREAKERS				WORKING CLEARANC							
PROPER GROUNDING				ANCHORAGE							
CONDITION OF INSULATION				REFERENCE DRAWIN	GS						
PROPER VOLTAGE CONNECTIONS				VERIFY PROPER SIZE AND FUSES	S OF BREAKERS	6					
TIGHTNESS OF BOLTED CONNECTIONS				CHECK PROPER EQUI		-					
EQUIPMENT IDENTIFICATION											
		SE		ECTRICAL TESTS							
15. BUS INSULATION RESISTANCE		A-GRD	B-GF	RD C-GRD	A-B		B-C	C-A			
@ V											
16. ΝΟΤΕS 1. ΤΕΣΤ ΑΛΛ ΧΙΡΧΥΙΤ ΒΡΕΑΚΕΡΣ	AXX	ΚΟΡΔΙΝΙ	TO MANY	ΥΦΑΧΤΥΡΕΡ϶Σ ΡΕΧ	ΟΜΜΕΝΔΑΤΙΟ	ΟΝΣ.					

UNINTERRUPTIBLE POWER SUPPLY (UPS) SYSTEM INSPECTION CHECKLIST For use of this form see TM 5-694; the proponent agency is COE.													
SECTION A - CUSTOMER DATA													
1. PLANT/BUILDING	2. 1	LOCA	TION				3. JOB	NUMBER					
4. EQUIPMENT	5. (CIRCL	JIT DESIGN	ATION			6. DATE (YYYYMMDD)						
7. TEST EQUIPMENT		8. TESTED BY											
SECTION B - VISUAL AND ELECTRICAL/MECHANICAL INSPECTION													
9. CHECK POINT	CON	D*	NOTES			CHECK	POINT		СО	NOTES			
COMPONENT INSPECTION/TESTING				ENEF	rgize an	ID TEST	SYSTEM						
INSTALLATION INSPECTION/TESTING				UTILI	TY TRIP	TEST							
WIRING VISUAL VERIFICATION					DED TRA RGENCY								
GENERATOR CONTROL FUNCTIONS				TIGHTNESS OF BOLTED CONNECTIONS									
LOADING UPS TEST				BATT	BATTERY DISCHARGE TEST								
DISCONNECT RECTIFIERS & INVERTERS SEPARATELY. DOES SYSTEM OPERATE CORRECTLY?					ALL UPS	S DIAGN	OSTIC FA	ULT					
	I	SE	CTION D - E	LECTR	ICAL TES	STS							
10. UPS INPUT	A-N	B-N	I C-N	A-B	B-C	C-A	A	В	С	N	G		
UPS OUTPUT	A-N	B-N	I C-N	A-B	B-C	C-A	А	В	С	N	G		
UPS SWITCHBOARD HARMONIC (THD)	A-N	B-N	I C-N	A-B	B-C	C-A	А	В	С	N	G		
11. NOTES													

*CONDITION: A=ACCEPTABLE; R=NEEDS REPAIR, REPLACEMENT OR ADJUSTMENT; C=CORRECTED; NA=NOT APPLICABLE **NOTE VALUE AND PHASING

PIN: 080195-000