

Notes: Component Functions

- wear slab surface with or without snowmelt.
- ponding; promotes rapid runoff to drains.

- Transfers heated liquid for snowmelting operations.
- bonded surface with improved bonding area.

1.4.4

PLAZA DECK SYSTEM -**BONDED WEAR SLAB** 

CONCEPTUAL - NOT FOR CONSTRUCTION